

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21005818/Evce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 Date: 25/05/2021 **AXA TOWERSINGAPORE 068811** ATTN: TAN WANCONG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJE 6339P SGS 1238S Veh. Inspected Policy No. GA442917 Coverage (\$) 0.00 Claim No. S1M03A2P Excess (\$) 0.00 TAN WANCONG **Assign Date** 14/05/2021 Assign From **Vehicle Particulars & Condition** 2. B.M.W. 520I Make & Model 1998 C.C HIDDEN 2018 Engine No. Year of Reg. WBAJA12070BJ19136 **GREY** Chassis No. Colour Odometer 24683 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 245/45 R18 PIRELLI 5 mm PIRELLI L/H Front Tyre 245/45 R18 5 mm 245/45 R18 **PIRELLI** R/H Rear Tyre 5 mm PIRELLI L/H Rear Tyre 245/45 R18 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 14/05/2021 14/05/2021 ( 06:00 PM ) Inspect Date / Time Accident Date **ENG SOON PAINTING SVC** Survey held at BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$13,000-\$14,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM21005818/Evce2

Inspected By

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

CHEN TSUE YEE

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days