

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21005821/R1PA3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210009143
<b>Claimant Vehicle No :</b>	FBG7645H	<b>Insured Vehicle No :</b>	YP5663Z
Date of Loss:	06/03/2021	Nature of Claim:	TP
		Claim No:	7135697724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBG7645H</b>	Engine No:	VMVS5BD000504
Make & Model:	SYM EXCEL II 150 A, 150cc (A)	Chassis No:	RLGHA15DMBD000504
Reg. Date:	07/11/2012 (Man. Year: 2011)	Odometer:	10083 km
Colour:	Black		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80-12	Rear Tyre Size:	130/70-12
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,611.50	1,193.00	418.50	25.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	345.00	260.00	85.00	24.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,956.50</b>	<b>1,453.00</b>	<b>503.50</b>	<b>25.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>(S\$)</b>	1,956.50	1,150.00	806.50	41.22
<b>+ GST 7.00/7.00% (S\$)</b>	136.96	80.50	56.46	41.22
<b>Nett Amount (S\$)</b>	<b>2,093.46</b>	<b>1,230.50</b>	<b>862.96</b>	<b>41.22</b>
<b>+ Loss of Use (4.0 x S\$25.00/day) (S\$)</b>		100.00		
<b>(S\$)</b>		1,330.50		
<b>Liabe Amount (80.00%) (S\$)</b>		<b>1,064.40</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,050.00</b>		

INSPECTION

Date of Assignment:	14/05/2021	
Date Inspected:	19/05/2021	Inspected At: Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10 Singapore 159762
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIGNAL	Broken	65.00 FL	*65.00 FL
2	1		*BRAKE LEVER	Scratched	35.00 FL	*35.00 FL
3	1		*HANDLE BAR	Serviceable	85.00 FL	*- FL
4	1		*SET BODY	Scratched	580.00 FL	*580.00 FL
5	1		*FRONT MUDGUARD	Scratched	95.00 FL	*95.00 FL
6	1		*MIRROR	Scratched	65.00 FL	*65.00 FL
7	1		*EXHAUST PIPE COVER	Scratched	180.00 FL	*180.00 FL
8	1		*SIDE BOX	Scratched	150.00 FL	*150.00 FL
9	1		*FRONT HEADLAMP	Serviceable	380.00 FL	*- FL
10	1		*REAR GIVI BOX	Scratched	140.00 FS	*140.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,775.00	1,310.00
- List Item Discount on L Items 10.00/10.00% (\$)	163.50	117.00
Total Parts (\$)	1,611.50	1,193.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	ALIGNMENT FORK	New	65.00	30.00
2	TRANSPORT	New	30.00	30.00
3	LABOR	New	250.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>345.00</b>	<b>260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >