

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005823/URA3Q2
Date: 18/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993609
Claimant Vehicle No :	SMJ9148S	Insured Vehicle No :	SMN3702K
Date of Loss:	05/05/2021	Nature of Claim:	TP
		Claim No:	4365710721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9148S	Engine No:	2ARH585268
Make & Model:	TOYOTA VELLFIRE, 2.5 Z (A)	Chassis No:	AGH300026317
Reg. Date:	26/11/2015 (Man. Year: 2015)	Odometer:	83426 km
Colour:	Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,600.72	4,179.95	2,420.77	36.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,730.00	890.00	33.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,220.72	5,909.95	3,310.77	35.91
Approved Total (Overridden) (S\$)		4,700.00		

(S\$)	9,220.72	4,700.00	4,520.72	49.03
+ GST 7.00/7.00% (S\$)	645.45	329.00	316.45	49.03
Nett Amount (S\$)	9,866.17	5,029.00	4,837.17	49.03
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		5,658.00		

INSPECTION

Date of Assignment: 14/05/2021

Date Inspected: 17/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Revo Performance Pte Ltd (HQ)
 BLK 1 KAKI BUKIT AVE 6 AUTOBAY #02-51
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,985.90 FL	*1,806.23 FL
2	1		*REAR BOOT LOCK	Damaged / Shorted	596.20 FL	*509.21 FL
3	1		*REAR BOOT RUBBER	Twisted	398.40 FL	*366.10 FL
4	1		*REAR BOOT EMBLEM VELLFIRE	Necessary	85.90 FL	*85.90 FL
5	2		*REAR BOOT SHOCK ABSORBER	Not Necessary	734.40 FL	*- FL
6	1		*REAR BOOT INNER COVER BOARD	Not Necessary	654.40 FL	*- FL
7	1		*REAR END PANEL	Dented	859.60 FL	*822.10 FL
8	1		*REAR END PANEL TOP GARNISH	Twisted	298.40 FL	*265.10 FL
9	1		*REAR COMPARTMENT TOP COVER KIT	Not Necessary	212.40 FL	*- FL
10	1		*REAR BUMPER	Dented	1,895.60 FL	*1,022.10 FL
11	1		*REAR BUMPER SIDE RH	Deformed / Torn	326.20 FL	*326.20 FL
12	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	86.40 FL	*- FL
13	1		*REAR BUMPER TOWING COVER	Missing	65.90 FL	*30.00 FL
14	1		*REAR BUMPER SENSOR RH	Shorted	398.60 FL	*265.00 FL
15	1		*REAR BUMPER SENSOR COVER RH	Not Necessary	55.60 FL	*- FL
16	4		*REAR BUMPER LOWER CLIPS	Necessary	22.00 FL	*22.00 FL
17	1		*REAR BUMPER SENSOR LOCK CLIPSE	Not Necessary	18.40 FL	*- FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,774.30	5,559.94
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,173.58	1,379.99
Total Parts (\$\$)	6,600.72	4,179.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	600.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	60.00
4	TO REMOVE AND REFIT REAR WINDSCREEN	New	160.00	120.00
5	TO REMOVE AND REFIT REAR GARNISH AND UP-HOLE STREP	New	160.00	80.00
6	TO REMOVE AND REPLACE BUMPER SENSOR	New	80.00	50.00
7	TO SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (S\$)			2,620.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >