

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005825/T1PA3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900012874
Claimant Vehicle No :	SMN9122U	Insured Vehicle No :	SMH8773D
Date of Loss:	11/05/2021	Nature of Claim:	TP
		Claim No:	2201995802SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN9122U		
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Engine No:	L15B71629762
Reg. Date:	17/02/2017 (Man. Year: 2016)	Chassis No:	MRHFC1660GT000506
Colour:	Black	Odometer:	68001 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,202.00	2,809.36	19,392.64	87.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,800.00	830.00	5,970.00	87.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,002.00	3,639.36	25,362.64	87.45
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	29,002.00	2,900.00	26,102.00	90.00
+ GST 7.00/7.00% (S\$)	2,030.14	203.00	1,827.14	90.00
Nett Amount (S\$)	31,032.14	3,103.00	27,929.14	90.00
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,590.45		

INSPECTION

Date of Assignment:	14/05/2021	
Date Inspected:	19/05/2021 Inspected At:	AP Automotive Services Pte Ltd 56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	495.90 FL	*- FL
2	1		*BOOTLID OUTER GARNISH	Not Necessary	134.50 FL	*- FL
3	1		*BOOTLID SPOILER (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*BOOTLID SPOILER LAMP (NPA)	Not Necessary	0.00 FL	*- FL
5	2		*BOOTLID LAMP L+R	Not Necessary	279.60 FL	*- FL
6	1		*BOOTLID LOCK SWITCH	Not Necessary	137.40 FL	*- FL
7	2		*BOOTLID NUMBER PLATE LAMP L+R	Not Necessary	120.40 FL	*- FL
8	1		*BOOTLID LOCK	Not Necessary	89.20 FL	*- FL
9	1		*BOOTLID LOCK CATCH	Not Necessary	38.90 FL	*- FL
10	1		*BOOTLID INNER TRIM	Not Necessary	91.50 FL	*- FL
11	2		*BOOTLID HINGE L+R	Not Necessary	114.00 FL	*- FL
12	2		*BOOTLID HINGE COVER L+R	Not Necessary	96.00 FL	*- FL
13	1		*BOOTLID WEATHERSTRIP	Not Necessary	95.10 FL	*- FL
14	2		*TAIL LAMP L+R	Not Necessary	536.00 FL	*- FL
15	2		*TAIL LAMP PANEL L+R	Not Necessary	157.00 FL	*- FL
16	1		*REAR BUMPER	Repeated	618.50 FL	*- FL
17	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	61.00 FL	*- FL
18	1		*REAR BUMPER REFLECTOR GARNISH L+R	N/S Not Necessary /O/SCracked	62.40 FL	*31.20 FL
19	2		*REAR BUMPER REFLECTOR SPONGE L+R (NPA)	Not Necessary	0.00 FL	*- FL
20	2		*SET REAR BUMPER REVERSE SENSOR	Not Working	409.30 FL	*337.00 FL
21	1		*REAR BUMPER LOWER	Not Necessary	191.50 FL	*- FL
22	1		*REAR BUMPER RETAINER L+R	N/S Not Necessary /O/SDeformed	60.40 FL	*30.20 FL
23	1		*REAR BUMPER REINFORCEMENT BAR	Bent	172.30 FL	*172.30 FL
24	1		*REAR BUMPER BRACKET L+R	N/S Not Necessary /O/SDeformed	57.00 FL	*28.50 FL
25	1		*REAR BUMPER UNDERCOVER	Not Necessary	285.90 FL	*- FL
26	2		*REAR FENDER INNER TRIM L+R	Not Necessary	190.60 FL	*- FL
27	1		*REAR FENDER AIRVENT	Not Necessary	28.20 FL	*- FL
28	2		*REAR FENDER COWLING L+R	Not Necessary	137.80 FL	*- FL
29	1		*END PANEL	Not Necessary	345.80 FL	*- FL
30	1		*END PANEL TOP GARNISH	Not Necessary	52.00 FL	*- FL
31	1		*REAR SMART LOCK ANTENNA	Not Necessary	42.00 FL	*- FL
32	1		*SPARE WHEEL PANEL	Not Necessary	370.80 FL	*- FL
33	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	98.70 FL	*- FL
34	1		*SPAREWHEEL PANEL ACCESSORIES BOX	Not Necessary	144.20 FL	*- FL
35	1		*SPAREWHEEL PANEL TOOLS SPONGE	Not Necessary	129.00 FL	*- FL
36	1		*EXHAUST PIPE	Not Necessary	625.20 FL	*- FL
37	2		*SET EXHAUST MOUNTING	Not Necessary	80.00 FL	*- FL
38	1		*EXHAUST HEAT SHIELD	Not Necessary	79.40 FL	*- FL
39	1		*BOOTLID SPOILER	Not Necessary	3,000.00 FS	*- FS
40	1		*BOOTLID SPOILER CLIPS	Not Necessary	100.00 FS	*- FS
41	1		*BOOTLID LOGO -HONDA	Not Necessary	300.00 FS	*- FS
42	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
43	2		*BOOTLID LAMP L+R	Not Necessary	1,000.00 FS	*- FS
44	1		*REAR NUMBER PLATE	Not Necessary	250.00 FS	*- FS
45	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
46	1		*TAIL LAMP L+R	Not Necessary	1,200.00 FS	*- FS
47	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*REAR BUMPER	Deformed	4,000.00 FS	*1,500.00 FS
49	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
50	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
51	1		*REAR BUMPER CENTER GARNISH	Deformed	600.00 FS	*200.00 FS
52	2		*REAR BUMPER SIDE GARNISH L+R	Not Necessary	550.00 FS	*- FS

Report was unsubmitted during this print-out.

5/30/23, 1:32 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	200.00 FS	*- FS
54	1		*REAR BUMPER LOWER DIFFUSOR	Deformed	2,500.00 FS	*600.00 FS
55	1		*REAR BUMPER LOWER DIFFUSOR GARNISH	Not Necessary	800.00 FS	*- FS
56	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
57	2		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
58	1		*END PANEL SEALANT	Not Necessary	250.00 FS	*- FS
59	1		*END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
60	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	23,527.50 2,929.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,325.50 119.84
					Total Parts (\$\$)	22,202.00 2,809.36
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	400.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	400.00
3	TO RNR REAR EXHAUST	New	250.00	0.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	0.00
5	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
7	TO RNR UNDERCARRIAGE	New	250.00	0.00
8	TO CHECK WATER LEAK	New	150.00	0.00
9	TO RNR FUEL TANK	New	250.00	0.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
11	TO RNR REAR BOOT MECHANISM	New	350.00	0.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
13	TO PERFORM RUST PROOFING	New	400.00	0.00
Gross Labour Cost (S\$)			6,800.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >