

ASS. REC. BY:

REF:

CC4/1719 21005825/Tiger3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$80K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: John

Vehicle: IN / OUT

Veh No: SMN 91224 Yr Regn: 2017 Feb.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime mover /

Truck / Trailer or

Make: Honda Civic 1.5 turbo 1498Colour: Black A/C: Insured: Std / NI / NASp. Reading: 68001 T/Radio: Insured: Std / NI / NA

Eng/No: _____

C/No: MRH FC166067000506Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/P / STD A/Rim orTyre Size: F: 235/40R18R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / SUMI /

TOYO / YOKO or

Fallen

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at AP AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C Foottop or

The U/C / Chassis frame / Body Structure cracked due to collision

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1) _____

Date/Time, File Return to?

☐

: Final Report

2) _____

Report Form: _____

Lump Sum / I.B.I. / _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Addl Fee: ☐

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Survey Fee

Transportation

S - R - SI

Phone

Other

Total

Estimation

Date
Vehicle SMN 9122 U
Make/Model HONDA CIVIC
Chassis No. MRHFC1660GT000506

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BOOTLID	1	\$ 495.90	\$ <i>bt</i> 495.90
2	BOOTLID OUTER GARNISH	1	\$ 134.50	\$ <i>cur</i> 134.50
3	BOOTLID SPOILER	1		\$ <i>x</i> -
4	BOOTLID SPOILER LAMP	1		\$ <i>x</i> -
5	BOOTLID LAMP L+R	2	\$ 139.80	\$ <i>x</i> 279.60
6	BOOTLID LOCK SWITCH	1	\$ 137.40	\$ <i>x</i> 137.40
7	BOOTLID NUMBER PLATE LAMP L+R	2	\$ 60.20	\$ <i>x</i> 120.40
8	BOOTLID LOCK	1	\$ 89.20	\$ <i>bt</i> 89.20
9	BOOTLID LOCK CATCH	1	\$ 38.90	\$ <i>x</i> 38.90
10	BOOTLID INNER TRIM	1	\$ 91.50	\$ <i>x</i> 91.50
11	BOOTLID HINGE L+R	2	\$ 57.00	\$ <i>x</i> 114.00
12	BOOTLID HINGE COVER L+R	2	\$ 48.00	\$ <i>x</i> 96.00
13	BOOTLID WEATHERSTRIP	1	\$ 95.10	\$ <i>cut</i> 95.10
14	TAIL LAMP L+R	2	\$ 268.00	\$ <i>LHx RHx</i> 536.00
15	TAIL LAMP PANEL L+R	2	\$ 78.50	\$ <i>x</i> 157.00
16	REAR BUMPER	1	\$ 618.50	\$ <i>de</i> 618.50
17	REAR BUMPER REFLECTOR L+R	2	\$ 30.50	\$ <i>LHx, RHx</i> 61.00
18	REAR BUMPER REFLECTOR GARNISH L+R	2	\$ 31.20	\$ <i>LHx, RHx</i> 62.40
19	REAR BUMPER REFLECTOR SPONGE L+R	2		\$ <i>x</i> -
20	REAR BUMPER REVERSE SENSOR SET	2	\$ 204.65	\$ <i>nm</i> 409.30
21	REAR BUMPER LOWER	1	\$ 191.50	\$ <i>de</i> 191.50
22	REAR BUMPER RETAINER L+R	2	\$ 30.20	\$ <i>LHx RHx de</i> 60.40
23	REAR BUMPER REFORCEMENT BAR	1	\$ 172.30	\$ <i>bt</i> 172.30
24	REAR BUMPER BRACKET L+R	2	\$ 28.50	\$ <i>LHx, RHx de</i> 57.00
25	REAR BUMPER UNDERCOVER	1	\$ 285.90	\$ <i>x</i> 285.90
26	REAR FENDER INNER TRIM L+R	2	\$ 95.30	\$ <i>x</i> 190.60
27	REAR FENDER AIRVENT	1	\$ 28.20	\$ <i>x</i> 28.20
28	REAR FENDER COWLING L+R	2	\$ 68.90	\$ <i>LHx, RHx</i> 137.80
29	END PANEL	1	\$ 345.80	\$ <i>bt</i> 345.80
30	END PANEL TOP GARNISH	1	\$ 52.00	\$ <i>de</i> 52.00
31	REAR SMART LOCK ANTENNA	1		\$ <i>cur</i> -
32	SPAREWHEEL PANEL	1	\$ 370.80	\$ <i>x</i> 370.80
33	SPAREWHEEL PANEL TOP BOARD	1	\$ 98.70	\$ <i>x</i> 98.70
34	SPAREWHEEL PANEL ACCESSORIES BOX	1	\$ 144.20	\$ <i>x</i> 144.20
35	SPAREWHEEL PANEL TOOLS SPONGE	1	\$ 129.00	\$ <i>x</i> 129.00
36	EXHAUST PIPE	1	\$ 625.20	\$ <i>x</i> 625.20
37	EXHAUST MOUNTING SET	2	\$ 40.00	\$ <i>x</i> 80.00

38	EXHAUST HEAT SHIELD		1	\$ 79.40	\$ X 79.40
				Total	\$ 6,585.50
				Less 20%	\$ 1,317.10
				Total	\$ 5,268.40

	S/Nett Items				
1	BOOTLID SPOILER		1	3000	\$ X 3,000.00
2	BOOTLID SPOILER CLIPS		1	100	\$ X 100.00
3	BOOTLID LOGO - HONDA		1	300	\$ X 300.00
4	BOOTLID INNER TRIM CLIPS		1	100	\$ X 100.00
5	BOOTLID LAMP L+R		2	500	\$ X 1,000.00
6	REAR NUMBER PLATE		1	250	\$ X 250.00
7	REVERSE CAMERA		1	800	\$ X 800.00
8	TAIL LAMP L+R		1	1200	\$ LH X RH cm / 600 1,200.00
9	TAIL LAMP CLIPS		1	50	\$ 2000 50.00
10	REAR BUMPER		1	4000	\$ de / 1000 4,000.00
11	REAR BUMPER CLIPS		1	100	\$ 3000 100.00
12	REAR BUMPER REVERSE SENSOR SET		1	300	\$ 2000 300.00
13	REAR BUMPER CENTER GARNISH		1	600	\$ 200 de / 600.00
14	REAR BUMPER SIDE GARNISH L+R		1	550	\$ X 550.00
15	REAR BUMPER REFLECTOR L+R		1	200	\$ X 200.00
16	REAR BUMPER LOWER DIFFUSOR		1	2500	\$ de / 600 2,500.00
17	REAR BUMPER LOWER DIFFUSOR GARNISH		1	800	\$ X 800.00
18	REAR FENDER INNER TRIM CLIPS		2	100	\$ X 200.00
19	REAR FENDER COWLING CLIPS		2	100	\$ X 200.00
20	END PANEL SEALANT		1	250	\$ 4000 250.00
21	END PANEL TOP GARNISH CLIPS		1	100	\$ 2000 100.00
22	SPAREWHEEL PANEL SEALANT		1	300	\$ X 300.00
				Total	\$ 13,500.00

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS		1	1800	\$ 700 1,800.00
2	SPRAY PAINT ON AFFECTED AREAS		1	1800	\$ 700 1,800.00
3	TO RNR REAR EXHAUST		1	250	\$ X 250.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION		1	150	\$ 30 150.00
5	TO RNR REAR INNER TRIM AND UPHOISTERY		1	400	\$ 60 400.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST		1	250	\$ X 250.00
7	TO RNR UNDERCARRIAGE		1	250	\$ X 250.00
8	TO CHECK WATER LEAK		1	150	\$ X 150.00
9	TO RNR FUEL TANK		1	250	\$ X 250.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS		1	600	\$ X 600.00
11	TO RNR REAR BOOT MECHANISM		1	350	\$ 60 350.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION		1	150	\$ 30 150.00
13	TO PERFORM RUST PROOFING		1	400	\$ 30 400.00
				Total Labour	\$ 6,800.00
				Parts Replacement Amount	\$ 18,768.40

Total Amount	\$ 25,568.40
--------------	--------------

Tanpin 47495749
 WP 11/5/21 24pm
 c/s moving after repair
 ~ 6 days
 Tanpin 47495749

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: