

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/GRB21005828/R1BS3Q2  
**Date:** 05/07/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SJW780S	<b>Insured Vehicle No :</b>	SLR3048G
Date of Loss:	10/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002125

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJW780S</b>	Engine No:	17090201551306PS
Make & Model:	LAND ROVER DISCOVERY, 3.0 D TSS SR (A)	Chassis No:	SALRA2AV7HA041511
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	47213 km
Colour:	White		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	255/55 R20	Rear Tyre Size:	255/55 R20
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,179.70	2,363.80	8,815.90	78.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,621.00	6,871.00	2,750.00	28.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,800.70</b>	<b>9,234.80</b>	<b>11,565.90</b>	<b>55.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,456.05</b>	<b>646.44</b>	<b>809.61</b>	<b>55.60</b>

<b>Nett Amount (S\$)</b>	<b>22,256.75</b>	<b>9,881.24</b>	<b>12,375.51</b>	<b>55.60</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 14/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 5.0 days

Inspected At:

45 LENG KEE ROAD

Repairer:Wearnes Automotive Pte Ltd (alexandra) (HQ)

---

**Adjuster:** MOHD RASUL**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2021)
<b>Parts:</b>	M1-SUV	LAND ROVER DISCOVERY 3.0 D TSS SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJW780S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR -FRONT -LESS	Repair	2,322.20 FS	*- FS
2	2		*SOUND DEADENING PAD	Not Necessary	1,156.00 FS	*- FS
3	1		*DOOR -REAR -LESS LH	Repair	2,995.50 FS	*- FS
4	1		*SEAL -DOOR FRONT	Not Necessary	170.50 FS	*- FS
5	1		*SEAL -DOOR REAR	Not Necessary	192.00 FS	*- FS
6	1		*MOULDING -DOOR OUTS	Not Necessary	352.80 FS	*- FS
7	1		*MOULDING -DOOR OUTS	Not Necessary	262.10 FS	*- FS
8	1		*MOULDING -REAR WHEEL	Scratched	145.40 FS	*145.40 FS
9	1		*MOULDING -REAR WHEEL	Scratched	112.20 FS	*112.20 FS
10	1		*SILL MOULDING RH RRS	Not Necessary	1,034.70 FS	*- FS
11	1		*SHIELD -SPLASH -WH	Not Necessary	330.10 FS	*- FS
12	1		*SIDE STEP -FIXED DI	Scratched	2,106.20 FS	*2,106.20 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>11,179.70</b>	<b>2,363.80</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRT DOOR RH ,FRT DOOR LOWER MLDG RH ,RR DOOR RH ,RR DOOR LOWER MLDG RH ,SIDE STEP BOARD ASSY RH ,ETC REPAIR REAR FENDER RH	New	4,500.00	3,250.00
2	TO SPRAY FRT DOOR RH ,RR DOOR RH ,RR FENDER RH	New	3,500.00	3,000.00
3	TO REMOVE ,REFIT & TRANSFER FRT DOOR RH INTERIOR COMPONENTS	New	500.00	0.00
4	TO REMOVE, REFIT & TRANSER RR DOOR RH INTERIOR COMPONENTS	New	500.00	0.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
<b>Gross Labour Cost (\$)</b>			<b>9,621.00</b>	<b>6,871.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >