

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21005830/GGS3Q2  
**Date:** 16/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900086663
<b>Claimant Vehicle No :</b>	SLT5063M	<b>Insured Vehicle No :</b>	GBE3654T
Date of Loss:	12/05/2021	Nature of Claim:	TP
		Claim No:	6316916751SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT5063M</b>		
Make & Model:	TOYOTA WISH, 1.8 X CVT (A)	Engine No:	2ZR0A19757
Reg. Date:	31/10/2017 (Man. Year: 2017)	Chassis No:	JTDGG20W30J008016
Colour:	White	Odometer:	55003 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,508.22	2,444.32	4,063.90	62.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,390.00	1,590.00	53.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,488.22</b>	<b>3,834.32</b>	<b>5,653.90</b>	<b>59.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		

<b>Nett Amount (S\$)</b>	<b>9,488.22</b>	<b>3,050.00</b>	<b>6,438.22</b>	<b>67.85</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 14/05/2021

Date Inspected: 18/05/2021      Inspected At: Kent Seng Car Service  
 Blk 1017 Yishun Industrial Park A, #01-240  
 Singapore 768759

Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	704.10 F	*704.10 FL
2	2		*FRONT BONNET HINGE	Bent	112.80 F	*112.80 FL
3	1		*FRONT BONNET INSULATOR	Not Necessary	277.10 F	*- FL
4	1		*FRONT BONNET LOGO	Necessary	66.40 F	*66.40 FL
5	1		*FRONT BONNET BOTTOM LOCK	Not Necessary	107.60 F	*- FL
6	1		*FRONT BONNET WIPPER GARNISH	Not Necessary	411.90 F	*- FL
7	1		*FRONT BONNET WIPPER GARNISH (CORNER)	Cut	66.70 F	*66.70 FL
8	1		*FRONT HEAD LAMP (LEFT)	Cracked	788.60 F	*788.60 FL
9	1		*FRONT SUPPORT PANEL ASSY	Repair	874.10 F	*- FL
10	1		*FRONT GRILLE ASSY	Broken	201.10 F	*201.10 FL
11	1		*FRONT GRILLE TOP GARNISH	Not Necessary	177.60 F	*- FL
12	1		*FRONT BUMPER	Deformed	480.10 F	*480.10 FL
13	2		*FRONT BUMPER SIDE GRILLE	Not Necessary	77.10 F	*- FL
14	1		*FRONT BUMPER CENTER GRILLE	Not Necessary	87.60 F	*- FL
15	1		*FRONT BUMPER INNER SPONGE	Cracked	88.30 F	*88.30 FL
16	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	279.40 F	*- FL
17	1		*FRONT BUMPER SIDE RETAINER	N/S Deformed/O/S Not Necessary	68.00 F	*34.00 FL
18	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	68.00 F	*- FL
19	1		*FRONT BUMPER LEFT SIDE FOG LAMP	Not Necessary	256.70 F	*- FL
20	10		*FRONT BUMPER CLIPS	Necessary	58.90 F	*30.00 FL
21	1		*FRONT LEFT SIDE FENDER	Buckled	687.00 F	*687.00 FL
22	1		*FRONT LEFT SIDE FENDER COWLING	Not Necessary	112.70 F	*- FL
23	8		*FRONT LEFT SIDE FENDER COWLING CLIPS	Not Necessary	47.12 F	*- FL
24	1		*AIR CLEANER HOSE	Not Necessary	107.60 F	*- FL
25	1		*AIR CLEANER BOX	Not Necessary	301.70 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,508.22</b>	<b>3,259.10</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	814.78
<b>Total Parts (\$)</b>	<b>6,508.22</b>	<b>2,444.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS	New	100.00	60.00
2	TO CHECK ELECTRICAL WIRING SYSTEM	New	80.00	30.00
3	STRAIGHTEN ,REPAIRING AND REALIGNING ONTO FRONT RIGHT SIDE FENDER ,CUTTING FRONT LEFT SIDE FENDER,CUTTING FRONT TOP PANEL ,DISMANTLE & REPLACE THE ABOVE MENTIONED PARTS	New	1,500.00	500.00
4	LABOUR FOR RESPRAY FRONT BONNET COVER ,FRONT TOP PANEL ,FRONT BUMPER ,FRONT LEFT & RIGHT SIDE FENDER	New	1,300.00	800.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,980.00</b>
				<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >