

# KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240  
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482  
 Email:kentsengcarservices@gmail.com

M/s AIG Asia Pacific Insurance Pte Ltd DATE 18.05.2021  
AIG Building, 78 Shenton Way #07-16, CAR NO SLT 5063 M  
Singapore 079120 MAKE Toyota Wish

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.  
 YOUR INSURED : GBE 3654 T

Pc	Pcs	JTDG20W30J008016	UNIT PRICE	AMOUNT
1	pc	Front bonnet / BT		\$704.10
2	pcs	Front bonnet hinge / BT	\$56.40	\$112.80
1	pc	Front bonnet insulator X NN		\$277.10
1	pc	Front bonnet logo / ac		\$66.40
1	pc	Front bonnet bottom lock X NN		\$107.60
1	pc	Front bonnet wipper garnish X NN		\$411.90
1	pc	Front bonnet wipper garnish (corner) / CA		\$66.70
1	pc	Front head lamp (left) / CA		\$788.60
1	pc	Front support panel assy X repair		\$874.10
1	pc	Front grille assy / CA		\$201.10
1	pc	Front grille top garnish X NN		\$177.60
1	pc	Front bumper / ac		\$480.10
2	pcs	Front bumper side grille X NN		\$77.10
1	pc	Front bumper center grille X NN		\$87.60
1	pc	Front bumper inner sponge / CA		\$88.30
1	pc	Front bumper reinforcement X NN		\$279.40
2	pcs	Front bumper side bracket X CH		\$68.00
2	pcs	Front bumper side retainer X PH		\$68.00
1	pc	Front bumper left side fog lamp X		\$256.70
10	pcs	Front bumper clips / ac	\$5.89	\$58.90
1	pc	Front left side fender / ac		\$687.00
1	pc	Front left side fender cowling X		\$112.70
8	pcs	Front left side fender cowling clips X NN	\$5.89	\$47.12
1	pc	Air cleaner hose X		\$107.60
1	pc	Air cleaner box X		\$301.70

*Handwritten signature*

# KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240  
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482  
 Email: kentsengcarservices@gmail.com

M/s	AIG Asia Pacific Insurance Pte Ltd	DATE	18.05.2021
	AIG Building, 78 Shenton Way #07-16, Singapore 079120	CAR NO	SLT 5063 M
		MAKE	Toyota Wish

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.  
 YOUR INSURED : GBE 3654 T

Pc	Pcs	JTDGG20W30J008016	UNIT PRICE	AMOUNT
		Continue from page one.		\$6,508.22
		Rust-proofing on the rear accident affected portions.		\$100.00
		To check electrical wiring system.		\$80.00
		Straightening, repairing and realigning onto front right side fender, cutting front left side fender, cutting front top panel, dismantle & replace the above mentioned parts.		\$1,500.00
		Labour for respray front bonnet cover, front top panel, front bumper, front left & right side fender.		\$1,300.00

60  
30  
500  
800

5 Days.  
 (Imp Sum Repair)  
 After repair photos.  
 Guo Qiang - 82880282  
 Guo Qiang @ lkkaut.com  
 18/5/21

*[Signature]*

**KENT SENG CAR SERVICES.**

Page 2 of 2

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: