

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21005835/ATF3E2

**Date:** 29/09/2021

### REFERENCE

Insured/Claimant: JOEHAN TOHKINGKEO @ HAN TOHKINGKEO  
Date of Loss: 12/05/2021

Policy No: 2070176029  
Nature of Claim: OD Claim No: 0300203204SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL2512X**  
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZDC20455  
Reg. Date: 22/12/2020 (Man. Year: 2020) Chassis No: WAUZZZF32M1047045  
Colour: White Odometer: 15493 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$160,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	76,602.00	54,216.40	22,385.60	29.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,784.00	16,884.00	7,900.00	31.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>101,386.00</b>	<b>71,100.40</b>	<b>30,285.60</b>	<b>29.87</b>
<b>- Excess (S\$)</b>	<b>400.00</b>	<b>400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>100,986.00</b>	<b>70,700.40</b>	<b>30,285.60</b>	<b>29.99</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>7,069.02</b>	<b>4,949.03</b>	<b>2,119.99</b>	<b>29.99</b>
<b>Nett Amount (S\$)</b>	<b>108,055.02</b>	<b>75,649.43</b>	<b>32,405.59</b>	<b>29.99</b>

### INSPECTION

Date of Assignment: 16/05/2021

Date Inspected: 14/05/2021 Inspected At:

24 Benoi Sector  
Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 28.0 days

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,815.00 FS	*2,251.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
3	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Cracked	118.00 FS	*93.28 FS
4	1		*FRONT BUMPER CENTER TRIM (MANHATTAN GREY)	Cracked	356.00 FS	*284.40 FS
5	1		*FRONT BUMPER CENTER GRILLE	Cracked	317.00 FS	*173.20 FS
6	2		*FRONT BUMPER CENTER SENSOR SUPPORT - LH / RH	Not Necessary	50.00 FS	*- FS
7	1		*FRONT BUMPER CENTER GRILLE COVER	Not Necessary	51.00 FS	*- FS
8	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Cracked	763.00 FS	*610.00 FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Cracked	306.00 FS	*122.00 FS
11	1		*FRONT BUMPER AIR GUIDE TRIM - LH / RH (GREY)	N/S Cut	164.00 FS	*130.80 FS
12	2		*FRONT BUMPER SENSOR SUPPORT - LH / RH	Not Necessary	50.00 FS	*- FS
13	1		*FRONT RADIATOR GRILLE	Cracked	1,928.00 FS	*1,542.40 FS
14	1		*FRONT RADIATOR GRILLE STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
15	1		*FRONT RADIATOR GRILLE COVER CAP	Not Necessary	56.00 FS	*- FS
16	1		*FRONT RADIATOR GRILLE BRACKET	Cracked	41.00 FS	*32.48 FS
17	1		*FRONT RADIATOR GRILLE SECURING PLATE	Cracked	33.00 FS	*26.16 FS
18	1		*FRONT RADIATOR GRILLE COVER	Cracked	244.00 FS	*194.80 FS
19	1		*FRONT RADIATOR GRILLE CAMERA	Not Necessary	1,141.00 FS	*- FS
20	1		*FRONT BUMPER REINFORCEMENT FOAM	Cracked	102.00 FS	*81.60 FS
21	1		*FRONT BUMPER REINFORCEMENT	Bent	916.00 FS	*732.40 FS
22	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Cracked	78.00 FS	*60.96 FS
23	1		*FRONT BUMPER TOP COVER	Cracked	123.00 FS	*98.00 FS
24	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
25	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
26	2		*HORN - LH / RH	Not Necessary	137.00 FS	*- FS
27	2		*HORN BRACKET - LH / RH	Bent	44.00 FS	*34.08 FS
28	4		*FRONT PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
29	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
30	1		*SET FRONT BUMPER WIRING	Cut	572.00 FS	*457.60 FS
31	2		*FRONT FENDER - LH / RH	Buckled	2,572.00 FS	*2,057.60 FS
32	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	176.00 FS	*- FS
33	2		*FRONT FENDER BRACKET - LH / RH	Bent	64.00 FS	*49.76 FS
34	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	480.00 FS	*- FS
35	1		*FRONT WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
36	2		*FRONT WHEEL HOUSING LINER COVER - LH / RH	Not Necessary	32.00 FS	*- FS
37	1		*FRONT BONNET	Distorted	3,508.00 FS	*2,806.40 FS
38	2		*FRONT BONNET HINGE - LH / RH	Bent	146.00 FS	*115.52 FS
39	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	296.00 FS	*- FS
40	2		*FRONT BONNET STRIKER - LH / RH	Not Necessary	220.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT BONNET SOUND ABSORBER	Not Necessary	219.00 FS	*- FS
42	1		*FRONT BONNET IMPACT PROTECTION - CENTER	Necessary	28.00 FS	*21.84 FS
43	2		*FRONT FENDER TOP COVER - LH / RH	Not Necessary	82.00 FS	*- FS
44	1		*FRONT PLENUM CHAMBER COVER	Cracked	129.00 FS	*103.20 FS
45	1		*FRONT BONNET BOWDEN CABLE - CENTER	Jammed	58.00 FS	*46.00 FS
46	2		*FRONT BONNET LOCK	Damaged	427.00 FS	*341.60 FS
47	1		*FRONT BONNET RELEASE ELEMENT	Damaged	58.00 FS	*46.00 FS
48	1		*FRONT BONNET RELEASE LEVER	Cut	14.00 FS	*11.20 FS
49	1		*FRONT BONNET RELEASE LEVER COVER	Missing	10.00 FS	*7.60 FS
50	1		*FRONT BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS
51	2		*FRONT HEADLIGHT MOUNTING - LH / RH	Cracked	236.00 FS	*188.80 FS
52	2		*FRONT HEADLIGHT - LH / RH	Cracked	14,550.00 FS	*11,640.00 FS
53	2		*FRONT HEADLIGHT POWER MODULE - LH / RH	Not Necessary	1,516.00 FS	*- FS
54	2		*FRONT HEADLIGHT HEAT SINK - LH / RH	Not Necessary	1,957.00 FS	*- FS
55	2		*FRONT HEADLIGHT HOSE - LH / RH	Not Necessary	48.00 FS	*- FS
56	2		*FRONT HEADLIGHT LIFT CYLINDER - LH / RH	Cracked	420.00 FS	*335.20 FS
57	1		*FRONT HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	80.00 FS	*- FS
58	1		*FRONT LOCK CARRIER	Cracked	1,272.00 FS	*1,017.60 FS
59	1		*FRONT A/C CONDENSER	Dented	551.00 FS	*440.80 FS
60	2		*FRONT A/C CONDENSER SEAL	Necessary	17.00 FS	*12.80 FS
61	1		*FRONT A/C REFRIGERENT LINE (COMPRESSOR>CONDENSER)	Cut	337.00 FS	*269.60 FS
62	1		*FRONT A/C REFRIGERANT LINE (COMPRESSOR>CUT-OFF POINT)	Bent	337.00 FS	*269.60 FS
63	1		*FRONT TEMPERATURE SENSOR	Cracked	7.00 FS	*5.52 FS
64	1		*FRONT ADDITIONAL RADIATOR	Bent	920.00 FS	*736.00 FS
65	1		*FRONT RADIATOR	Dented	1,035.00 FS	*828.00 FS
66	1		*COOLANT (6PCS)	Necessary	269.00 FS	*214.56 FS
67	4		*FRONT RADIATOR AIR GUIDE - LH / RH / UPPER / BOTTOM	Cracked	160.00 FS	*125.60 FS
68	1		*FRONT RADIATOR FAN COVER	Cracked	1,529.00 FS	*1,223.20 FS
69	1		*FRONT RADIATOR FAN COVER AIR GUIDE	Cracked	56.00 FS	*44.48 FS
70	1		*FRONT INTAKE AIR DUCT COVER	Cracked	29.00 FS	*22.72 FS
71	1		*FRONT INTAKE AIR DUCT COVER AIR GUIDE	Cracked	20.00 FS	*15.36 FS
72	1		*FRONT WATER DRAINAGE HOSE	Necessary	21.00 FS	*16.16 FS
73	1		*FRONT INTAKE AIR DUCT HOSE	Cracked	34.00 FS	*26.80 FS
74	1		*AIR FILTER	Cracked	239.00 FS	*191.20 FS
75	1		*INTAKE MANIFOLD	Not Necessary	121.00 FS	*- FS
76	2		*FRONT WHEEL ARCH TRIM - LH / RH	Necessary	1,072.00 FS	*857.60 FS
77	1		*FRONT WINDSCREEN	Cracked	1,294.00 FS	*1,035.20 FS
78	1		*FRONT WINDSCREEN RAIN SENSOR GEL FOIL	Necessary	137.00 FS	*109.20 FS
79	1		*FRONT WINDSCREEN RAIN SENSOR RETAINING SPRING	Not Necessary	21.00 FS	*- FS
80	2		*FRONT WINDSCREEN WATER DEFLECTOR - LH / RH	Not Necessary	130.00 FS	*- FS
81	1		*FRONT WINDSCREEN PRIMER	Necessary	20.00 FS	*15.76 FS
82	2		*FRONT DOOR WINDOW SLOT SEAL TRIM - LH / RH	Not Necessary	448.00 FS	*- FS
83	1		*FRONT STEERING AIRBAG	Activated	3,165.00 FS	*2,532.00 FS
84	1		*FRONT PASSENGER AIRBAG	Activated	3,165.00 FS	*2,532.00 FS
85	2		*SIDE HEAD AIRBAG UNIT - LH / RH	Activated	2,888.00 FS	*2,310.40 FS
86	1		*STEERING WHEEL	Cut	2,241.00 FS	*1,792.80 FS
87	1		*DASHBOARD	Torn	4,575.00 FS	*3,660.00 FS
88	1		*HEADLINER	Crumpled	2,114.00 FS	*1,691.20 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
89	1		*FRONT LOUD SPEAKER TRIM - RH	Not Necessary	129.00 FS	*- FS
90	1		*FRONT DEFROSTER NOZZLE - RH	Not Necessary	151.00 FS	*- FS
91	2		*FRONT SEATBELT - LH / RH	Activated	1,744.00 FS	*1,394.40 FS
92	2		*FRONT SEATBELT HIGH ADJUSTMENT	Damaged	342.00 FS	*273.60 FS
93	1		*AIRBAG CONTROL UNIT	Activated	1,642.00 FS	*1,313.60 FS
94	2		*AIRBAG CRASH SENSOR (NPA)	Activated	0.00 FS	*622.40 FS
95	2		*FRONT GRAB HANDLE - LH / RH	Cut	215.00 FS	*172.00 FS
96	2		*REAR GRAB HANDLE - LH / RH	Cut	216.00 FS	*172.00 FS
97	1		*A-PILLAR TRIM - LH / RH	Deformed	378.00 FS	*301.60 FS
98	1		*B-PILLAR TRIM - LH / RH	Not Necessary	306.00 FS	*- FS
99	1		*C-PILLAR TRIM - LH / RH	Cracked	320.00 FS	*255.20 FS
100	1		*DOOR WINDOW - LH	Not Necessary	242.00 FS	*- FS
101	2		*FRONT RADIATOR SEALING STRIP	Not Necessary	36.00 FS	*- FS
102	4		*FRONT RADIATOR RUBBER BUSH	Necessary	101.00 FS	*80.32 FS
103	1		*FRONT NO. PLATE	Dented	60.00 FS	*60.00 FS
104	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
105	1		*SUNDRIES	Necessary	400.00 FS	*88.88 FS
106	1		*INTAKE MANIFOLD (Supplementary)	Cracked	610.00 FS	*538.40 FS
107	1		*CHARGED AIR COOLER (Supplementary)	Dented	775.00 FS	*619.60 FS
108	1		*COOLANT HOSE - UPPER (Supplementary)	Cut	89.00 FS	*71.12 FS
109	1		*REFRIGERANT LINE (A/C CONDENSER -> CUT OFF POINT) (Supplementary)	Bent	330.00 FS	*289.20 FS
110	2		*RADIATOR RUBBER BUSH - UPPER (Supplementary)	Not Necessary	82.00 FS	*- FS
111	2		*RADIATOR BUSH - LOWER (Supplementary)	Not Necessary	19.00 FS	*- FS
112	1		*GAS FILLED STRUT (Supplementary)	Not Necessary	104.00 FS	*- FS
113	1		*REFRIGERANT LINE BRACKET (Supplementary)	Cracked	27.00 FS	*20.88 FS
114	1		*SPRING BAND CLAMP (Supplementary)	Necessary	20.00 FS	*15.52 FS
115	1		*ENGINE OIL END CAP (Supplementary)	Missing	30.00 FS	*23.28 FS
116	2		*REAR SEAT BELT - LH / RH (Supplementary)	Activated	1,020.00 FS	*800.40 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 76,602.00 54,216.40**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
<b>Labour Items</b>					
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT (NPA)	New	0.00	0.00	
2	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00	
3	TO REMOVE AND RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM,TO CARRY OUT VACUUM AND REGAS	New	1,700.00	1,700.00	
4	TO REMOVE CENTER CONSOLE,INSTRUMENT PANELS AND CLUSTERS.RENEW DASHBOARD,BOTH FRONTAL AIRBAGS,SLIP RING,TRANSFER OLD FITTINGS,RENEW SEAT BELTS AND CONTROL UNIT,PILLAR TRIMS,ROOF LINING AND BOTH CURTAIN AIR BAGS	New	3,600.00	3,600.00	
5	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00	
6	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	560.00	560.00	
7	TO RENEW FRONT WINDSCREEN	New	480.00	480.00	
8	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00	
9	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00	
10	TO REMOVE AND RENEW FRONT WINDSCREEN SENSOR FOIL AND RESET SYSTEM	New	300.00	300.00	
11	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,BOTH FRONT FENDERS AND BOTH HEADLIGHTS.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,400.00	3,500.00	
12	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,BOTH FRONT FENDERS,BONNET,HINGES,BOTH UPPER A- PILLAR AND BOTH FRONT DOORS	New	8,500.00	3,850.00	
13	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00	
14	TO DISMANTLE INTAKE MANIFOLD, INTERCOOLER, AIR COND PIPES AND RENEW ACCORDING TO DAMAGED (Supplementary)	New	980.00	980.00	
			<b>Gross Labour Cost (\$\$)</b>	<b>24,784.00</b>	<b>16,884.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >