

## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

### ESTIMATE

| Invoice Name & Address                  |                 | Owner Name    | & Vehicle Info         | _ |
|---|-----------------|---------------|------------------------|---|
|   | Cust No/Name    | KCV08581/Mr L | im Cheng Vern          |   |
| CHINA TAIPING INSURANCE (SINGAPORE)     | Reg No/Reg Date |               | / 25/05/2018           | 4 |
| 3 Anson Road #16-00<br>Springleaf Tower | Date In/Mileage |               | 53565                  |   |
| Singapore 079909                        | Chassis No      | JMAXTGK1WJZ00 | )1801                  |   |
| Attn: Claims Dept.                      | Engine No       | 4B40DL7315    |                        |   |
| Contact No 63896111                     | Make/Model      | MIT/ECLIPSE ( | CROSS 1.5 T/C 2WD SUNR |   |
| Contact no Coopera                      | Colour/Trim     | C02           | / BK                   | - |

| 1.11       | Terms                                 | Date/Time Printe  | d CSE            | Operator                                       | auntsin sin | WIP No        |       | H Second P |
|------------|---------------------------------------|---|------------------|--|-------------|---------------|-------|------------|
| Account No | MANAGEMENT OF THE PARTY OF THE PARTY. | 14/05/2021/ 14  |                  | 303 / Reneme                                   | r           | 11902         |       | -58        |
| 0000018    | Credit                                |   | Goods / Services | THE RESERVE AND ADDRESS OF THE PERSON NAMED IN | Qty         | Unit Price I  | Disc% | Amount     |
| NAT DUT OO | 000                                   | Description of  | 300037007700     |  |             |               |       | 250.00     |
| S MIPNT880 | IC/SCANNI                             | NG  |                  |  |             |               |       | 8 0 100.00 |
| MIDNITOO   | 100                                   |   |                  |  |             |               |       | 8 0 19010  |
| TO CHECK   | ALL LIGH                              | HTING/WIRING SYS  | TEM ON REAR AC   | CIDENI   |             |               |       | 15         |
| AFFECTE    | AREAS                                 |   |                  |  |             |               |       | 300.00     |
| S MIPNT880 | 880                                   |   | 0 1110           |  |             |               |       | V          |
|            |                                       | ATE GLASS UPPER   | & LWK            |  |             |               |       | 220.00     |
| S MIPNT880 | 088                                   | OOL SOLAR FILM C  | N NEW TAILGATE   | GLASS UPPER &                                  | LOWER       |               |       | P 100.00   |
| A MIDNITOR | 200                                   |   |                  |  |             |               |       | 100.00     |
| TO APPL    | Y SEALANT                             | KIT ON NEW TAIL   | GATE GLASS UPP   | ER & LOWER                                     | J. J.       |               |       | 640.00     |
| · MEDNETON | 200                                   |   |                  |  | 0115/4      | 2)            |       | 71         |
| TO TRAN    | SFER TAIL                             | GATE COMPONENTS   | & MECHANISM PA   | KIS  | 01146       | -77           |       | 320 640.0  |
|            | 000                                   | NSTALL ALL CARPI  |                  |  |             |               |       |            |
| TO REMO    | VE & RE-II                            | NSTALL ALL CARPE  | ADFAS            |  |             | 10            | 120 1 | 20 2550 0  |
|            |                                       | CCIDENT AFFECTE   |                  |  |             | -             | 17    | 2500.0     |
| S MIPNT88  | ACE TATIC                             | ATE, REAR BUMPER  | UPPER, EXTENSIO  | N BUMPER, CLIPS                                | ,BRACKETS,  |               |       | -          |
| DUMPER     | GARNISH P                             | ROTECTOR, SENSOR  | , REINFORCEMENT, | LATCH, ETC                                     |             |               | 111   | 2          |
| -TO REP    | AIR REAR                              | END PANEL   |                  | TED ADEAS                                      |             |               | 16>   | 400 5      |
| STRAIGH    | TEN, REFOR                            | M, ALIGN ON REAR  | ACCIDENT AFFEC   | TEU AKEAS                                      |             |               |       | 2200.0     |
| S MIPNT98  | 088                                   | ROTECTOR, SENSOR<br>END PANEL<br>M, ALIGN ON REAR<br>IN REAR ACCIDENT | AFFECTED AREAS   | Provid   | e invote so | iles agreemen | 1). 2 | 280 -550.0 |
| S MIPNT88  | AINTING U                             | IN REAR ACCIDENT  |                  |  |             |               |       |            |
| 5 MIPNIOO  | y ZERTONA                             | PAINT PROTECTI  | ON               |  |             |               |       | ¥ 50.0     |
| S MIPNT88  |                                       |   |                  |  |             |               |       | , -1       |
| REAR LI    | CENSE PLA                             | ATE WITH CASING   |                  |  |             |               |       | 50.0       |
| M SUNDRY   |                                       |   |                  |  |             |               |       | 1 705 5    |
| C & C L    |                                       | una Ci  | ASS, TAILGATE W  | shen   | 1.00        |               |       | ¥ 706.0    |
| M JJ5805/  |                                       | UPR GL  | R, WINDSHIELD G  | 744  | 2.00        |               | 0.00  | 32.0       |
| M JJMR462  |                                       | SPACER  | OTR WINDOW       |  | 4.00        |               | 0.00  | 48.0       |
| M JJMR957  |                                       | FASTEN  | ER, WINDSHIELD   | NUC  | 8.00        | 0.00          |       | - 3        |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, cradit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal of the windscreen in the event of inadvertent breakage in the course of renewal of the windscreen in the event of inadvertent breakage. the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### ESTIMATE

| 1000 | Invoice Name & Address  |   | Owner Name & Vehicle Info   | -       |
|------|---|---|---|---------|
|      | CHINA TAIPING INSURANCE (SINGAPORE)  3 Anson Road #16-00  Springleaf Tower  Singapore 079909  Attn: Claims Dept.  Contact No 63896111 | Reg No/Reg Date<br>Date In/Mileage<br>Chassis No<br>Engine No | KCV08581/Mr Lim Cheng Vern<br>SLZ9947E / 25/05/2018<br>14/05/2021/ 53565<br>JMAXTGK1WJZ001801<br>4B40DL7315 | A March |
|      |   | Colour/Trim   | MIT/ECLIPSE CROSS 1.5 T/C 2WD SUNR CO2 / BK   |         |

|   | Account No   | Terms  | Date/Time Printed (   | SE O   | perator      |         | 1000             |       | 2017            |
|---|--------------|--------|---|--|--------------|---------|------------------|-------|-----------------|
|   |              | Credit |   |  |              |         | WIP No           |       |                 |
|   |              | -      | Description of Goods / S  | No. of the contract of the con | 03 / Renemer |         | 11902            |       | - 6             |
| - | 4 JJ5805A627 |        | William Agent Land Block and Artist Agent |  |              |         | Unit Price       | Disc% | Amount          |
| 1 |              |        | LWR GLASS, TAILO  |  | ac.          | 1.00    | 524.00           | 0.00  | <b>→</b> 524.00 |
| 1 |              |        | LWR DAM, TAILGAT  |  |              | 1.00    | 13.00            | 0.00  | 13.00           |
| 1 |              |        | SPACER, TAILGATE  |  |              | 2.00    | 8.00             | 0.00  | -16.00          |
| 1 |              |        | SPACER, TAILGATE  | 1 ven  |              | 2.00    | 8.00             | 0.00  | 16.00           |
| 1 |              |        | CLIP, TAILGATE  | 1  |              | 2.00    | 3.00             | 0.00  | 6.00            |
| M |              |        | PIN, TAILGATE WI  |  | -1           | 1.00    | 4.00             | 0.00  | - 4.00          |
| M |              |        | PANEL ASSY, TAIL  |  | - D          | he 1.00 | 984.00           | 0.00  | 984.00          |
| M |              |        | GARNISH TAILGAT   |  | Dear Total   | 1.00    | 490.00           | 0.00  | 490.002         |
| M |              |        | GARNISH CHROME,<br>MARK, THREE-DIA  |  |              | 1.00    | 111.00           | 0.00  | 111.00          |
| M |              |        | MARK, ECLIPSE CRO   | No she   |              | 1.00    | 58.00            | 0.00  | 58.00           |
| M |              |        | W/STRIP, TAILGATE   | Table 1  | 5            | 1.00    | 87.00            | 0.00  | 87.00           |
| М | JJ5808A099   |        | STRIKER, TAILGATE   |  |              | 1.00    | 194.00           | 0.00  | ₹ 194.00        |
| M | JJ5808A119   |        |   | LAT Pacu   | -110         | 1.00    | 20.00            | 0.00  | ₹ 20.00         |
| M | JJ6410F379   |        | LATCH, TAILGATE   | 200  | The Thirty   | 1.00    | 385.00           | 0.00  | 385.00          |
| M | JJMR200300   |        | FACE, RR BUMPER<br>CLIP, BUMPER   | K-CC   |              | 1.00    | 556.00           | 0.00  | 556.00          |
| M | JJ6410C989   |        | LH BRKT, R/BMPR F   | ACE Hen  |              | 10.00   | 4.00             | 0.00  | 40.00           |
| M | JJ64100990   |        | RH BRKT, R/BMPR F   |  |              | 1.00    | 25.00            | 0.00  | 25.00           |
| M | JJ6410F208xA | 1      | EXTENSION, RR BUM   | 01   | _d           | 1.00    | 25.00            | 0.00  | 1 25.00         |
| М | JJ6415A069HA |        | LH COVER, RR BUMP   | ILLA   | /            | 1.00    | 152.00           | 0.00  | 152.00          |
| M | JJ6415A070HA |        | RH COVER, RR BUMP   |  |              | 1.00    | 117.00           | 0.00  | 117.00          |
| М | JJMZ576675EX |        | REAR BUMPER GARN  |  |              | 1.00    | 117.00<br>443.00 | 0.00  | 117.00          |
| M | JJMZ576676EX |        | REAR CORNER EXTE  |  | med          | 1.00    | 266.00           | 0.00  | 7 443.00        |
| M | JJMZ576679EX |        | REAR BUMPER PROT  |  |              | 1.00    | 181.00           | 0.00  | 266.00          |
| М | JJ8336A159   |        | LH LAMP ASSY, BAC   |  |              | 1.00    | 118.00           | 0.00  | 118.00          |
| M | JJ8337A144   |        | RH RR, FOG LAMP A   |  | -            | 1.00    | 132.00           | 0.00  | ¥ 132.00        |
| M | JJ8651A279   |        | LH SENSOR, CORNER   |  | L            | 1.00    | 333.00           | 0.00  | ÷ 033.002       |
| М | JJ8651A280   |        | RH SENSOR, CORNER   |  |              | 1.00    | 333.00           | 0.00  | 333.00          |
| M | JJ8651A277   |        | CTR SENSOR, BACK I  |  |              | 2.00    | 329.00           | 0.00  | 658.00          |
| M | JJ6410D224   |        | REINFORCEMENT, RR   |  |              | 1.00    | 497.00           | 0.00  | 497.00          |
| M | JJ8637A176   |        | BUZZER, KEYLESS C   |  | 1            | 1.00    |                  | 0.00  | 91.00           |
| M | JJ8637B115   |        | ANTENNA, KEYLESS  |  |              | 1.00    |                  | 0.00  | ×96.00          |
| Z | NOTES        |        | A SHAPE A   |  |              |         |                  |       |                 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not into any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



Amount

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### **ESTIMATE**

| Invoice Name & Address                                  | Owner N   | ame & Vehicle Info                | 1000 |
|---|---|-----------------------------------|------|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 | Cust No/Name KCV08581/I<br>Reg No/Reg Date SLZ9947E | Mr Lim Cheng Vern<br>/ 25/05/2018 |      |
| Springleaf Tower<br>Singapore 079909                    | Date In/Mileage 14/05/202<br>Chassis No JMAXTGK1W   |                                   | - 1  |
| Attn: Claims Dept.                                      | Engine No 4B40DL731                                 | 5                                 | -    |
| Contact No 63896111                                     | Make/Model MIT/ECLIPS Colour/Trim CO2               | SE CROSS 1.5 T/C 2WD SUNR         | à    |

| Account No | Terms     | Date/Time Printed  | CSE        | Operator   | WIP No                                  |
|------------|-----------|--|------------|--|---|
| F0000018   | Credit    | 14/05/2021/ 14:34  | DS         | 303 / Renemer  | 11902                                   |
|            |           | Description of Goods   | / Services | S A A A STATE OF THE STATE OF T | Qty Unit Price Disc%                    |
|            | AIMING TH | 5/2021 ALONG NEW UPPE<br>HIRD PARTY<br>MENT CAR<br>TP INS: CHINA T |            | ROAD   | Adrian (i)<br>P/P 20/05/21.<br>05 Days. |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature.

Date:

Confirm & accepted by

7.880.00 Parts 0.02 Labour 0.0 Standard Menu 7,610.00 Specialist Job 0.00 Others (Lub, etc) 50.00 Sundry 15,540.00 Total (w/o GST)

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated co ts quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional part: or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card on cheque, You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal. the labber seal or other repair requiring the removal of the windscreen. Page 3 of 32



#### CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD **EUNOS LINK SERVICE CENTRE**



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### **ESTIMATE**

| Invoice Name & Address              |                 | Owner Name & Vehicle Info          |
|-------------------------------------|-----------------|------------------------------------|
| CHINA TAIPING INSURANCE (SINGAPORE) | Cust No/Name    | /Mr Lim Cheng Vern                 |
| 3 Anson Road #16-00                 | Reg No/Reg Date | SLZ9947E / 25/05/2018              |
| Springleaf Tower                    | Date In/Mileage | 01/06/2021/ 54143                  |
| Singapore 079909                    | Chassis No      | JMAXTGK1WJZ001801                  |
| Attn: Claims Dept.                  | Engine No       | 4B40DL7315                         |
| Contact No 63896111                 | Make/Mode1      | MIT/ECLIPSE CROSS 1.5 T/C 2WD SUNR |
|                                     | Colour/Trim     | CO2 / BK                           |

| Acco  | unt No               | Terms     | Date/Time Printed     | CSE         | Operator                                | PARTY STATE | WIP No     | TESTE |                |
|-------|----------------------|-----------|-----------------------|-------------|---|-------------|------------|-------|----------------|
| F0000 | 0018                 | Credit    | 03/06/2021/ 14:08     | DS          | 303 / Renemer                           |             | 11902      |       |                |
|       |                      |           | Description of Good   | s / Service | S                                       | Qty         | Unit Price | Disc% | Amount         |
| S M   | IPNT880              | 88        |                       |             |   |             |            |       | 250.00         |
|       |                      | IC/SCANN  | ING                   |             |   |             |            |       |                |
| SM    | IPNT880              | 88        |                       |             |   |             |            |       | 80.00          |
| T     | O CHECK              | ALL LIGH  | HTING/WIRING SYSTEM   | ON REAR A   | CCIDENT                                 |             |            |       |                |
| A     | FFECTED              | AREAS     |                       |             |   |             |            |       | 300.00         |
|       | IPNT880              |           |                       |             |   |             |            |       | 300.00         |
|       |                      |           | NSTALL TAILGATE GLAS  | S UPPER &   | LWR                                     |             |            |       | 100.00         |
| S M   | MIPNT880             | 88        |                       |             | DED 4 LOUED                             |             |            |       | 100.00         |
|       |                      |           | KIT ON NEW TAILGATE   | GLASS UP    | PER & LOWER                             |             |            |       | 640.00         |
|       | MIPNT880             |           | ALE COMPONENTS & MC   | CHANTEM D   | ADTC                                    | -           |            |       |                |
|       |                      |           | GATE COMPONENTS & ME  |             | AKIS C                                  | 125         | 1          |       | 320.00         |
| SM    | MIPNT880             | 88 PE 1   | NSTALL ALL CARPETS/1  | DIMMING T   | TO FACTI ITATE                          | 111(8       | 7]         |       |                |
| I D   | DEBATE O             | N DEAD A  | CCIDENT AFFECTED ARE  | JI (CAS     | 111111111111111111111111111111111111111 | 1156        | フ          |       |                |
|       | MIPNT880             |           | CCIDENT MITEOTES 74   |             |   |             |            |       | 1920.00        |
| 3 III | TO REPLA             | CF TAILG  | ATE, REAR BUMPER UPPE | R, EXTENSI  | ON BUMPER, CLIPS,                       |             |            |       |                |
| В     | RUMPER G             | ARNISH P  | ROTECTOR, REINFORCEME | NT, EMBLEM  | MS,ETC                                  |             |            |       |                |
| _     | TO REPA              | TR REAR   | END PANEL             |             |   |             |            |       |                |
| S     | STRAIGHT             | EN REFOR  | M, ALIGN ON REAR ACC  | DENT AFFE   | CTED AREAS                              |             |            |       | 1650.00        |
| SM    | MIPNT980             | 88        |                       |             |   |             |            |       | 1050.00        |
| 5     | SPRAY PA             | INTING O  | N REAR ACCIDENT AFF   | ECTED AREA  | AS                                      |             |            |       |                |
| (     | (TAILGAT             | E, REAR B | UMPER UPPER, REAR EN  | PANEL)      |   |             |            |       | 280.00         |
| SN    | MIPNT880             | 88        |                       |             |   |             |            |       |                |
|       |                      | ZERTONA   | PAINT PROTECTION      |             |   |             |            |       | 50.00          |
|       | SUNDRY               |           |                       |             |   |             |            |       |                |
| 9     | C & C LC             |           | STOPPER, WI           | NOSHTELD (  | 3                                       | 2.00        | 3.00       |       | 6.00           |
| 70.00 | JJMR4622             |           | SPACER, QTR           |             |   | 4.00        | 8.00       |       | 32.00          |
|       | JJMR9577             |           | FASTENER, W           | INDSHIELD   |   | 8.00        | 6.00       |       | 48.00          |
|       | JJMB8144             |           | LWR DAM, TA           |             |   | 1.00        | 13.00      |       | 13.00<br>16.00 |
|       | JJ5805A4<br>JJ5805A4 |           | SPACER, TAI           |             |   | 2.00        | 8.00       |       | 16.00          |
|       | JJ5805A4             |           | SPACER, TAI           |             |   | 2.00        | 8.00       |       | 6.00           |
|       | JJ6127A              |           | CLIP, TAILG           |             |   | 2.00        | 3.00       | 0.00  | 0.00           |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered and additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered and additional parts or labour which may be required. any auditional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

#### **ESTIMATE**

| Invoice Name & Address              |                 | Owner Name & Vehicle Info          |
|-------------------------------------|-----------------|------------------------------------|
| CHINA TAIPING INSURANCE (SINGAPORE) | Cust No/Name    | /Mr Lim Cheng Vern                 |
| 3 Anson Road #16-00                 | Reg No/Reg Date | SLZ9947E / 25/05/2018              |
| Springleaf Tower                    | Date In/Mileage | 01/06/2021/ 54143                  |
| Singapore 079909                    | Chassis No      | JMAXTGK1WJZ001801                  |
| Attn: Claims Dept.                  | Engine No       | 4B40DL7315                         |
| Contact No 63896111                 | Make/Model      | MIT/ECLIPSE CROSS 1.5 T/C 2WD SUNR |
|                                     | Colour/Trim     | CO2 / BK                           |

| Account No   | Terms  | Date/Time Printed                               | CSE          | Ope | rator  |     |                                    | WIP No        |       |                                  |
|--|--|---|--------------|-----|--------|-----|------------------------------------|---------------|-------|----------------------------------|
| F0000018   | Credit   | 03/06/2021/ 14:08                               | DS           | 303 | / Rene | mer |                                    | 11902         |       |                                  |
|  |  | Description of Good                             | s / Services |     |        |     | Qty                                | Unit Price    | Disc% | Amount                           |
| X JJ5805A5   | 545  | PIN, TAILGAT                                    | E WINDOW     |     |        |     | 1.00                               | 4.00          | 0.00  | 4.00                             |
| X JJ5801B8   | 324  | PANEL ASSY,                                     | TAILGATE     |     |        |     | 1.00                               | 984.00        | 0.00  | 984.00                           |
| X JJ5817A2   | 286HC  | GARNISH, TAI                                    |              |     |        |     | 1.00                               | 490.00        | 0.00  | 490.00                           |
| X JJMZ5766   | 578EX  | GARNISH CHR                                     | OME, TAILG   |     |        |     | 1.00                               | 111.00        | 0.00  | 111.00                           |
| X JJMN1461   | 116  | MARK, THREE-                                    | DIA          |     |        |     | 1.00                               | 58.00         | 0.00  | 58.00                            |
| X JJ7415A7   | 714  | MARK, ECLIPS                                    |              |     |        |     | 1.00                               | 87.00         | 0.00  | 87.00                            |
| X JJ6410F3   | 379  | FACE, RR BUM                                    |              |     |        |     | 1.00                               | 556.00        | 0.00  | 556.00                           |
| JJMR3289   | 954  | CLIP, SPLASH                                    |              |     |        |     | 10.00                              | 4.00          | 0.00  | 40.00                            |
| X JJ6410F2   | 208XA  | EXTENSION, R                                    | R BUMPER     |     |        |     | 1.00                               | 152.00        | 0.00  | 152.00                           |
| X JJMZ5766   | 575EX  | REAR BUMPER                                     | GARNISH      |     |        |     | 1.00                               | 443.00        | 0.00  | 443.00                           |
| X JJMZ5766   | 576EX  | REAR CORNER                                     | EXTENSIO     |     |        |     | 1.00                               | 266.00        | 0.00  | 266.00                           |
| X JJMZ5766   | 579EX  | REAR BUMPER                                     | PROTECTO     | T P | 50     | 50  | 1.00                               | 181.00        | 0.00  | 181.00                           |
| X JJ6410D2   | 224  | REINFORCEME                                     | NT, RR BUM   |     | 11 11  | M   | 1.00                               | 497.00        | 0.00  | 497.00                           |
| X JJ8637A  | 176  | BUZZER, KEY                                     | LESS OPER    |     | LU     | CI  | 1.00                               | 91.00         | 0.00  | 91.00                            |
| NOTES  |  | 5/2021 ALONG NEW UPP                            |              |     |        |     |                                    |               |       |                                  |
| LOSS OF<br>TP#: GBI<br>Z NOTES<br>FINALIZA             | _AIMING TH<br>USE 6 DAY<br>E7817P<br>ATION (TO   | TP INS: CHINA TAL 6 WORKING DAYS)               |              |     |        |     |                                    |               |       |                                  |
| LOSS OF<br>TP#: GBI<br>NOTES<br>FINALIZA               | _AIMING TH<br>USE 6 DAY<br>E7817P<br>ATION (TO   | YS TP INS: CHINA                                |              |     |        |     |                                    |               |       |                                  |
| LOSS OF<br>TP#: GBI<br>Z NOTES<br>FINALIZA             | _AIMING TH<br>USE 6 DAY<br>E7817P<br>ATION (TO   | TP INS: CHINA TAL 6 WORKING DAYS)               |              |     |        |     |                                    |               |       |                                  |
| LOSS OF<br>TP#: GBI<br>Z NOTES<br>FINALIZA             | AIMING THE USE 6 DAY E7817P  ATION (TO'ON TO: MR | TP INS: CHINA TAL 6 WORKING DAYS) . ADRIAN LING |              |     |        | 1   | Parts<br>Labour                    |               |       | 0.0                              |
| LOSS OF<br>TP#: GBI<br>Z NOTES<br>FINALIZA<br>ATTENTIO | AIMING THE USE 6 DAY E7817P  ATION (TO'ON TO: MR | TP INS: CHINA TAL 6 WORKING DAYS) . ADRIAN LING |              |     |        | 1   | Labour<br>Standard M               |               |       | 0.0                              |
| LOSS OF<br>TP#: GBI<br>Z NOTES<br>FINALIZA<br>ATTENTIO | AIMING THE USE 6 DAY E7817P  ATION (TO'ON TO: MR | TP INS: CHINA TAL 6 WORKING DAYS) . ADRIAN LING |              |     |        | 5   | Labour<br>Standard M<br>Specialist | Job           |       | 0.0<br>0.0<br>5,540.0            |
| LOSS OF<br>TP#: GBI<br>Z NOTES<br>FINALIZA<br>ATTENTIO | AIMING THE USE 6 DAY E7817P  ATION (TO'ON TO: MR | TP INS: CHINA TAL 6 WORKING DAYS) . ADRIAN LING |              |     |        | 5   | Labour<br>Standard M               | Job           |       | 4,097.0<br>0.0<br>0.0<br>5,540.0 |
| LOSS OF<br>TP#: GBI<br>Z NOTES<br>FINALIZA<br>ATTENTIO | AIMING THE USE 6 DAY E7817P  ATION (TO'ON TO: MR | TP INS: CHINA TAL 6 WORKING DAYS) . ADRIAN LING |              |     |        | 5   | Labour<br>Standard M<br>Specialist | Job<br>o,etc) |       | 0.0<br>0.0<br>5,540.0            |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, Should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 2