



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



Company Reg No. 200609327M
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address

Ong Swee Leong Jeffrey
16 STIRLING RD
#30-16
SINGAPORE 148957

Contact No Mobile: 97648491

Owner Name & Vehicle Info

Cust No/Name /ONG SWEE LEONG JEFFREY
Reg No/Reg Date SLN573Y / 21/04/2017
Date In/Mileage / 0
Chassis No VF73A5GZTGJ808294
Engine No 10FJCC2280823
Make/Model CIT/GC4P 1.6 THP 165 EAT6 INTENSIVE ML
Colour/Trim WPP BLANC BANQUISE / IXF YATAGO GREY

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|-------|-------------------|-----|--------------|--------|
| CSM00073 | Cash | 14/05/2021/ 16:15 | BLC | 442 / CocoLu | 16521 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|-----|------------|-------|-------------|
| E PNT88000 RENEW FRT BUMPER, FRT FENDER RH. 1.5 x 500 | | | | 750 1000.00 |
| E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, SUPPORT PANEL 2 x 380 | | | | 760 1140.00 |
| A 54900099 CHECK WIRING & ELECTRICAL SYSTEM | | | | 225.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | 20.00 |
| M SUNDRY | | | | |
| M FRONT BUMPER 1.00 1031/ 1022.00 0.00 1022.00 | | | | |
| M BUMPER BRACKET 1.00 327.00 0.00 327.00 | | | | |
| M BUMPER MOULDING 1.00 207/ 206.00 0.00 206.00 | | | | |
| M BUMPER MOULDING 1.00 206.00 0.00 206.00 | | | | |
| M BUMPER MOULDING 1.00 225.00 0.00 225.00 | | | | |
| M BMPR RUBBR BOOT 1.00 308/ 305.00 0.00 305.00 | | | | |
| M GUARD GRILLE INFERIEUR 1.00 311/ 308.00 0.00 308.00 | | | | |
| M BADGE SUPPORT 1.00 203.00 0.00 203.00 | | | | |
| M CHEVRON EMBLEM SUPERIEUR 1.00 147.00 0.00 147.00 | | | | |
| M CHEVRON EMBLEM INFERIEUR 1.00 147.00 0.00 147.00 | | | | |
| M BRACKET SET 1.00 125/ 124.00 0.00 124.00 | | | | |
| M BRACKET SET LAT 1.00 124.00 0.00 124.00 | | | | |
| M BUMPER BRACKET 1.00 516/ 511.00 0.00 511.00 | | | | |
| M BUMPER BRACKET 1.00 224/ 207.00 0.00 207.00 | | | | |
| M BUMPER BRACKET 1.00 119/ 118.00 0.00 118.00 | | | | |
| M REAR DUCT RH 1.00 258.00 0.00 258.00 | | | | |
| M FACE CROSSMEMBR SUP 1.00 107.00 0.00 107.00 | | | | |
| M AIR BULKHEAD RH 1.00 571/ 566.00 0.00 566.00 | | | | |
| M FRONT WING RH ASS 1.00 517.00 0.00 517.00 | | | | |
| M FRONT LIGHT RH 1.00 1667/ 1652.00 0.00 1652.00 | | | | |
| M HEADLIGHT ASSY RH | | | | |

Estimate

Stere (CLKK)
00-NM AL
Ex pcc - ?
PIP

M BL S
4 djs

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

Authorised signatory and company stamp

Signature: _____
Date: _____

| | |
|------------------------|-----------------|
| Parts | 7,280.00 |
| Labour | 2,415.00 |
| Standard Menu | 0.00 |
| Specialist Job | 0.00 |
| Diagnostics Job | 0.00 |
| Sundry/Others | 20.00 |
| Total (w/o GST) | 9,715.00 |

This party survey is done by LKK Auto Consultants. This is a computer generated document, no signature is required.

Validity of this estimate is 14 days from date of issue. If the repairer is a computer generated document, no signature is required.

Estimated costs quoted are based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you to be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.