

CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 17/05/21
LKK - STEVE

VEHICLE NO : SLN 573Y

MODEL : CIT/GC4P 1.6 THP

WIP : 16521

Material	:	\$	<u>4,063.20</u>
Labour	:	\$	<u>1,805.00</u>
Sub-Total	:	\$	<u>5,868.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>5,568.20</u>
GST 7%	:	\$	<u>389.77</u>
Grand Total	:	\$	<u>5,957.97</u>

Finalise By/Date : LARRY ON 31/05/21

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS



CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1000	Cust No/Name /ONG SWEE LEONG JEFFREY Reg No/Reg Date SLN573Y / 21/04/2017 Date In/Mileage 27/05/2021/ 61504 Chassis/Package VF73A5GZTGJ808294 /CC17S5 Engine No 10FJCC2280823 Make/Model CIT/GC4P 1.6 THP 165 EAT6 INTENSIVE ML Colour/Trim WPP BLANC BANQUISE / IXF YATAGO GREY



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
FAX00001	Credit	31/05/2021/ 11:59	BLC	884 / Lauro Songcuan	16521	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, FRONT FENDER RH				750.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER & FRONT FENDER RH				760.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				225.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X EXC EXCESS FOR OWN DAMAGE CLAIM				-300.00
X FRONT BUMPER ✓	1022.00	1.00	* 1031.00 20.00	824.80 ✓
X BUMPER MOULDING ?	206.00	1.00	* 207.00 20.00	165.60 ?
X BMR RUBBR BOOT ✓	305.00	1.00	* 308.00 20.00	246.40 ✓
X GUARD GRILLE INFERIEUR ?	308.00	1.00	* 311.00 20.00	248.80 ?
X BRACKET SET ?	124.00	1.00	* 125.00 20.00	100.00 ?
X BUMPER BRACKET ?	511.00	1.00	* 516.00 20.00	412.80 ?
X BUMPER BRACKET ?	207.00	1.00	* 224.00 20.00	179.20 ?
X REAR DUCT RH ?	118.00	1.00	* 119.00 20.00	95.20 ?
X FRONT WING RH ASS ✓	566.00	1.00	* 571.00 20.00	456.80 ✓
X HEADLIGHT ASSY RH ?	1652.00	1.00	* 1667.00 20.00	1333.60 ?
Z TEXT OD CLAIM - AIG DOA: 14/05/2021 SURVEY: STEVE (LKK) 04 DAYS				

* - change price

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,063.20		Nett	5,568.20
Labour	1,785.00	7% GST on	5568.20	389.77
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	5,957.97
Diagnostics Job	0.00		Paid	0.00
Sundry/Others	-280.00		Total Due	5,957.97
Total(w/o GST)	5,568.20			

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

CAR NO: SLN 573X

WIP: 16521

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Headlamp (RH)	(?) SUPP	} <u>Juan</u> <u>18-5-2021</u>	✓ RR	9802041680
2	Frt Bumper Mounting	(?) SUPP		- RR	1617536780
3	Stone Guard Grilles	(?) SUPP		- RR	9814296480
4	Bumper Bracket Set	(?) SUPP		- OP	1610194380 (10/15/21)
5	Bumper Bracket	(?) SUPP		- RR	9676008380
6	Bumper Fixing Stiffener	(?) SUPP		- RR	16175370XY
7	If Bumper RR Ventilat RR Duct (RH)	(?) SUPP		- RR	9814207980
8		(?) SUPP			
9		(?) SUPP			
10		(?) SUPP			
11		(?) SUPP			
12		(?) SUPP			
13		(?) SUPP			
14		(?) SUPP			
15		(?) SUPP			
16		(?) SUPP			
17		(?) SUPP			
18		(?) SUPP			
19		(?) SUPP			
20		(?) SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: cc

SURVEYOR: Steve

User: DA11572
Vehicle : C4 PICASSO C4 SPACETOURER/C4
SPACETOURER (B78)
VIN: VF73A5GZTGJ808294

Rec No: SLN 5737
Before using DTC
to check all the fault

Print date : Thursday, 27 May 2021 14:50:16
Start of vehicle session : 27/05/2021 - 14:45
Tool version : 09.97



Global test
Expert/Global test
Vehicle\menu_tgref.s : 81_02

FAMILY NO.		CONTROL UNIT
13		Built-in systems interface BSI2010_EV (13 Faults)

U1F25 87 Fault: absence of communication with the instrument panel

Properties

Cause Local
Status Intermittent
Features -

U1F38 87 Fault: absence of communication with the instrument panel matrix display

Properties

Cause Local
Status Intermittent
Features -

B181A 87 Fault in the response from the electric steering lock to the request for locking/unlocking

Properties

Cause Local
Status Intermittent
Features No reply

B1808 87 Fault in the unlocking of the immobiliser by the engine management ECU

Properties

Cause	Local
Status	Intermittent
Features	Open circuit or short circuit to positive

B1715 64

Fault: lack of coherence between the vehicle locking status and the locking status of the front right door lock

Properties

Cause	Local
Status	Intermittent
Features	Incoherence

B1716 64

Fault: lack of coherence between the vehicle locking status and the locking status of the front left door lock

Properties

Cause	Local
Status	Intermittent
Features	Incoherence

B1328 11

Rear screen and/or mirrors de-icing control fault

Properties

Cause	Local
Status	Intermittent
Features	Short circuit to earth

U1F00 00

Fault event not stored in the faults log

Properties

Cause	Local
Status	Present
Features	-

User: DA11572

Vehicle : C4 PICASSO C4 SPACETOURER/C4

SPACETOURER (B78)

VIN: VF73A5GZTGJ808294

no: 811572
to Base all the found Job Done by Q.C

Print date : Thursday, 27 May 2021 15:00:12

Start of vehicle session : 27/05/2021 - 14:45

Tool version : 09.97



Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

Test drive check
Conclusion.

FAMILY NO. CONTROL UNIT



Built-in systems interface

BSI2010_EV



Engine management ECU

MED17_4_4



**Anti-lock Braking System (ABS) or
Electronic Stability Program (ESP)**

ESP90



**Automatic or piloted manual
gearbox**

BVA_AM6_AT6_UDS



Controls under the steering wheel

COM2008P



**Controls on the steering wheel /
integral controls steering wheel**

VCI



Left-hand windscreen wiper motor

MOTEV_UDS



**Right-hand windscreen wiper
motor**

MOTED_UDS



Air conditioning

★ **BCC**

*Important, ECU present on the vehicle
but configured absent*



Instrument panel

★ **ECU not recognised**

*Down-grade mode: this information is
not guaranteed*



Rain and brightness sensor

PLUIE_LUMINOSITE_UDS



Airbags and pretensioners ECU

RBG_UDS



Battery charge status control unit

BECB_GEN2



Voltage maintaining device

✳ **DMTR_DTC3B**

*Important, ECU present on the vehicle
but configured absent*

1



Motorised Boot Unit

VERINS_MOTORISES (1 Faults)

B1003 55

Configuration fault

Properties

Status

Permanent

Characterisation of the fault

Configuration incorrect or not carried out



Additional heating

Communication error



Hands full access ECU, right-hand side or rear

BAAST



Touch screen

✳ **EMF_DGT_LVDS_BD**

*Important, ECU present on the vehicle
but configured absent*



Electric steering lock

AVE




Urea ECU

Not present




Engine wiring housing

Not present




Trailer relay unit

Not present



External CD player

Not present



Audio amplifier

Not present



Multifunction video camera (CMF) **Not present**



Anti-theft alarm

Not present



Intrusion alarm siren

Not present