

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21005848/Etce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 10/06/2021 SINGAPORE 068811 ATTN: CHEN XIN YOU Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJL 7557H GBA 5622T Veh. Inspected Policy No. GA477537 Coverage (\$) 0.00 Claim No. S1M039PU Excess (\$) 0.00 **CHEN XIN YOU Assign Date** 17/05/2021 Assign From **Vehicle Particulars & Condition** 2. NISSAN NV350 2488 Make & Model C.C HIDDEN 2018 Engine No. Year of Reg. JN1MC2E26Z0008615 SILVER Chassis No. Colour Odometer 159730 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C BRIDGESTONE 4 mm L/H Front Tyre 195 R15C BRIDGESTONE 4 mm 195 R15C BRIDGESTONE R/H Rear Tyre 4 mm BRIDGESTONE 4 mm L/H Rear Tyre 195 R15C 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 07/05/2021 27/05/2021 (12:00 PM) Inspect Date / Time Accident Date KOK WANG CAR GROOMING (HQ) Survey held at 1 SOON LEE STREET #06-40 PIONEER CENTRE SINGAPORE 627605 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/ASM21005848/Etce2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days