

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Abu Kassim, Noor Mariesa

Date: 21 May 2021

Preliminary Advice

Vehicle No	: SMH5723T	Accident Date	: 12/05/2021
Make	: MITSUBISHI ECLIPSE CROSS	Policy No.	: 1900009706
Assignment Date	: 17/05/2021	Excess	: S\$0.00
Date of Inspection	: 17/05/2021	Est. Duration of Repair	: 22
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	129,999.00
Pre-Accident Value	:S\$	95,000.00
COE / PARF Rebate	:S\$	44,567.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	85,432.00
Margin for Repair (Pre-accident Value)	:S\$	50,433.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : WE RECOMMENDED THE VEHICLE AS TOTAL LOSS DUE TO BOTH REAR BODY CHASSIS BADLY DAMAGED. WORKSHOP TOTAL LOSS LETTER HAS BEEN UPLOADED.