

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005855/APA3Q2
Date: 15/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900007600
Claimant Vehicle No :	SMN3585G	Insured Vehicle No :	SDP5550P
Date of Loss:	10/05/2021	Nature of Claim:	TP
		Claim No:	0040473636SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3585G		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B6002693
Reg. Date:	02/08/2019 (Man. Year: 2019)	Chassis No:	GK82002288
Colour:	Grey	Odometer:	26089 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,309.60	2,458.08	1,851.52	42.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,190.00	1,510.00	55.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,009.60	3,648.08	3,361.52	47.96
Approved Total (Overridden) (S\$)		2,900.00		

(S\$)	7,009.60	2,900.00	4,109.60	58.63
+ GST 7.00/7.00% (S\$)	490.67	203.00	287.67	58.63
Nett Amount (S\$)	7,500.27	3,103.00	4,397.27	58.63
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,355.00		
Global Sum Settlement (S\$)		3,350.00		

INSPECTION

Date of Assignment: 14/05/2021

Date Inspected: 14/05/2021

Estimated Period of Repair: 4.0 days

 Inspected At: Success United Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
 Singapore 417921
Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,391.80 FL	*1,193.00 FL
2	1		*REAR BOOT LID SHUTTLE EMBLEM	Necessary	75.00 FL	*75.00 FL
3	1		*REAR BOOT LID HONDA EMBLEM	Necessary	37.80 FL	*37.80 FL
4	1		*REAR BOOT LID WEATHERSTRIP	Not Necessary	218.50 FL	*- FL
5	1		*REAR BOOT LID MECHANISM LOCK	Not Necessary	151.60 FL	*- FL
6	1		*REAR BOOT LID REFLECTOR LAMP LH	Not Necessary	395.40 FL	*- FL
7	1		*REAR BOOT LID DAMPER LH	Not Necessary	165.00 FL	*- FL
8	1		*REAR WINDSCREEN RUBBER	Necessary	218.30 FL	*218.30 FL
9	1		*REAR BUMPER	Deformed	1,350.00 FL	*1,150.00 FL
10	1		*REAR BUMPER SIDE HOLDER LH	Not Necessary	45.90 FL	*- FL
11	1		*REAR BUMPER BRACKET LH	Not Necessary	48.70 FL	*- FL
12	1		*REAR BUMPER BRACKET LAMP LH	Cracked	74.50 FL	*74.50 FL
13	1		*REAR BUMPER BRACKET GARNISH LH	Not Necessary	64.00 FL	*- FL
14	1		*REAR END PANEL	Repair	601.50 FL	*- FL
15	5		*REAR BUMPER CLIPS	Necessary	24.00 FL	*24.00 FL
16	1		*SET REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
17	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,282.00	3,012.60
- List Item Discount on L Items 20.00/20.00% (\$)	972.40	554.52
Total Parts (\$)	4,309.60	2,458.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS CHECK LIGHTING	New	100.00	30.00
2	TO REMOVE ,REINSTAL REAR WINDSCREEN	New	250.00	120.00
3	TO REMOVE ,REINSTAL UPHOLSTERY INNER TRIM GARNISHES	New	150.00	40.00
4	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00
5	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,700.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >