

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21005857/EVY3

Date: 08/06/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00003532100		
Claimant Vehicle No :	PC8091D	Insured Vehicle No :	CB8427D		
Date of Loss:	13/05/2021	Nature of Claim:	TP	Claim No:	SNM21D202775/C03/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8091D	Engine No:	ISBE4225B21870126
Make & Model:	HIGER KLQ6728, 3.8 D (M)	Chassis No:	LKLR1ESC08B002765
Reg. Date:	01/08/2009 (Man. Year: 2009)	Odometer:	523936 km
Colour:	Yellow		
Engine Capacity:	6692 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5 (D)
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4/4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	850.00	0.00	850.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	2,500.00	800.00	24.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	4,150.00	2,500.00	1,650.00	39.76

INSPECTION

Date of Assignment:	17/05/2021		
Date Inspected:	03/06/2022	Inspected At:	Ftl Auto (HQ) 566 Woodlands Road (Mandai Estate) Singapore 728697
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Jun 2022)	
Parts:	N/A	HIGER KLQ6728 3.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8091D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH LAST COMPARTMENT	Repaired	850.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	850.00 0.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 0.00
					Total Parts (\$\$)	850.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	2,400.00	2,000.00
2	LABOUR CHARGE	New	900.00	500.00
Gross Labour Cost (S\$)			3,300.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >