

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21005858/T1VF3N2**Date:** 21/12/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29139817AT2		
Claimant Vehicle No :	SGX1308Y	Insured Vehicle No :	SJN296X		
Date of Loss:	14/05/2021	Nature of Claim:	TP	Claim No:	635965

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX1308Y		
Make & Model:	HONDA STREAM, 1.8 (A)	Engine No:	R18A1747367
Reg. Date:	13/08/2007 (Man. Year: 2007)	Chassis No:	RN61041999
Colour:	Black	Odometer:	477787 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,412.00	4,815.92	3,596.08	42.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,700.00	2,260.00	4,440.00	66.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,112.00	7,075.92	8,036.08	53.18
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	15,112.00	3,000.00	12,112.00	80.15
+ GST 7.00/7.00% (\$\$)	1,057.84	210.00	847.84	80.15
Nett Amount (\$\$)	16,169.84	3,210.00	12,959.84	80.15

INSPECTION

Date of Assignment:	17/05/2021	
Date Inspected:	19/05/2021 Inspected At:	AP Automotive Services Pte Ltd 56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2021)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX1308Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	936.70 FL	*936.70 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	82.00 FL	*82.00 FL
3	1		*TAILGATE LOGO-HONDA	Necessary	59.00 FL	*59.00 FL
4	1		*TAILGATE EMBLEM-STREAM	Necessary	55.00 FL	*55.00 FL
5	1		*TAILGATE HANDLE GARNISH	Not Necessary	70.00 FL	*- FL
6	1		*TAILGATE HANDLE SWITCH	Not Necessary	95.00 FL	*- FL
7	1		*TAILGATE LOCK	Bent	135.00 FL	*135.00 FL
8	1		*TAILGATE CATCH	Not Necessary	76.00 FL	*- FL
9	1		*TAILGATE INNER TRIM	Deformed	174.00 FL	*174.00 FL
10	2		*TAILGATE DAMPER L+R	Not Necessary	396.00 FL	*- FL
11	2		*TAILGATE HINGE L+R	Not Necessary	194.00 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Cut	148.00 FL	*148.00 FL
13	1		*TAIL LAMP L+R	O/s Cut/N/s Not Necessary	705.00 FL	*352.50 FL
14	1		*TAIL LAMP PANEL L+R	O/s Bent/N/s Not Necessary	439.20 FL	*219.60 FL
15	1		*REAR BUMPER	Deformed	588.90 FL	*588.90 FL
16	1		*REAR BUMPER TOW COVER	Not Necessary	38.00 FL	*- FL
17	1		*REAR BUMPER RETAINER L+R	O/s Deformed/N/s Not Necessary	162.00 FL	*81.00 FL
18	2		*REAR BUMPER BRACKET L+R (NPA)	Not Necessary	0.00 FL	*- FL
19	1		*REAR BUMPER UNDERCOVER	Not Necessary	37.50 FL	*- FL
20	1		*REAR FENDER RH	Buckled	981.90 FL	*981.90 FL
21	1		*REAR FENDER INNER TRIM L+R	O/s Deformed/N/s Not Necessary	556.00 FL	*278.00 FL
22	1		*REAR FENDER COWLING L+R	O/s Missing/N/s Not Necessary	152.00 FL	*76.00 FL
23	1		*END PANEL	Bent	306.70 FL	*306.70 FL
24	1		*END PANEL TOP GARNISH	Deformed	172.00 FL	*130.90 FL
25	1		*SPAREWHEEL PANEL (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*SPAREWHEEL PANEL TOP BOARD RH	Deformed	468.00 FL	*260.80 FL
27	1		*EXHAUST PIPE	Bent	988.60 FL	*541.70 FL
28	1		*EXHAUST MOUNTING	Torn	161.00 FL	*37.20 FL
29	1		*EXHAUST HEAT SHIELD (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL
31	1		*REAR DOOR WEATHERSTRIP RH (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
33	1		*TAILGATE INNER TRIM CLIPS	Necessary	100.00 FS	*20.00 FS
34	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
35	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
36	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
37	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
38	1		*REAR FENDER SEALANT	Necessary	200.00 FS	*40.00 FS
39	1		*REAR FENDER INNER TRIM CLIPS	Necessary	100.00 FS	*30.00 FS
40	1		*REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
41	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS
42	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
43	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,047.50 5,904.90
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,635.50 1,088.98

Report was unsubmitted during this print-out.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	900.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	1,000.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
5	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
6	TO CHECK WATER LEAK	New	150.00	30.00
7	TO RNR FUEL TANK	New	250.00	0.00
8	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
9	TO RNR REAR TAILGATE MECHANISM	New	400.00	60.00
10	TO RNR REAR DOOR MECHANISM	New	400.00	0.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
12	TO PERFORM RUST PROOFING	New	400.00	30.00
Gross Labour Cost (\$)			6,700.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >