

ASS. REC. BY: Tough

REF: CS/MSG 21005858/T10f3

ASSIGNMENT

COE 2022 Aug.

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SGX 1308Y Yr Regn: 2007 Aug
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime mover /
 Truck / Trailer or
 Make: Honda Stream 1799
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 477787 T/Radio: Insured / Std / NI / NA
 Eng/No: RN61041999
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / R/Rim or
 Tyre Size: F: 205/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /
 TOYO / YOKO or Continental

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 19/5/21 @ 4.05pm
 Survey held at AP Auto

Des. of Damages: Fnt / Rear / O/S / N/S / U/C Rooftop or
Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bel. or Market Value: \$10K
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
WP
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: John Vehicle: IN / OUT

Date / Time	Action / Instruction
	Repair limit \$3500; inform John repair limit \$3000

Date/Time, File Pass to? ☐ : Prell. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?
 2) _____

Report Form: _____
 Lump Sum / L.B. / C: _____

Days Of Repair: _____
 Resurvey No. of Trips: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 \$ + \$ = \$
 Photos: _____
 Others: _____

Estimation

Date 5th 1308 Y
Vehicle SH 6298-J
Make/Model HONDA STREAM
Chassis No. RN61041999

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAILGATE	1		\$ bt 936.70
2	TAILGATE WINDSCREEN MOULDING	1	\$ 82.00	\$ net 82.00
3	TAILGATE LOGO - HONDA	1	\$ 59.00	\$ net 59.00
4	TAILGATE EMBLEM - STREAM	1	\$ 55.00	\$ net 55.00
5	TAILGATE HANDLE GARNISH	1	\$ 70.00	\$ x net 70.00
6	TAILGATE HANDLE SWITCH	1	\$ 95.00	\$ x net 95.00
7	TAILGATE LOCK	1	\$ 135.00	\$ bt 135.00
8	TAILGATE CATCH	1	\$ 76.00	\$ x net 76.00
9	TAILGATE INNER TRIM	1	\$ 174.00	\$ de 174.00
10	TAILGATE DAMPER L+R	2	\$ 198.00	\$ x net 396.00
11	TAILGATE HINGE L+R	2	\$ 97.00	\$ x net 194.00
12	TAILGATE WEATHERSTRIP	1	\$ 148.00	\$ net 148.00
13	TAIL LAMP L+R	2	<u>352.50</u>	\$ LHxRH 705.00
14	TAIL LAMP PANEL L+R	2	<u>219.60</u>	\$ LHxRH 439.20
15	REAR BUMPER	1		\$ de 588.90
16	REAR BUMPER TOW COVER	1	\$ 38.00	\$ x net 38.00
17	REAR BUMPER RETAINER L+R	2	\$ <u>81.00</u>	\$ LHxRH 162.00
18	REAR BUMPER BRACKET L+R	2		\$ LHxRH 40.00
19	REAR BUMPER UNDERCOVER	1	\$ 37.50	\$ x net 37.50
20	REAR FENDER RH	1		\$ bu 981.90
21	REAR FENDER INNER TRIM L+R	2	\$ <u>278.00</u>	\$ LHxRH 556.00
22	REAR FENDER COWLING L+R	2	\$ <u>76.00</u>	\$ LHxRH 152.00
23	END PANEL	1		\$ bt 306.70
24	END PANEL TOP GARNISH	1	\$ 172.00	\$ de 172.00
25	SPAREWHEEL PANEL	1		\$ x net -
26	SPAREWHEEL PANEL TOP BOARD	1	\$ 468.00	\$ RH de 468.00
27	EXHAUST PIPE	1		\$ bt 988.60
28	EXHAUST MOUNTING	1		\$ tn 161.00
29	EXHAUST HEAT SHIELD	1		\$ x net -
30	REAR DOOR RH	1		\$ RH -
31	REAR DOOR WEATHERSTRIP RH	1		\$ x net -
			Total	\$ 3,069.50
			Less 20%	\$ 613.90
			Total	\$ 2,455.60

S/Nett Items

1	TAILGATE WINDSCREEN SEALANT	1	150	\$ 40w	150.00
2	TAILGATE INNER TRIM CLIPS	1	100	\$ 20w	100.00
3	REAR NUMBER PLATE	1	120	\$ X nn	120.00
4	TAIL LAMP CLIPS	1	50	\$ 20w	50.00
5	REAR BUMPER CLIPS	1	100	\$ 30w	100.00
6	REAR BUMPER REVERSE SENSOR SET	1	300	\$ 200nn	300.00
7	REAR FENDER SEALANT	1	200	\$ 40w	200.00
8	REAR FENDER INNER TRIM CLIPS	1	100	\$ 30w	100.00
9	REAR FENDER COWLING CLIPS	1	100	\$ 20w	100.00
10	END PANEL SEALANT	1	250	\$ 40w	250.00
11	END PANEL TOP GARNISH CLIPS	1	100	\$ 20w	100.00
12	SPAREWHEEL PANEL SEALANT	1	300	\$ X nn	300.00
			Total	\$	1,570.00

460

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	1800	\$ 900.	1,800.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1600	\$ 1000	1,600.00
3	TO RNR REAR WINDSCREEN	1	400	\$ 120.	400.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ 30	150.00
5	TO RNR REAR INNER TRIM AND UPHOISTERY	1	400	\$ 60.	400.00
6	TO CHECK WATER LEAK	1	150	\$ 30.	150.00
7	TO RNR FUEL TANK	1	250	\$ X nn	250.00
8	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ X nn	600.00
9	TO RNR REAR TAILGATE MECHANISM	1	400	\$ 60.	400.00
10	TO RNR REAR DOOR MECHANISM	1	400	\$ X nn	400.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 30.	150.00
12	TO PERFORM RUST PROOFING	1	400	\$ 30.	400.00
					2260
	Total Labour			\$	6,700.00
	Parts Replacement Amount			\$	4,025.60
	Total Amount			\$	10,725.60

Taufhin 97495449
 'WP' 19/5/21 e 4:15 pm
 L/S Resurvey after repair
 Taufhin e lkharku van
 8 days.
 To met limit.

4355.92
 460
 2260
 7075.92
 20% 5660.73
 Repair limit \$3000
 COR US \$3000; 8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: