

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005860/KQF3E2**Date:** 09/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00004392100
Claimant Vehicle No :	SMM2866H	Insured Vehicle No :	SJH693P
Date of Loss:	10/05/2021	Nature of Claim:	TP
		Claim No:	SNM21D202754/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM2866H	Engine No:	2NRX446836
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3201177951
Reg. Date:	25/06/2019 (Man. Year: 2019)	Odometer:	55820 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 2 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,640.44	1,168.41	472.03	28.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,010.00	1,030.00	50.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,680.44	2,178.41	1,502.03	40.81
+ GST 8.00/8.00% (S\$)	294.44	174.27	120.17	40.81
Nett Amount (S\$)	3,974.88	2,352.68	1,622.20	40.81

INSPECTION

Date of Assignment:	19/05/2021	
Date Inspected:	18/05/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$325.08 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM2866H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	667.21 FL	*667.21 FL
2	1		*BOOTLID LOGO	Necessary	66.72 FL	*66.72 FL
3	1		*BOOTLID EMBLEM VIOS	Necessary	58.73 FL	*58.73 FL
4	1		*BOOTLID EMBLEM E	Necessary	59.64 FL	*59.64 FL
5	1		*BOOTLID LOCK	Repair	322.49 FL	*- FL
6	1		*BOOTLID STICKER 619	Necessary	80.00 FS	*80.00 FS
7	1		*REAR BUMPER	Buckled	388.92 FL	*388.92 FL
8	1		*REAR BUMPER SIDE RETAINER LH	*Check	113.44 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	113.44 FL	*- FL
10	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
11	1		*REAR BUMPER STICKER	Necessary	180.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,100.59	1,491.22
- List Item Discount on L Items 25.00/25.00% (\$\$)	460.15	322.81
Total Parts (\$\$)	1,640.44	1,168.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK ,STRAIGHTEN AND RENEW ACCIDENT REA SUCH AS BOOTLID ,REAR BUMPER ,REAR END PANEL AND ETC	New	850.00	480.00
2	TO PUTTY AND RESPRAY ACCIDENT AREA SUCH AS BOOTLID ,REAR BUMPER ,REAR END AND ETC	New	800.00	500.00
3	TO APPLY TUFF COAT	New	150.00	30.00
4	TO REMOVE AND INSTALL SPARE TYRE ,TOP BOARD TO FACILITATE REPAIR (*Check)	New	240.00	0.00
Gross Labour Cost (S\$)			2,040.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >