

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 3381Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	815.00	815.00
2	REAR BUMPER SIDE HOLDER-LH & RH @\$15.00	N/S BENT	30.00	15.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	210.00	-
1	REAR BUMPER REFLECTOR	NOT NECESSARY	22.00	-
1	REAR FENDER COWLING-LH	NOT NECESSARY	30.00	-
10	REAR FENDER COWLING CLIPS @\$6.00	NOT NECESSARY	60.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	506.00	-
1	REAR BUMPER TOP BEAM	NOT NECESSARY	82.00	-
1	TAIL LAMP N/S	CRACKED	855.00	675.00
	LESS 10% DISCOUNT		-266.00	-155.50
			2,394.00	1,399.50
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER SENSOR (SN)	SERVICEABLE	220.00	-
			220.00	-
	<u>LABOUR</u>			
	TO REPLACE/KNOCK OUT DENTS ON REAR END PANEL,FLOOR PANEL AND REAR FENDER INCLUDING AFFECTED ATTACHMENTS AND FITTINGS.CUT/WELD AND REALIGN.		800.00	600.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		550.00	450.00
	TO CHECK WIRING.		50.00	20.00
	TO TRANSFER REAR BUMPER SENSOR.		120.00	50.00
	TO TUFF-KOTE.	NOT NECESSARY	60.00	-
	TO REMOVE AND REFIT END PANEL GARNISH TO FACILITATE REPAIR.		80.00	80.00
			1,660.00	1,200.00
	GRAND TOTAL		4,274.00	2,599.50

Report Ref No. CS/SMO21005864/Uuf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO21005864/Uuf3n2

CHUA KANG SENG Licensed Appraiser