



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 2289C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR MUD GUARD BRACKET (UPPER) (CONSISTENT)	NOT NECESSARY	87.00	-
1	REAR MUD GUARD BRACKET (LOWER) (CONSISTENT)	BENT	75.00	75.00
1	REAR MUD GUARD (CONSISTENT)	DISTORTED	68.00	68.00
1	NUMBER PLATE LIGHT (CONSISTENT)	CRACKED	53.00	53.00
1	REAR RIM (CONSISTENT)	TO REPAIR SEE LABOUR	524.00	-
1	REAR SWING ARM (CONSISTENT)	BENT	489.00	489.00
2	REAR SWING ARM BEARING @\$21.60 (CONSISTENT)	NOT NECESSARY	43.20	-
2	REAR SWING ARM BUSH @\$18.70 (CONSISTENT)	NECESSARY	37.40	37.40
1	REAR EXHAUST ASSY (CONSISTENT)	NOT NECESSARY	631.00	-
1	REAR EXHAUST END COVER (CONSISTENT)	NOT NECESSARY	65.00	-
	LESS 10% DISCOUNT		-207.26	-72.24
			1,865.34	650.16
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	BENT	50.00	12.00
1	REAR TYRE(SN) (CONSISTENT)	NOT NECESSARY	200.00	-
1	REAR BOX BACK (SN) (CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR BOX (SN) (CONSISTENT)	NOT NECESSARY	200.00	-
			600.00	12.00
<u>LABOUR</u>				
	TO PROVIDE LABOUR CHARGES ,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR RIM.		500.00	220.00
			500.00	220.00
GRAND TOTAL			2,965.34	882.16

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			700.00
---	--	--	---------------

Report Ref No. CC4/ASM21005865/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.