

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005867/URA3Q2
Date: 09/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100134571
Claimant Vehicle No :	FBP9568L	Insured Vehicle No :	SJQ3054S
Date of Loss:	09/05/2021	Nature of Claim:	TP
		Claim No:	4461764210SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP9568L	Engine No:	G3H6E0014509
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG431000011652
Reg. Date:	10/07/2019 (Man. Year: 2019)	Odometer:	67981 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	Timsun 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	723.00	320.40	402.60	55.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	245.00	100.00	145.00	59.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	968.00	420.40	547.60	56.57
+ GST 7.00/7.00% (S\$)	67.76	29.43	38.33	56.57

Nett Amount (S\$)	1,035.76	449.83	585.93	56.57
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
 No. 6 Defu Lane 4
 Singapore 539410

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BEARING 6300-2N2 (NSK)	Not Necessary	32.00 F	*- FL
2	2		*EMBLEM ABS	Not Necessary	10.00 F	*- FL
3	1		*HEADLAMP ASSY	Cracked	299.00 F	*299.00 FL
4	1		*LAMP SIGNAL FRONT LH	Not Necessary	34.00 F	*- FL
5	1		*LAMP SIGNAL FRONT RH	Not Necessary	34.00 F	*- FL
6	1		*MUDGUARD FRONT (GREY)	Cracked	45.00 F	*45.00 FL
7	1		*RIM SPORT FRONT (BLACK)	Not Necessary	238.00 F	*- FL
8	2		*SEAL OIL FRONT RIM 20X35X7	Not Necessary	10.00 F	*- FL
9	1		*VALVE RIM	Not Necessary	9.00 F	*- FL
10	1		*AXLE FRONT WHEEL	Bent	12.00 F	*12.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	723.00	356.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	35.60
Total Parts (S\$)	723.00	320.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	189.00	100.00
2	TRANSPORT CHARGES	New	56.00	0.00
			Gross Labour Cost (S\$)	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >