

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21005872/EVF3E2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant:	TEH GAIK LEAN	Policy No:	1800004413	
Date of Loss:	15/05/2021	Nature of Claim:	OD	Claim No: 7477172600SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9469P	Engine No:	G4FGHH692158
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFJ411MJ5761784
Reg. Date:	24/01/2018 (Man. Year: 2017)	Odometer:	67870 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,476.40	7,990.00	2,486.40	23.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,725.00	8,705.00	2,020.00	18.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,201.40	16,695.00	4,506.40	21.26
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	20,901.40	16,395.00	4,506.40	21.56
+ GST 7.00/7.00% (S\$)	1,463.10	1,147.65	315.45	21.56
Nett Amount (S\$)	22,364.50	17,542.65	4,821.85	21.56

INSPECTION

Date of Assignment:	17/05/2021	
Date Inspected:	17/05/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	20.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH TYRE	Not Necessary	260.00 FS	*- FS
2	1		*FRT RH RIM	Cut	300.00 FS	*260.00 FS
3	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
4	1		*LAMP ASSY-HEAD, LH	Broken	810.00 FL	*810.00 FL
5	1		*LAMP ASSY-REAR COMBINATION, LH	Broken	368.00 FL	*368.00 FL
6	1		*GEAR ASSY-STEERING	Not Necessary	832.00 FL	*- FL
7	1		*KNUCKLE-FRONT AXLE, LH	Bent	350.00 FL	*350.00 FL
8	1		*HUB ASSY-FR WHEEL	Jammed	150.00 FL	*150.00 FL
9	1		*BAR ASSY-FR STABILIZER	Not Necessary	254.00 FL	*- FL
10	1		*LINK-STABILIZER	Bent	72.00 FL	*72.00 FL
11	1		*STRUT ASSY-FR, LH	Bent	280.00 FL	*280.00 FL
12	1		*PAD-FRONT SPRING, LWR	Necessary	23.00 FL	*23.00 FL
13	1		*BEARING-STRUT	Necessary	54.00 FL	*54.00 FL
14	1		*INSULATOR ASSY-STRUT	Necessary	93.00 FL	*93.00 FL
15	1		*PANEL-FENDER, LH	Dented	376.00 FL	*376.00 FL
16	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL
17	1		*CROSSMEMBER COMPL	Bent	1,330.00 FL	*1,330.00 FL
18	1		*ARM COMPLETE-FRONT DOOR, LH	Bent	380.00 FL	*380.00 FL
19	1		*PANEL ASSY-FRONT DOOR, LH	Dented	1,542.00 FL	*1,542.00 FL
20	1		*PANEL ASSY-QUARTER OUTER, LH	Dented	1,213.00 FL	*1,213.00 FL
21	1		*INSULATOR-FENDER LH	Necessary	28.00 FL	*28.00 FL
22	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
23	1		*LIP ASSY-FRONT BUMPER	Not Necessary	55.00 FL	*- FL
24	1		*DUCT ASSY-FR BUMPER, LH	Broken	33.00 FL	*33.00 FL
25	1		*COVER-BLANKING FR FOG LH	Not Necessary	18.00 FL	*- FL
26	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
27	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
28	1		*RAIL ASSY-FR BUMPER	Not Necessary	496.00 FL	*- FL
29	1		*BRACKET-FR BUMPER SIDE MTG, LH	Broken	13.00 FL	*13.00 FL
30	1		*GUARD ASSY-FRONT WHEEL, LH	Crushed	95.00 FL	*95.00 FL
31	1		*COVER-RR BUMPER	Dented	688.00 FL	*688.00 FL
32	1		*COVER-RR BUMPER, CTR	Cut	315.00 FL	*315.00 FL
33	1		*BRACKET-RR BUMPER SIDE MTG, LH	Broken	29.00 FL	*29.00 FL
34	1		*BLACK TAPE-FRT DOOR FRAME UPR	Necessary	13.00 FL	*13.00 FL
35	1		*BLACK TAPE-FR DR RR, LH	Necessary	12.00 FL	*12.00 FL
36	1		*W/STRIP ASSY-FR DR BELT O/S LH	Not Necessary	58.00 FL	*- FL
37	1		*W/STRIP ASSY-FR DR SIDE LH	Not Necessary	122.00 FL	*- FL
38	1		*DUCT ASSY-AIR CURTAIN, LH	Broken	6.00 FL	*6.00 FL
39	1		*BEARING-FRONT WHEEL HUB	Necessary	131.00 FL	*131.00 FL
			(Supplementary)			
40	1		*HOSE-BRAKE FRONT, LH	Bent	84.00 FL	*84.00 FL
			(Supplementary)			
41	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
			(Supplementary)			
42	1		*MOUNTING CLIPS	Necessary	5.00 FL	*5.00 FL
			(Supplementary)			
43	1		*CLIPS (X20)	Necessary	40.00 FL	*40.00 FL
			(Supplementary)			
44	1		*HINGE ASSY-REAR DOOR UPPER, RH	Bent	33.00 FL	*33.00 FL
			(Supplementary)			
45	1		*MOUNTING CLIP-REAR COMBI	Necessary	5.00 FL	*5.00 FL
			(Supplementary)			
46	1		*LAMP ASSY-SIDE REPEATER, LH	Missing	30.00 FL	*30.00 FL
			(Supplementary)			
47	1		*DUCT ASSY-EXTENSION	Broken	144.00 FL	*144.00 FL
			(Supplementary)			
48	1		*FILM-ANTI CHIPPG LH	Necessary	27.00 FL	*27.00 FL
			(Supplementary)			

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*HINGER ASSY-DOOR UPPER, LH (Supplementary)	Bent	26.00 FL	*26.00 FL
50	1		*TUBE-N/CYL TO FRONT BRAKE, LH (Supplementary)	Bent	46.00 FL	*46.00 FL
51	1		*MOULDING-REAR WINDOW GLASS (Supplementary)	Necessary	27.00 FL	*27.00 FL
52	1		*W/STRIP ASSY-RR DR BELT O/S LH (Supplementary)	Broken	89.00 FL	*89.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,943.00	9,915.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,466.60	1,925.00
Total Parts (\$)	10,476.40	7,990.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, FRT LH FENDER, FRT LH DOOR, REAR LH FENDER, REAR BUMPER & AFFECTED AREA. REPAIR ON LH ROCKER PANEL, FRT LH A-PILLAR & FRT LH FENDER INNER	New	4,000.00	2,400.00
2	PAINT WORK ON FRT BUMPER, BONNET, FRT LH FENDER, FRT LH DOOR, REAR LH FENDER, REAR BUMPER, LH ROCKER PANEL, FRT LH A-PILLAR & FRT LH FENDER INNER	New	3,150.00	2,800.00
3	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	80.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	180.00	180.00
5	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	140.00	140.00
6	TO REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR	New	400.00	400.00
7	TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL	New	150.00	120.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	TO CONDUCT COMPUTERISE FULL WHEEL ALIGNMENT	New	120.00	120.00
11	TO TRANSFER FRT RH RIM INCLUDING BALANCING	New	30.00	30.00
12	REPLACE FRT UNDERCARRIAGE	New	400.00	400.00
13	PERFORM RUST PREVENTION	New	80.00	80.00
14	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	80.00
15	REPAIR LH ROCKER PANEL, & LH FRONT WHEEL HOUSING (Supplementary)	New	800.00	800.00
16	RESPRAY ON LH ROCKER PANEL, LH FRONT WHEEL HOUSING, LH REAR DOOR (Supplementary)	New	525.00	525.00
17	REMOVE & INSTALL FUSE BOX WIRING TO FACILITATE REPAIR (Supplementary)	New	200.00	200.00
18	CHECK & BLEED ON BRAKING SYSTEM (Supplementary)	New	200.00	200.00
Gross Labour Cost (\$\$)			10,725.00	8,705.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >