

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--|-----------------|-------|------------------------|--|
| | AXA INSURANCE | PTE LTD | | Ref: | CC4/ASM21005874/Bpa3q2 | |
| | 8 SHENTON WAY AXA TOWERSING | | | Date: | 07/10/2021 | |
| | ATTN:KHOR SAW | THENG | | Code: | ASM | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHC 1511A | Veh. Inspected | | SMX 9175P | |
| | Policy No. | VFX/P2419138 | Coverage (\$) | | 0.00 | |
| | Claim No. | S1M039SJ | Excess (\$) | | 0.00 | |
| | Assign From | | Assign Date | | 17/05/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | MITSUBISHI EVO X | c.c | | 1998 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2007 | |
| | Chassis No. | CZ4A0000602 | Colour | | WHITE | |
| | Odometer | 38456 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 265/35 R18 | DUNLOP | | 5 mm | |
| | L/H Front Tyre | 265/35 R18 | DUNLOP | | 5 mm | |
| | R/H Rear Tyre | 265/35 R18 | DUNLOP | | 5 mm | |
| | L/H Rear Tyre | 265/35 R18 | DUNLOP | | 5 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | 5. General Information | | | | | |
| | Accident Date | 10/05/2021 | Inspection Date | e | 17/05/2021 | |
| | Survey held at | BIFROST AUTO PTE LTD | | | | |
| | | 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | |
| | | | | | | |