

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005877/GRS3Q2
Date: 25/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100507736
Claimant Vehicle No :	SHD4800R	Insured Vehicle No :	SLN573Y
Date of Loss:	14/05/2021	Nature of Claim:	TP
		Claim No:	0280049796SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4800R	Engine No:	G4LEKU298694
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 (A)	Chassis No:	KMHC851CVKU164953
Reg. Date:	24/07/2019 (Man. Year: 2019)	Odometer:	203932 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,715.96	637.64	1,078.32	62.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	640.00	180.00	21.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,535.96	1,277.64	1,258.32	49.62
+ GST 7.00/7.00% (S\$)	177.52	89.43	88.09	49.62

Nett Amount (S\$)	2,713.48	1,367.07	1,346.41	49.62
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,069.83		

INSPECTION

Date of Assignment: 17/05/2021

Date Inspected: 17/05/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	276.20 FL	*- FL
4	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL
5	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	155.00 FL	*- FL
6	10		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER TOW COVER	Cut	98.80 FL	*98.80 FL
8	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS
9	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
					Sub Total (S\$)	2,087.45
					- List Item Discount on L Items 20.00/20.00% (S\$)	371.49
					Total Parts (S\$)	1,715.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSOR	New	120.00	40.00
Gross Labour Cost (\$\$)			820.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >