

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005880/GGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070116560
Claimant Vehicle No :	SHA1053R	Insured Vehicle No :	SMU4233D
Date of Loss:	15/05/2021	Nature of Claim:	TP
		Claim No:	0510641915SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1053R	Engine No:	G4LEKU397240
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU186517
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	216628 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,355.72	4,342.40	2,013.32	31.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,300.00	620.00	32.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,275.72	5,642.40	2,633.32	31.82
+ GST 7.00/7.00% (S\$)	579.30	394.97	184.33	31.82
Nett Amount (S\$)	8,855.02	6,037.37	2,817.65	31.82
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (S\$)		625.95		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,915.32		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment:	17/05/2021	
Date Inspected:	17/05/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Cracked	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL
4	1		*REAR BUMPER STAY LH	Bent	138.10 FL	*138.10 FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*BOOTLID COVER	Buckled	2,480.40 FL	*2,480.40 FL
7	1		*BOOTLID H EMBLEM	Necessary	38.00 FL	*38.00 FL
8	1		*BOOTLID EMBLEM IONID	Necessary	31.80 FL	*31.80 FL
9	1		*BOOTLID EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
10	1		*BOOTLID LAMP LH	Scratched	870.40 FL	*870.40 FL
11	1		*TAILLAMP LH	Not Necessary	794.40 FL	*- FL
12	1		*REAR FLECTOR LH	Not Necessary	41.45 FL	*- FL
13	1		*REAR BUMPER TOW COVER	Cut	98.80 FL	*98.80 FL
14	1		*RADAR BLIND SPOT LH	Not Necessary	1,625.00 FL	*- FL
15	2		*REAR BUMPER BRACKET LH	Not Necessary	55.80 FL	*- FL
16	1		*BOOTLID COMFORT APP STICKER	Necessary	40.00 FS	*40.00 FS
17	2		*BOOTLID COMFORT /TEL NUMBER STICKER	Necessary	60.00 FS	*60.00 FS
18	1		*REAR NUMBER PLATE W/HOLDER	Cracked	55.00 FS	*55.00 FS
19	1		*REAR REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
					Sub Total (S\$)	7,860.90 5,344.25
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,505.18 1,001.85
					Total Parts (S\$)	6,355.72 4,342.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	TOWING FEE	New	60.00	60.00
4	DIAGNOSE AND RESET ERROR CODE	New	240.00	0.00
5	TUFF KOTE	New	60.00	0.00
6	REMOVE/REFIX REVERSE SENSOR	New	60.00	40.00
Gross Labour Cost (\$\$)			1,920.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >