

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21005883/DES3Q2
Date: 01/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJZ1951T	Insured Vehicle No :	SMR5916B
Date of Loss:	16/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002212

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ1951T		
Make & Model:	HONDA CIVIC, 1.5 VTi (M)	Engine No:	B16A21007489
Reg. Date:	04/06/1992 (Man. Year: 1992)	Chassis No:	JHMEG63900S003782
Colour:	Red	Odometer:	477372 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,985.76	1,334.08	18,651.68	93.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	850.00	4,250.00	83.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,085.76	2,184.08	22,901.68	91.29
Approved Total (Overridden) (S\$)		1,750.00		

(S\$)	25,085.76	1,750.00	23,335.76	93.02
+ GST 7.00/7.00% (S\$)	1,756.00	122.50	1,633.50	93.02
Nett Amount (S\$)	26,841.76	1,872.50	24,969.26	93.02
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 17/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047**Adjuster:** BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2021)
Parts:	143	HONDA CIVIC 1.5 VTi (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ1951T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,380.00 FL	*552.90 FL
2	1		*BONNET INSULATOR	Not fitted	310.00 FL	*- FL
3	1		*BONNET SEAL	Not Necessary	150.00 FL	*- FL
4	1		*HEAD LAMP LH/RH	O/SNot Necessary/N/SMtgBroken	3,780.00 FL	*426.70 FL
5	2		*HEAD LAMP PANEL LH/RH	Not Necessary	402.80 FL	*- FL
6	1		*HEAD LAMP WIRE HARNESS	Not Necessary	1,992.00 FL	*- FL
7	2		*FRONT SIGNAL LAMP LH/RH	Not Necessary	2,008.40 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	190.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not fitted	423.00 FL	*- FL
10	1		*FRONT REINFORCEMENT BAR	Not fitted	992.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL	Repair	2,680.00 FL	*- FL
12	1		*FRONT HORN	Not Necessary	198.00 FL	*- FL
13	1		*A/C CONDENSOR	Not Necessary	1,890.00 FL	*- FL
14	1		*A/C CONDENSOR DISCHARGE HOSE	Not Necessary	310.00 FL	*- FL
15	1		*A/C CONDENSOR SUCTION HOSE	Not Necessary	295.00 FL	*- FL
16	1		*RADIATOR	Not Necessary	2,194.00 FL	*- FL
17	1		*RADIATOR FAN MOTOR	Not Necessary	450.00 FL	*- FL
18	1		*RADIATOR FAN BLADE	Not Necessary	231.00 FL	*- FL
19	1		*RADIATOR FAN COWLING	Not Necessary	481.00 FL	*- FL
20	1		*FRONT BUMPER	Distorted	2,600.00 F	*663.00 FN
21	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
22	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*FRONT NO PLATE	Not Necessary	100.00 FS	*- FS
24	1		*COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)

24,257.20

1,662.60

- List Item Discount on L Items 20.00/20.00% (\$\$)

4,271.44

195.92

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- Nett Item Discount on N Items 0.00/20.00% (S\$)						0.00132.60
Total Parts (S\$)						19,985.761,334.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	200.00	20.00
4	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
5	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			5,100.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >