



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2202979

INV Date 20/05/2022

Reference CC4/LPC21005885/Tga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLX 8853J
Insured Veh. XD 6555X
Claim No. 20/21/21/VC00/024546
Policy No. Z/20/VC00/107172-001
Accident Date 07/05/2021
Inspection Date 18/05/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21005885/Tga3q2 Date: 20/05/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 6555X	Veh. Inspected	SLX 8853J	
Policy No.	Z/20/VC00/107172-001	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024546	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	17/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDGG20W60J007975	Colour	BLACK	
Odometer	46744 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	CST	6 mm	
L/H Front Tyre	195/65 R15	CST	6 mm	
R/H Rear Tyre	195/65 R15	CST	6 mm	
L/H Rear Tyre	195/65 R15	CST	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2021	Inspection Date	18/05/2021	
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #01-87 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 8853J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	499.50	499.50
2	REAR BUMPER SIDE BRACKET L/R @\$68.50	NOT NECESSARY	137.00	-
2	REAR BUMPER SIDE REFLECTOR L/R @\$69.60	NOT NECESSARY	139.20	-
2	REAR BUMPER SIDE RETAINER L/R @\$64.43	NOT NECESSARY	128.86	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	477.20	-
1	REAR END PANEL TOP GARNISH	DEFORMED	202.50	202.50
1	SET REAR END PANEL TOP GARNISH CLIPS	NECESSARY	28.00	10.00
1	REAR END PANEL SENSOR	CRACKED	151.80	151.80
1	REAR TAILGATE	BENT	1,209.65	1,209.65
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	68.50	68.50
1	REAR TAILGATE 'VALVE Matic' EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE MECHANISM LOCK	BENT	409.00	269.00
2	REAR TAILGATE REFLECTOR LAMP L/R @\$232.90	N/S CRACKED / O/S NOT NECESSARY	465.80	232.90
1	REAR TAILGATE WEATHER STRIP	TWISTED	220.60	220.60
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	132.40	132.40
2	REAR TAILLAMP L/R	NOT NECESSARY	321.50	-
	LESS 25% DISCOUNT		-1,161.63	-762.96
			3,484.88	2,288.89
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
			870.00	270.00
<u>LABOUR</u>				
	DIAGNOSE ,REPLACE AND /OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120.00	30.00
	TO REMOVE,REFIX /RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.		100.00	30.00

Report Ref No. CC4/LPC21005885/Tga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REINSTALL REAR TAILGATE WINDSCREEN (TO FR).		200.00	120.00
	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR).		100.00	60.00
	TO TRANSFER TAILGATE /BOOTLID MECHANISM AND WIRING ASSY (TO FR).		150.00	60.00
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT.		1,200.00	700.00
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,200.00	700.00
	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL.		150.00	30.00
			3,220.00	1,730.00
GRAND TOTAL			7,574.88	4,288.89
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC4/LPC21005885/Tga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLX 8853J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLX 8853J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

