

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005891/T1PA3Q2
Date: 12/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027944	
Claimant Vehicle No :	SHC6995D	Insured Vehicle No :	SLT8756C	
Date of Loss:	14/05/2021	Nature of Claim:	TP	Claim No: 3152070449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6995D		
Make & Model:	KIA OPTIMA, 1.7 D (A)	Engine No:	D4FDFH314432
Reg. Date:	30/12/2015 (Man. Year: 2015)	Chassis No:	KNAGM414MF5658193
Colour:	Silver	Odometer:	593167 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,052.90	0.00	2,052.90	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	630.00	700.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,382.90	630.00	2,752.90	81.38
+ GST 7.00/7.00% (S\$)	236.80	44.10	192.70	81.38

Nett Amount (S\$)	3,619.70	674.10	2,945.60	81.38
<hr/>				
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$67.76/day) (S\$)		203.28		
+ Doc/Search Fee (S\$)		2.00		
<hr/>				
Nett Liability (S\$)		1,029.38		
<hr/>				
Global Sum Settlement (S\$)		1,000.00		
<hr/>				

INSPECTION

Date of Assignment: 17/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (Changi)
 23 Changi South Ave 2 #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	696.00 FL	*- FL
2	1		*REAR BUMPER LOWER COVER	Repair	206.00 FL	*- FL
3	1		*REAR BUMPER INNER SPONGE	Not Necessary	114.00 FL	*- FL
4	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Not Necessary	58.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	607.00 FL	*- FL
6	2		*REAR BUMPER STAY O/S & N/S	Not Necessary	108.00 FL	*- FL
7	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	*- FL
8	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
10	1		*SET REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
11	1		*REAR BUMPER TOP PROTECTOR	Not Necessary	80.00 FS	*- FS
12	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,239.00	0.00
- List Item Discount on L Items 10.00/10.00% (\$)	186.10	0.00
Total Parts (\$)	2,052.90	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR RESHAPE AND ADJUST OF THE END PANEL ,ETC	New	550.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL	New	400.00	400.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (S\$)			1,330.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >