

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21005892/GPA3Q2

Date:

27/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

7210009136

Claimant Vehicle No : SHC6495E**Insured Vehicle No :**

SMX7687S

Date of Loss: 13/05/2021

Nature of Claim:

TP

Claim No:

8531452615SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC6495E**

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No:

D4FDEH313565

Reg. Date: 08/07/2015 (Man. Year: 2014)

Chassis No:

KNAGM414MF5593720

Colour: Silver

Odometer:

678136 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size:

205/65 R16

Front Left Side: Maxxis 6 mm

Rear Left Side:

Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side:

Maxxis 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,746.10	897.80	1,848.30	67.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	440.00	1,390.00	75.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,576.10	1,337.80	3,238.30	70.77
Approved Total (Overridden) (S\$)		1,050.00		

(S\$)	4,576.10	1,050.00	3,526.10	77.05
+ GST 7.00/7.00% (S\$)	320.33	73.50	246.83	77.05
Nett Amount (S\$)	4,896.43	1,123.50	3,772.93	77.05
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$67.76/day) (S\$)		271.04		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,596.54		
Global Sum Settlement (S\$)		1,590.00		

INSPECTION

Date of Assignment: 17/05/2021

Date Inspected: 17/05/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID WEATHERSTRIP	Not Necessary	96.00 FL	*- FL
2	1		*BOOTLID LOWER GARNISH	Not Necessary	290.00 FL	*- FL
3	1		*BOOTLID CRDI	Not Necessary	29.00 FL	*- FL
4	1		*BOOTLID EMBLEM	Not Necessary	27.00 FL	*- FL
5	1		*END PANEL INNER GARNISH	Not Necessary	74.00 FL	*- FL
6	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
7	1		*REAR BUMPER LOWER COVER	Cut	206.00 FL	*206.00 FL
8	1		*REAR BUMPER INNER SPONGE	Not Necessary	114.00 FL	*- FL
9	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Not Necessary	58.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Not Necessary	607.00 FL	*- FL
11	2		*REAR BUMPER STAY O/S & N/S	Not Necessary	108.00 FL	*- FL
12	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	*- FL
13	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	*- FL
14	2		*REAR BUMPER N/S & O/S REFLECTOR	Not Necessary	92.00 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
16	1		*SET REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
17	1		*SET BOOTLID LOWER GARNISH CLIPS	Necessary	38.00 FS	*38.00 FS
18	1		*SET BOOTLID STICKERS	Not Necessary	100.00 FS	*- FS
19	1		*REAR NO.PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
20	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	38.00 FS	*- FS
21	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,993.00	988.00
- List Item Discount on L Items 10.00/10.00% (S\$)	246.90	90.20
Total Parts (S\$)	2,746.10	897.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	40.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR RESHAPE AND ADJUST OF THE END PANEL ,ETC	New	850.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON BOOTLID LOWER GARNISH ,REAR BUMPER ,END PANEL	New	600.00	200.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (S\$)			1,830.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >