

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21005894/ETF3E2

Date: 08/07/2021

REFERENCE

Insured/Claimant:	STELLA NG KIN WAH	Policy No:	2070116560		
Date of Loss:	15/05/2021	Nature of Claim:	OD	Claim No:	0510641915SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4233D	Engine No:	G4LDD035882
Make & Model:	KIA SELTOS, 1.4 DCT (A)	Chassis No:	MZBER811VLN121357
Reg. Date:	13/08/2020 (Man. Year: 2020)	Odometer:	7345 km
Colour:	Orange		
Engine Capacity:	1353 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,900.80	12,059.60	841.20	6.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,255.00	3,375.00	880.00	20.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,155.80	15,434.60	1,721.20	10.03
- Excess (S\$)	3,400.00	3,400.00	0.00	0.00
(S\$)	13,755.80	12,034.60	1,721.20	12.51
+ GST 7.00/7.00% (S\$)	962.91	842.42	120.49	12.51
Nett Amount (S\$)	14,718.71	12,877.02	1,841.69	12.51

INSPECTION

Date of Assignment:	18/05/2021	
Date Inspected:	17/05/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*EMBLEM-SYMBOL MARK KIA	Necessary	43.00 FL	*43.00 FL
4	1		*EMBLEM-GT LINE	Necessary	31.00 FL	*31.00 FL
5	1		*PANEL ASSY-HOOD	Dented	1,073.00 FL	*1,073.00 FL
6	1		*LAMP ASSY-HEAD, RH	Broken	3,547.00 FL	*3,547.00 FL
7	1		*CONDENSER ASSY-COOLER	Bent	639.00 FL	*639.00 FL
8	1		*GUARD-AIR	Not Necessary	140.00 FL	*- FL
9	1		*RADIATOR ASSY	Bent	492.00 FL	*492.00 FL
10	1		*BLOWER ASSY	Broken	574.00 FL	*574.00 FL
11	1		*BEAM COMPLETE-FR BUMPER	Bent	364.00 FL	*364.00 FL
12	1		*MEMBER ASSY-RADIATOR SUPT, UPR	Broken	179.00 FL	*179.00 FL
13	1		*MEMBER ASSY-RADIATOR SUPT, LWR	Not Necessary	113.00 FL	*- FL
14	1		*COVER-FR BUMPER, UPR	Broken	229.00 FL	*229.00 FL
15	1		*COVER-FR BUMPER, LWR	Not Necessary	229.00 FL	*- FL
16	1		*GRILLE-FRONT BUMPER	Broken	78.00 FL	*78.00 FL
17	1		*SKID PLATE-FR BUMPER	Cut	522.00 FL	*522.00 FL
18	1		*PIECE-FRONT BUMPER, LWR	Broken	21.00 FL	*21.00 FL
19	1		*LIP-FR BUMPER	Not Necessary	37.00 FL	*- FL
20	1		*COVER-RADIATOR GRILLE UPR	Not Necessary	62.00 FL	*- FL
21	1		*GARNISH-RADIATOR GRILLE	Not Necessary	433.00 FL	*- FL
22	1		*GRILLE ASSY-RADIATOR, LWR	Broken	68.00 FL	*68.00 FL
23	1		*PIECE-RADIATOR GRILLE NO.2	Broken	448.00 FL	*448.00 FL
24	1		*GRILLE-RADIATOR	Broken	302.00 FL	*302.00 FL
25	1		*BRACKET-REINF	Broken	22.00 FL	*22.00 FL
26	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	149.00 FL	*149.00 FL
27	1		*BRACKET-FR BUMPER SIDE, LH	Broken	8.00 FL	*8.00 FL
28	1		*BRACKET-FR BUMPER SIDE, RH	Broken	8.00 FL	*8.00 FL
29	1		*PANEL- FENDER - RH	Dented	392.00 FL	*392.00 FL
30	1		(Supplementary) *GUARD-AIR	Broken	140.00 FL	*140.00 FL
31	1		(Supplementary) *HORN ASSY-LOW PITCH	Bent	58.00 FL	*58.00 FL
32	1		(Supplementary) *LAMP ASSY-HEAD, LH	Broken	3,547.00 FL	*3,547.00 FL
33	1		(Supplementary) *RIVET-BLIND	Necessary	10.00 FL	*10.00 FL
34	1		(Supplementary) *COVER-RADIATOR GRILLE UPR	Crushed	62.00 FL	*62.00 FL
35	1		(Supplementary) *CLIP	Necessary	10.00 FL	*10.00 FL
36	1		(Supplementary) *CAP-FRONT HOOK	Crushed	3.00 FL	*3.00 FL
37	1		(Supplementary) *LAMP ASSY-FRONT AUXILIARY, LH	Broken	499.00 FL	*499.00 FL
38	1		(Supplementary) *LAMP ASSY-FRONT AUXILIARY, RH	Broken	499.00 FL	*499.00 FL
39	1		(Supplementary) *LATCH ASSY-HOOD	Bent	119.00 FL	*119.00 FL
40	1		(Supplementary) *COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
41	1		(Supplementary) *ULTRASONIC SENSOR ASSY-P.A.S	Broken	163.00 FL	*163.00 FL
42	1		(Supplementary) *GARNISH-RADIATOR GRILLE	Broken	433.00 FL	*433.00 FL
43	1		(Supplementary) *COVER-FR BUMPER, LWR	Cut	229.00 FL	*229.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **16,101.00** **15,057.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, BONNET, SUPPORT & AFFECTED AREA	New	1,600.00	800.00
2	PAINT WORK ON FRT BUMPER & BONNET	New	700.00	700.00
3	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	PERFORM RUST PREVENTION	New	80.00	0.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	REPLACE RH FRONT FENDER (Supplementary)	New	400.00	400.00
9	REPAIR RH FRONT HEADLAMP SUPPORT (Supplementary)	New	200.00	200.00
10	REPLACE FRONT UPPER SUPPORT PANEL (Supplementary)	New	400.00	400.00
11	SPRAY PAINT RH FRONT FENDER (Supplementary)	New	350.00	350.00
12	SPRAY PAINT RH FRONT HEADLAMP SUPPORT (Supplementary)	New	175.00	175.00
Gross Labour Cost (\$\$)			4,255.00	3,375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >