



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 7868H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	FENDER SUB-ASSY, FR (SN)	DENTED	850.30	850.30
1	LINER, FR FENDER, RH (SN)	NOT NECESSARY	172.70	-
1	EMBLEM, SIDE PANEL (SN)	NECESSARY	54.60	54.60
1	CAP SUB-ASSY, WHEEL (SN)	CUT	235.70	235.70
			1,343.30	1,170.60
	<u>LABOUR</u>			
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	TO CHECK WIRING AND LIGHTING.		122.40	122.40
	TO CONDUCT WHEEL ALIGNMENT CHECK.	NOT NECESSARY	180.00	-
	TO REPLACE / REPAIR FRONT RH SIDE ACCIDENT DAMAGE PARTS.		2,880.00	1,080.00
	TO SPRAY PAINT ON FRONT RH SIDE ACCIDENT AFFECTED AREAS.		2,950.00	1,770.00
			6,312.40	3,152.40
	GRAND TOTAL		7,655.70	4,323.00
	RECOMMENDED COST OF REPAIRS			4,323.00

Report Ref No. CS/SMR21005899/Euf3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.