



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 6202A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	CUT	738.00	738.00
1	RR CENTRAL STRIP-CHROME (SN)	NOT NECESSARY	225.00	-
1	OVERRIDER-RH REAR BUMPER (SN)	CUT	225.00	225.00
1	WING MOULDING RHR (SN)	NOT NECESSARY	175.50	-
6	CLIP (SN)	NECESSARY	5.40	5.40
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			1,468.90	988.40
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER,REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		600.00	600.00
	TO RESPRAY REAR BUMPER.		600.00	300.00
	TO TRANSFER REVERSE SENSORS.	NOT NECESSARY	600.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NOT NECESSARY	300.00	-
	TO REPROGRAMME ECU SYSTEM AND CLEAR FAULT CODE AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			2,700.00	1,500.00
	GRAND TOTAL		4,168.90	2,488.40
	RECOMMENDED COST OF REPAIRS			2,488.40

Report Ref No. CS/SMR21005905/Euf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.