

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD		Ref:	CS3/ASM21005906/Bqce2	
	8 SHENTON WAY AXA TOWERSING		Date:	24/06/2021	
	ATTN: TAN JUN H	ONG	Code	: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 3680B	Veh. Inspected	SLK 1556G	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M03A5F	Excess (\$)	0.00	
	Assign From	TAN JUN HONG	Assign Date	18/05/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	BMW X1 SDRIVE 18L	c.c	1499	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	WBAHS120005F03403	Colour	BLACK	
	Odometer	120997 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/50 R18	PIRELLI	6 mm	
	L/H Front Tyre	225/50 R18	PIRELLI	6 mm	
	R/H Rear Tyre	225/50 R18	PIRELLI	6 mm	
	L/H Rear Tyre	225/50 R18	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUS	JSTAINED DAMAGES AT THE REAR N/S PORTION.			
5.	General Information				
	Accident Date	11/05/2021	Inspect Date / Time	02/06/2021 (12:25 PM)	
	Survey held at	LIAN HENG PAINTER CO.	•		
		BLK 160 SIN MING DRIVE #06-10 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM21005906/Bqce2

Inspected By

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

DECD Auto Computer OAE Liverand America

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$