

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005908/TPA3Q2**Date:** 07/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070176029
Claimant Vehicle No :	GBE580S	Insured Vehicle No :	SLL2512X
Date of Loss:	12/05/2021	Nature of Claim:	TP
		Claim No:	0300203204SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE580S		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30001197N
Reg. Date:	24/08/2015 (Man. Year: 2015)	Chassis No:	JN1SC2F24Z0857338
Colour:	Silver	Odometer:	291886 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,039.03	12,604.03	35,435.00	73.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,350.00	3,570.00	10,780.00	75.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	62,389.03	16,174.03	46,215.00	74.08
Approved Total (Overridden) (\$\$)		12,900.00		
(\$\$)	62,389.03	12,900.00	49,489.03	79.32
+ GST 7.00/7.00% (\$\$)	4,367.23	903.00	3,464.23	79.32
Nett Amount (\$\$)	66,756.26	13,803.00	52,953.26	79.32
+ Car Rental (12.0 x S\$100.00/day + 7.00% GST) (\$\$)		1,284.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		15,094.45		

INSPECTION

Date of Assignment:	18/05/2021	
Date Inspected:	19/05/2021	Inspected At: AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	12.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN MOULDING	Necessary	173.00 FL	*173.00 FL
2	1		*FRONT WIPER PANEL	Not Necessary	568.00 FL	*- FL
3	2		*FRONT WIPER ARM L+R	Not Necessary	166.00 FL	*- FL
4	2		*FRONT WIPER NOZZLE L+R	Not Necessary	76.00 FL	*- FL
5	1		*FRONT SIDE GARNISH L+R	N/S Not Necessary /O/S Deformed	420.00 FL	*210.00 FL
6	1		*FRONT CENTER PANEL	Bent	1,554.00 FL	*1,554.00 FL
7	1		*FRONT CENTER PANEL EMBLEM -CABSTAR	Necessary	36.70 FL	*36.70 FL
8	2		*FRONT SIDE PANEL L+R	Not Necessary	868.00 FL	*- FL
9	1		*FRONT GRILLE	Cut	480.00 FL	*480.00 FL
10	1		*FRONT GRILLE LOGO -NISSAN	Necessary	88.00 FL	*88.00 FL
11	2		*HEADLAMP L+R	Cracked	1,184.00 FL	*1,184.00 FL
12	2		*FRONT SIDE LAMP L+R	Not Necessary	664.00 FL	*- FL
13	1		*FRONT BUMPER	Deformed	748.00 FL	*748.00 FL
14	1		*FRONT BUMPER BRACKET	Bent	407.00 FL	*407.00 FL
15	1		*AIRCON HIGH PRESSURE HOSE	Bent	371.00 FL	*371.00 FL
16	1		*AIRCON LOW PRESSURE HOSE	Bent	319.00 FL	*319.00 FL
17	1		*AIRCON TEMPERATURE SUCTION PIPE (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*AIRCON TEMPERATURE DISCHARGE PIPE (NPA)	Not Necessary	0.00 FL	*- FL
19	1		*AIRCON BLOWER	Cracked	311.00 FL	*311.00 FL
20	1		*AIRCON BLOWER BOX	Cracked	524.00 FL	*524.00 FL
21	1		*WIPER WASHER TANK	Not Necessary	125.00 FL	*- FL
22	1		*RADIATOR TANK (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*TAILGATE	Bent	1,817.00 FL	*1,817.00 FL
24	2		*TAILGATE SIDE LOCK L+R	Bent	360.00 FL	*360.00 FL
25	3		*SET TAILGATE HINGE	Bent	504.00 FL	*504.00 FL
26	1		*END PANEL	Bent	752.00 FL	*752.00 FL
27	1		*FLOOR PANEL	Not Necessary	4,820.00 FL	*- FL
28	2		*REAR LOWER BRACKET L+R	Bent	180.00 FL	*180.00 FL
29	2		*REAR LOWER BRACKET STOPPER SET L+R	Cut	80.00 FL	*80.00 FL
30	2		*TAIL LAMP L+R	Cracked	780.00 FL	*780.00 FL
31	2		*TAIL LAMP INNER BRACKET L+R	Not Necessary	38.00 FL	*- FL
32	2		*TAIL LAMP OUTER BRACKET L+R	Bent	76.00 FL	*76.00 FL
33	1		*REAR NUMBER PLATE BRACKET	Bent	31.00 FL	*31.00 FL
34	2		*SIDE GATE L+R	Not Necessary	5,080.00 FL	*- FL
35	2		*SIDE GATE LOWER PANEL L+R	Not Necessary	3,744.00 FL	*- FL
36	1		*TOWING HOOK	Not Necessary	298.00 FL	*- FL
37	1		*SARE TYRE BRACKET	Bent	441.00 FL	*441.00 FL
38	1		*FRONT WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
39	1		*FRONT CENTER PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
40	1		*FRONT SIDE PANEL SEALANT	Not Necessary	120.00 FS	*- FS
41	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*30.00 FS
42	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
43	1		*TAILGATE STICKER -70KM/H	Necessary	80.00 FS	*30.00 FS
44	1		*TAILGATE STICKER -13 PAX	Necessary	80.00 FS	*30.00 FS
45	1		*TAILGATE SCUFF PLATE	Necessary	1,000.00 FS	*500.00 FS
46	1		*TAILGATE SCUFF PLATE RIVET	Necessary	200.00 FS	*80.00 FS
47	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
48	1		*FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS
49	1		*FLOOR PANEL SCUFF PLATE	Bent	3,000.00 FS	*700.00 FS
50	1		*FLOOR PANEL SCUFF PLATE RIVET	Necessary	200.00 FS	*80.00 FS
51	1		*REAR NUMBER PLATE	Bent	80.00 FS	*30.00 FS
52	1		*REAR CANOPY	Not Necessary	3,000.00 FS	*- FS
53	2		*SIDE GATE TOP HANDLE L+R	Not Necessary	4,000.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*SIDE GATE SCUFF PLATE L+R	Not Necessary	5,000.00 FS	*- FS
55	2		*SIDE GATE SCUFF PLATE RIVET L+R	Not Necessary	400.00 FS	*- FS
56	1		*SPARE RIM	Not Necessary	1,000.00 FS	*- FS
57	1		*SPARE TYRE	Not Necessary	600.00 FS	*- FS
58	1		*REAR CHASSIS L+R	Repair	1,223.00 FL	*- FL
59	1		*REAR CHASSIS L+R (NPA)	Repair	0.00 FL	*- FL
60	1		*REAR CHASSIS CENTER SUPPORT (LOCAL REPAIR)	Bent	1,223.00 FS	*500.00 FS
61	1		*SET REVERSE SENSOR }	Not Working	300.00 FS	*200.00 FS
62	1		*SET REVERSE SENSOR HOLDER }		300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	50,969.70	13,746.70
- List Item Discount on L Items 10.00/10.00% (S\$)	2,930.67	1,142.67
Total Parts (S\$)	48,039.03	12,604.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	3,800.00	1,400.00
2	SPRAY PAINT ON AFFECTED AREAS	New	2,400.00	1,000.00
3	TO RNR DASHBOARD	New	800.00	180.00
4	TO RNR AIRCON CONDENSOR AND TOP UP GAS	New	300.00	100.00
5	TO RNR RADIATOR	New	250.00	0.00
6	TO RNR AIRCON BLOWER	New	300.00	100.00
7	TO RNR REAR CANOPY	New	1,200.00	0.00
8	TO RNR REAR SIDE GATE TOP HANDLE	New	1,200.00	0.00
9	TO RNR REAR SCUFF PLATES	New	1,500.00	100.00
10	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
11	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
12	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
13	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
14	TO PERFORM RUST PROOFING	New	600.00	40.00
15	TO RNR REAR CHASSIS	New	1,200.00	500.00
Gross Labour Cost (\$)			14,350.00	3,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >