



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
OH SOON SENG BLK 671B JURONG WEST STREET 65 #05-114 SINGAPORE 642671 Contact No Mobile: 94503319	Cust No/Name /OH SOON SENG Reg No/Reg Date SKV7558R / 21/05/201 Date In/Mileage / 0 Chassis No KNAD6811VK6251898 Engine No G3LCJP150634 Make/Model KIA/STONIC 1.0 A SX BIT W GREEN TRI Colour/Trim GAB GREEN ROOF W PL/ BGH MEDIUM GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	18/05/2021/ 10:10	BLC	442 / CocoLu	33460			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								800.00
RENEW FRT BUMPER, BONNET 2 X 490								700.00
E PNT98000								80.00
SPRAY PAINT FOR FRT BUMPER, BONNET 350 X 2								50.00
M SUNDRY								30.00
APPLY RESEAL FRT NO. PLATE FROM LTA - MIS								120.00
M SUNDRY								20.00
FRT NUMBER PLATE WITH FRAME / BR								
A 90000001								
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
Sundry								
M COVER-FR BUMPER UPR / BR					1.00	476.00	00.00	476.00
M COVER-FR BUMPER, LWR / CUT (centre) lower					1.00	367.00	00.00	367.00
M GRILLE-FRONT BUMPER / CUT (Side)					1.00	96.00	00.00	96.00
M SKID PLATE-FR BUMPER / CUT					1.00	55.00	00.00	55.00
M GRILLE ASSY-RADIATOR					1.00	324.00	00.00	324.00
M STRIP-FR BUMPER X NM					1.00	27.00	00.00	27.00
M COVER-RADIATOR GRILLE UPR ? / BR					1.00	46.00	00.00	46.00
M MOULDING-FRONT BUMPER A/INTAKE ? / BR (Centre)					1.00	61.00	00.00	61.00
M ABSORBER-FRONT BUMPER ENERGY / BR					1.00	98.00	00.00	98.00
M STIFFNER-FR BPR LWR ? X NM					1.00	123.00	00.00	123.00
M BRACKET-FR BUMPER SIDE, RH ? X NM					1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE, LH ? X NM					1.00	13.00	00.00	13.00
M AIR DUCT-FR BUMPER, RH ? X NM					1.00	38.00	00.00	38.00
M AIR DUCT-FR BUMPER, LH ? X NM					1.00	38.00	00.00	38.00
M LIP ASSY-FRONT BUMPER ? X NM					1.00	32.00	00.00	32.00
M LAMP ASSY-HEAD, RH / CUT					1.00	1845.00	00.00	1845.00
M PANEL ASSY-HOOD / ON					1.00	904.00	00.00	904.00

Estimate

Steve CLKK)
18/5/21, 11.42am
00-AL AL

Estimate

Steve CLKK)

18/5/21, 11.44am

00-AL AL

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Exrrrr - ?

P/P

By BCL Sy

4 days

7% GST on 6,356.00
Total Payable 6,800.92

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.