

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21005911/KVF3E2

Date: 07/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLH7029M

Insured Vehicle No : SMY6972U

Date of Loss: 11/05/2021

Nature of Claim: TP

Claim No: 9799089181SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH7029M**

Make & Model: HONDA JAZZ, 1.5 (A)

Engine No: L15B31190555

Reg. Date: 15/11/2016 (Man. Year: 2016)

Chassis No: JHMGK5850HX200807

Colour: Metallic Blue

Odometer: 112116 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size: 185/55 R16

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,956.21	4,626.46	4,329.75	48.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,630.00	1,850.00	53.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,436.21	6,256.46	6,179.75	49.69
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	12,436.21	5,000.00	7,436.21	59.79
+ GST 7.00/7.00% (S\$)	870.53	350.00	520.53	59.79
Nett Amount (S\$)	13,306.74	5,350.00	7,956.74	59.79

INSPECTION

Date of Assignment: 18/05/2021

Date Inspected: 18/05/2021 Inspected At:

S Three Automotive Recovery Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C
Singapore 575643

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	632.50 FL	*523.50 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	56.00 FL	*56.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	56.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	144.52 FL	*144.52 FL
5	1		*FRONT BUMPER LOWER GRILLE CENTRE	Cracked	116.92 FL	*116.92 FL
6	1		*FRONT BUMPER LOWER COVER	Serviceable	302.00 FL	*- FL
7	1		*FRONT BUMPER SIDE GRILLE LH	Serviceable	101.52 FL	*- FL
8	1		*FRONT BUMPER SIDE GRILLE RH	Serviceable	101.52 FL	*- FL
9	1		*FRONT FOG LAMP LH	Mtg Cracked	380.60 FL	*290.80 FL
10	1		*FRONT FOG LAMP COVER LH	Dented	166.00 FL	*166.00 FL
11	1		*FRONT GRILLE	Scratched	116.92 FL	*116.92 FL
12	1		*FRONT GRILLE LOGO	Necessary	23.42 FL	*23.42 FL
13	1		*FRONT HORN ASSY	Serviceable	186.00 FL	*- FL
14	1		*FRONT BONNET	Buckled	1,800.00 FL	*633.60 FL
15	1		*FRONT BONNET GRILLE	Serviceable	160.00 FL	*- FL
16	1		*FRONT BONNET HINGE LH	Repair	48.90 FL	*- FL
17	1		*FRONT BONNET HINGE RH	Repair	48.90 FL	*- FL
18	1		*FRONT BONNET LOCK	Distorted	35.02 FL	*35.02 FL
19	1		*FRONT BONNET RUBBER	Serviceable	55.90 FL	*- FL
20	1		*FRONT HEADLAMP LH	Mtg Cracked	744.60 FL	*744.60 FL
21	1		*FRONT HEADLAMP RH	Mtg Cracked	744.60 FL	*744.60 FL
22	1		*FRONT HEADLAMP LOWER BRACKET LH	Distorted	25.03 FL	*25.03 FL
23	1		*FRONT HEADLAMP LOWER BRACKET RH	Distorted	25.03 FL	*25.03 FL
24	1		*FRONT FENDER LH	Repair	475.60 FL	*- FL
25	1		*FRONT FENDER RH	Repair	475.60 FL	*- FL
26	1		*FRONT FENDER INNER SHIELD LH	Serviceable	98.10 FL	*- FL
27	1		*FRONT FENDER INNER SHIELD RH	Serviceable	98.10 FL	*- FL
28	1		*FRONT SUPPORT PANEL ASSY	Bent	360.32 FL	*360.32 FL
29	1		*FRONT SUPPORT PANEL GARNISH	Serviceable	106.50 FL	*- FL
30	1		*RADIATOR ASSY	Punctured	89.80 FL	*89.80 FL
31	1		*AIR CON CONDENSOR	Bent	553.62 FL	*553.62 FL
32	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
33	1		*FRONT BUMPER LOWER SPOILER	No such part	680.00 FS	*- FS
34	1		*FRONT BUMPER LOWER SPOILER SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	50.00 FS	*- FS
36	1		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	50.00 FS	*- FS
37	1		*FRONT NO. PLATE	Bent	50.00 FS	*45.00 FS
38	1		*FRONT SUPPORT PANEL GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*50.00 FS
40	1		*AIR CON SIDE GARNISH LH	Cracked	128.80 FL	*82.00 FL
41	1		*AIR CON PIPE-CONDENSOR TO COOLING COIL	Dented	93.42 FL	*93.42 FL
42	1		*AIR COOLER BOX	Cracked	428.00 FL	*132.00 FL
43	1		*TEMPERATURE SENSOR	Cracked	380.00 FL	*258.10 FL
44	1		*FRONT NO PLATE GARNISH	Dented	80.00 FL	*80.00 FL
45	1		*FOG LAMP LED LIGHT BULB LH	Mtg Cracked	368.00 FL	*281.60 FL
46	1		*RADIATOR COOLANT	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,917.76	5,741.82
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,961.55	1,115.36
Total Parts (\$\$)	8,956.21	4,626.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	New	1,500.00	600.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,500.00	800.00
3	CHECK & REPAIR WIRING SYSTEM	New	120.00	20.00
4	R&R RADIATOR SYSTEM	New	120.00	50.00
5	R&R AIRCON CONDENSOR & CHARGE UP GAS	New	120.00	100.00
6	RESPRAY TUFF KOTE ON AFFECTED AREA	New	120.00	60.00
Gross Labour Cost (\$\$)			3,480.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >