



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2103946

INV Date 07/06/2021

Reference CC4/FCI21005912/Uea3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 4865X
Insured Veh. SKW 9355R
Claim No. D21001517MFZH/1
Policy No. D-21097484MFZH
Accident Date 12/05/2021
Inspection Date 18/05/2021

Description	Total
Survey Inspection	263.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	263.00
GST (7%)	18.41
Grand Total	281.41

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI21005912/Uea3q2 Date: 07/06/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKW 9355R	Veh. Inspected	SLF 4865X
Policy No.	D-21097484MFZH	Coverage (\$)	0.00
Claim No.	D21001517MFZH/1	Excess (\$)	0.00
Assign From	VIC	Assign Date	18/05/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI (A)	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SJNFEAJ11U1714762	Colour	RED
Odometer	48121 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	NEXEN	6 mm
L/H Front Tyre	215/60 R17	NEXEN	6 mm
R/H Rear Tyre	215/60 R17	GOODYEAR	6 mm
L/H Rear Tyre	215/60 R17	GOODYEAR	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	12/05/2021	Inspection Date	18/05/2021
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 4865X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	DENTED / DEFORMED	876.40	876.40
1	REAR BUMPER FOAM (N)	NOT NECESSARY	155.80	-
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	691.50	-
2	REAR BUMPER SIDE RETAINER RH/LH @\$42.00 (N)	NOT NECESSARY	84.00	-
1	REAR TAILGATE EMBLEM 'NISSAN' (N)	NOT NECESSARY	65.00	-
1	REAR TAILGATE EMBLEM 'QASHQAI' (N)	NECESSARY	94.40	94.40
	LESS 10% DISCOUNT		-196.71	-97.08
			1,770.39	873.72
SPECIAL NETT ITEMS				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
			315.00	235.00
LABOUR				
	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		400.00	280.00
	TO SPRAY PAINTING ON ACCIDENT PARTS.		500.00	400.00
	TO REMOVE REPLACE REVERSE SENSOR .		80.00	50.00
			980.00	730.00
GRAND TOTAL			3,065.39	1,838.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CC4/FCI21005912/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 4865X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R










LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 4865X

RE-INSPECTION

