



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104107

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 11/06/2021
Reference CC4/FCI21005914/Ura3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SGN 7890U
Insured Veh. GBJ 913P
Claim No. D21001519MFCV
Policy No. D-21097015MFCV
Accident Date 13/05/2021
Inspection Date 31/05/2021

Description	Total
Survey Inspection	249.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	249.00
GST (7%)	17.43
Grand Total	266.43

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21005914/Ura3q2	
			Date: 11/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 913P	Veh. Inspected	SGN 7890U
	Policy No.	D-21097015MFCV	Coverage (\$)	0.00
	Claim No.	D21001519MFCV	Excess (\$)	0.00
	Assign From	CHRIS LIM	Assign Date	18/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	MR053HY4204209567	Colour	SILVER
	Odometer	164622 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R14	MICHELIN	6 mm
	L/H Front Tyre	185/60 R14	MICHELIN	6 mm
	R/H Rear Tyre	185/60 R14	MICHELIN	6 mm
	L/H Rear Tyre	185/60 R14	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/05/2021	Inspection Date	31/05/2021
	Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 7890U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	546.30	546.30
2	FRONT BUMPER SIDE HOLDER @\$14.70	O/S CRACKED	29.40	14.70
10	FRONT BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	FRONT BUMPER UNDERCOVER	NOT NECESSARY	79.80	-
10	FRONT BUMPER UNDERCOVER CLIPS @\$5.50	NOT NECESSARY	55.00	-
1	FRONT BUMPER FOGLAMP COVER -RH	MISSING	79.80	79.80
1	FRONT GRILLE ASSY W/TOYOTA LOGO	NECESSARY	220.00	220.00
1	FRONT HEADLAMP -RH	CRACKED	233.80	233.80
1	FRONT FENDER -RH	BENT / BUCKLED	191.50	191.50
1	FRONT FENDER COWLING -RH	DEFORMED / TORN	101.50	101.50
10	FRONT FENDER COWLING CLIPS -RH @\$5.50	NECESSARY	55.00	55.00
1	WASHER TANK	DEFORMED	61.00	61.00
	LESS 25% DISCOUNT		-427.03	-389.65
			1,281.07	1,168.95
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS.		500.00	400.00
	TO RESPRAY PAINT ON AFFECTED PORTIONS.		700.00	500.00
	TO CHECK WIRING .		50.00	20.00
			1,250.00	920.00
	GRAND TOTAL		2,531.07	2,088.95
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00

Report Ref No. CC4/FCI21005914/Ura3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGN 7890U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGN 7890U

RE-INSPECTION

