

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005916/T1PA3Q2
Date: 15/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900147885
Claimant Vehicle No :	SLD5355E	Insured Vehicle No :	SMN4783U
Date of Loss:	11/05/2021	Nature of Claim:	TP
		Claim No:	5917364177SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD5355E	Engine No:	CYV110866
Make & Model:	VOLKSWAGEN GOLF, 1.2 TSI (A)	Chassis No:	WVWZZZAUZGW234066
Reg. Date:	21/06/2016 (Man. Year: 2016)	Odometer:	126885 km
Colour:	Black		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,584.12	8,065.43	15,518.69	65.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,250.00	1,640.00	5,610.00	77.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,834.12	9,705.43	21,128.69	68.52
Approved Total (Overridden) (S\$)		7,800.00		

(S\$)	30,834.12	7,800.00	23,034.12	74.70
+ GST 7.00/7.00% (S\$)	2,158.39	546.00	1,612.39	74.70
Nett Amount (S\$)	32,992.51	8,346.00	24,646.51	74.70
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,102.45		
Global Sum Settlement (S\$)		9,000.00		

INSPECTION

Date of Assignment: 18/05/2021

Date Inspected: 19/05/2021

Estimated Period of Repair: 6.0 days

Inspected At:

AP Automotive Services Pte Ltd
 56 Loyang Way, #04-04 Loyang Enterprise Building
 Singapore 508775

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,840.91 FL	*1,840.91 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	189.45 FL	*189.45 FL
3	2		*TAILGATE LAMP L+R	Cracked	995.20 FL	*995.20 FL
4	1		*TAILGATE LOCK	Bent	425.55 FL	*425.55 FL
5	1		*TAILGATE LOCK CATCH	Not Necessary	95.21 FL	*- FL
6	1		*TAILGATE INNER TRIM	Cracked	521.56 FL	*521.56 FL
7	2		*SET TAILGATE HINGE	Not Necessary	190.40 FL	*- FL
8	2		*SET TAILGATE DAMPER	Not Necessary	275.60 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Cut	339.48 FL	*339.48 FL
10	2		*TAIL LAMP L+R	Not Necessary	1,087.64 FL	*- FL
11	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	178.66 FL	*- FL
12	1		*REAR BUMPER	Deformed	1,510.75 FL	*1,510.75 FL
13	2		*REAR BUMPER NUMBER PLATE L+R	Not Necessary	130.80 FL	*- FL
14	2		*REAR BUMPER REFLECTOR L+R	Cracked	204.60 FL	*204.60 FL
15	1		*REAR BUMPER LOWER	Cut	410.32 FL	*410.32 FL
16	2		*REAR BUMPER RETAINER L+R	Deformed	248.50 FL	*248.50 FL
17	1		*REAR BUMPER CENTER BRACKET	Deformed	256.80 FL	*256.80 FL
18	1		*REAR BUMPER REINFORCEMENT BAR	Bent	697.75 FL	*697.75 FL
19	2		*REAR BUMPER BRACKET L+R	Not Necessary	173.80 FL	*- FL
20	1		*REAR BUMPER SPONGE	Not Necessary	123.45 FL	*- FL
21	1		*REAR FENDER L+R (NPA)	Repair	0.00 FL	*- FL
22	2		*REAR FENDER INNER TRIM L+R	Not Necessary	858.70 FL	*- FL
23	2		*REAR FENDER COWLING L+R	Torn	424.94 FL	*424.94 FL
24	1		*END PANEL	Repair	859.65 FL	*- FL
25	1		*END PANEL TOP GARNISH	Deformed	345.78 FL	*345.78 FL
26	1		*REAR SMART LOCK ANTENNA	Not Necessary	279.50 FL	*- FL
27	1		*REAR SMART LOCK ANTENNA WIRE HARNESS	Not Necessary	638.20 FL	*- FL
28	1		*SPAREWHEEL PANEL	Not Necessary	1,234.80 FL	*- FL
29	1		*SPAREWHEEL PANEL TOP BOARD	Not Necessary	501.62 FL	*- FL
30	1		*EXHAUST PIPE (NPA)	Not Necessary	0.00 FL	*- FL
31	2		*SET EXHAUST MOUNTING	Not Necessary	144.40 FL	*- FL
32	1		*EXHAUST HEAT SHIELD	Not Necessary	231.67 FL	*- FL
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
34	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*SET TAIL LAMP CLIPS	Necessary	40.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
36	1		*TAIL LAMP PANEL SEALANT	Not Necessary	100.00 FS	*- FS	
37	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS	
38	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS	
39	1		*REAR NUMBER PLATE	Cut	100.00 FS	*45.00 FS	
40	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS	
41	1		*SET REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS	
42	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS	
43	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS	
44	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS	
45	1		*EXHAUST PIPE	Not Necessary	8,000.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	25,125.69	8,906.59
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,541.57	841.16
					Total Parts (\$\$)	23,584.12	8,065.43

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT ON AFFECTED AREAS	New	2,200.00	700.00
2	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	700.00
3	TO RNR REAR EXHAUST	New	250.00	0.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION }	New	150.00	30.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
6	TO UNLOAD AND UPHOLSTERY REAR BOOT	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	30.00
8	TO RNR FUEL TANK	New	250.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	800.00	0.00
10	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
12	TO PERFORM RUST PROOFING	New	400.00	30.00
Gross Labour Cost (\$\$)			7,250.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >