

ASS. REC. BY:

Tough

REF:

CC4/191621005916/T1P93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

950K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR. Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLO5355E Yr Regn: 2016 JuneType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime mover /

Truck / Trailer or _____

Make: Volkswagen Golf 1.2 1197Colour: Black A/C: Insure Std / NI / NASp. Reading: 126885 T/Radio: Insure Std / NI / NA

Eng/No: _____

C/No: WVW 222 1976 W 234066Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / SUMI

TOYO / YOKO or

PIR

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I.

19/5/21 0359pm

Survey held at

AP Info

Des. of Damages: Front / Rear / O/S / N/S / U/C Foottop or

The U/C / Chassis frame / Body Structure cracked due to collision

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Formet: _____

Lump Sum / L.B.I. / P

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Survey Fee

Transportation

) \$-R- \$

) Phone

) Other

Total

Estimation

Date
Vehicle SLD 5355 E
Make/Model VOLKSWAGEN GOLF
Chassis No. VVVZZZAUZGW234066

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAILGATE	1	\$ 1,840.91	\$ <i>bt</i> 1,840.91
2	TAILGATE WINDSCREEN MOULDING	1	\$ 189.45	\$ <i>nee</i> 189.45
3	TAILGATE LAMP L+R	2	\$ 497.60	\$ <i>x cr</i> 995.20
4	TAILGATE LOCK	1	\$ 425.55	\$ <i>bt</i> 425.55
5	TAILGATE LOCK CATCH	1	\$ 95.21	\$ <i>x</i> 95.21
6	TAILGATE INNER TRIM	1	\$ 521.56	\$ <i>awa</i> 521.56
7	TAILGATE HINGE SET	2	\$ 95.20	\$ <i>x</i> 190.40
8	TAILGATE DAMPER SET	2	\$ 137.80	\$ <i>x</i> 275.60
9	TAILGATE WEATHERSTRIP	1	\$ 339.48	\$ <i>int</i> 339.48
10	TAIL LAMP L+R	2	\$ 543.82	\$ <i>x</i> 1,087.64
11	TAIL LAMP LOWER BRACKET L+R	2	\$ 89.33	\$ <i>x</i> 178.66
12	REAR BUMPER	1	\$ 1,510.75	\$ <i>de</i> 1,510.75
13	REAR BUMPER NUMBER PLATE LAMP L+R	2	\$ 65.40	\$ <i>x</i> 130.80
14	REAR BUMPER REFLECTOR L+R	2	\$ 102.30	\$ <i>ora</i> 204.60
15	REAR BUMPER LOWER	1	\$ 410.32	\$ <i>art</i> 410.32
16	REAR BUMPER RETAINER L+R	2	\$ 124.25	\$ <i>de</i> 248.50
17	REAR BUMPER CENTER BRACKET	1	\$ 256.80	\$ <i>de</i> 256.80
18	REAR BUMPER REINFORCEMENT BAR	1	\$ 697.75	\$ <i>bt</i> 697.75
19	REAR BUMPER BRACKET L+R	2	\$ 86.90	\$ <i>x</i> 173.80
20	REAR BUMPER SPONGE	1	\$ 123.45	\$ <i>x</i> 123.45
21	REAR FENDER L+R	1		REPAIR
22	REAR FENDER INNER TRIM L+R	2	\$ 429.35	\$ <i>x</i> 858.70
23	REAR FENDER COWLING L+R	2	\$ 212.47	\$ <i>tr</i> 424.94
24	END PANEL	1	\$ 859.65	\$ <i>Ry</i> 859.65
25	END PANEL TOP GARNISH	1	\$ 345.78	\$ <i>de</i> 345.78
26	REAR SMART LOCK ANTENNA	1	\$ 279.50	\$ <i>x</i> 279.50
27	REAR SMART LOCK ANTENNA WIRE HARNESS	1	\$ 638.20	\$ <i>x</i> 638.20
28	SPAREWHEEL PANEL	1	\$ 1,234.80	\$ <i>x</i> 1,234.80
29	SPAREWHEEL PANEL TOP BOARD	1	\$ 501.62	\$ <i>x</i> 501.62
30	EXHAUST PIPE	1		\$ <i>x</i> -
31	EXHAUST MOUNTING SET	2	\$ 72.20	\$ <i>x</i> 144.40
32	EXHAUST HEAT SHIELD	1	\$ 231.67	\$ <i>x</i> 231.67
			Total	\$ 15,415.69
			Less 10%	\$ 1,541.57
			Total	\$ 13,874.12

	S/Nett Items				
1	TAILGATE WINDSCREEN SEALANT	1	120	\$ <i>120.00</i>	120.00
2	TAILGATE INNER TRIM CLIPS SET	1	100	\$ <i>X</i>	100.00
3	TAIL LAMP CLIPS SET	1	40	\$ <i>20.00</i>	40.00
4	TAIL LAMP PANEL SEALANT	1	100	\$ <i>X</i>	100.00
5	REAR BUMPER CLIPS SET	1	100	\$ <i>30.00</i>	100.00
6	REAR BUMPER REVERSE SENSOR SET	1	300	\$ <i>200.00</i>	300.00
7	REAR NUMBER PLATE	1	100	\$ <i>45.00</i>	100.00
8	REAR FENDER INNER TRIM CLIPS SET	1	100	\$ <i>X</i>	100.00
9	REAR FENDER COWLING CLIPS SET	1	100	\$ <i>20.00</i>	100.00
10	END PANEL SEALANT	1	250	\$ <i>40</i>	250.00
11	END PANEL TOP GARNISH CLIPS SET	1	100	\$ <i>20.00</i>	100.00
12	SPAREWHEEL PANEL SEALANT	1	300	\$ <i>X</i>	300.00
13	EXHAUST PIPE	1	8000	\$ <i>X</i>	8,000.00
			Total	\$	1,710.00

	LABOUR				
1	SPRAY PAINT ON AFFECTED AREAS	1	2200	\$ <i>700</i>	2,200.00
2	PANEL BEATING ON AFFECTED AREAS	1	2000	\$ <i>700</i>	2,000.00
3	TO RNR REAR EXHAUST	1	250	\$ <i>X</i>	250.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ <i>130</i>	150.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$ <i>130</i>	150.00
6	TO UNLOAD AND UPHOISTERY REAR BOOT	1	400	\$ <i>60</i>	400.00
7	TO CHECK WATER LEAK	1	150	\$ <i>30</i>	150.00
8	TO RNR FUEL TANK	1	250	\$ <i>X</i>	250.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	800	\$ <i>X</i>	800.00
10	TO RNR REAR TAILGATE MECHANISM	1	350	\$ <i>60</i>	350.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ <i>30</i>	150.00
12	TO PERFORM RUST PROOFING	1	400	\$ <i>30</i>	400.00
			Total		

Parts Replacement Amount	\$	15,584.12
Total Amount For Labour	\$	7,250.00
Total Amount	\$	22,834.12

Tanpin 97495749
WP' 17/5/21 0330pm
05 days
1/6 Reming after repair
Tanpin @ Kuantan

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: