

AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
ROC: 202022890H
BLOCK 9006
TAMPINES STREET 93 #01-202
SINGAPORE 528840
TEL: 6784 4465
FAX: 6787 4886

Estimation

Date
Vehicle SLD 5355 E
Make/Model VOLKSWAGEN GOLF
Chassis No. WVWZZZAUZGW234066

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAILGATE	1	\$ 1,840.91	\$ <i>bt</i> 1,840.91
2	TAILGATE WINDSCREEN MOULDING	1	\$ 189.45	\$ <i>ne</i> 189.45
3	TAILGATE LAMP L+R	2	\$ 497.60	\$ <i>x on</i> 995.20
4	TAILGATE LOCK	1	\$ 425.55	\$ <i>bt</i> 425.55
5	TAILGATE LOCK CATCH	1	\$ 95.21	\$ <i>x ny</i> 95.21
6	TAILGATE INNER TRIM	1	\$ 521.56	\$ <i>an</i> 521.56
7	TAILGATE HINGE SET	2	\$ 95.20	\$ <i>x ny</i> 190.40
8	TAILGATE DAMPER SET	2	\$ 137.80	\$ <i>x ny</i> 275.60
9	TAILGATE WEATHERSTRIP	1	\$ 339.48	\$ <i>cut</i> 339.48
10	TAIL LAMP L+R	2	\$ 543.82	\$ <i>x ny</i> 1,087.64
11	TAIL LAMP LOWER BRACKET L+R	2	\$ 89.33	\$ <i>x ny</i> 178.66
12	REAR BUMPER	1	\$ 1,510.75	\$ <i>de</i> 1,510.75
13	REAR BUMPER NUMBER PLATE LAMP L+R	2	\$ 65.40	\$ <i>x ny</i> 130.80
14	REAR BUMPER REFLECTOR L+R	2	\$ 102.30	\$ <i>cr</i> 204.60
15	REAR BUMPER LOWER	1	\$ 410.32	\$ <i>cut</i> 410.32
16	REAR BUMPER RETAINER L+R	2	\$ 124.25	\$ <i>de</i> 248.50
17	REAR BUMPER CENTER BRACKET	1	\$ 256.80	\$ <i>de</i> 256.80
18	REAR BUMPER REINFORCEMENT BAR	1	\$ 697.75	\$ <i>bt</i> 697.75
19	REAR BUMPER BRACKET L+R	2	\$ 86.90	\$ <i>x ny</i> 173.80
20	REAR BUMPER SPONGE	1	\$ 123.45	\$ <i>x ny</i> 123.45
21	REAR FENDER L+R	1		REPAIR
22	REAR FENDER INNER TRIM L+R	2	\$ 429.35	\$ <i>x ny</i> 858.70
23	REAR FENDER COWLING L+R	2	\$ 212.47	\$ <i>tn</i> 424.94
24	END PANEL	1	\$ 859.65	\$ <i>Ry</i> 859.65
25	END PANEL TOP GARNISH	1	\$ 345.78	\$ <i>de</i> 345.78
26	REAR SMART LOCK ANTENNA	1	\$ 279.50	\$ <i>x</i> 279.50
27	REAR SMART LOCK ANTENNA WIRE HARNESS	1	\$ 638.20	\$ <i>x</i> 638.20
28	SPAREWHEEL PANEL	1	\$ 1,234.80	\$ <i>x</i> 1,234.80
29	SPAREWHEEL PANEL TOP BOARD	1	\$ 501.62	\$ <i>x</i> 501.62
30	EXHAUST PIPE	1		\$ <i>x</i> -
31	EXHAUST MOUNTING SET	2	\$ 72.20	\$ <i>x</i> 144.40
32	EXHAUST HEAT SHIELD	1	\$ 231.67	\$ <i>x</i> 231.67
			Total	\$ 15,415.69
			Less 10%	\$ 1,541.57
			Total	\$ 13,874.12

8410.68
7569.61

S/Nett Items				
1	TAILGATE WINDSCREEN SEALANT	1	120	\$ nec 120.00
2	TAILGATE INNER TRIM CLIPS SET	1	100	\$ X n 100.00
3	TAIL LAMP CLIPS SET	1	40	\$ 20 nec 40.00
4	TAIL LAMP PANEL SEALANT	1	100	\$ X n 100.00
5	REAR BUMPER CLIPS SET	1	100	\$ 30 nec 100.00
6	REAR BUMPER REVERSE SENSOR SET	1	300	\$ 200 nec 300.00
7	REAR NUMBER PLATE	1	100	\$ 45 nec 100.00
8	REAR FENDER INNER TRIM CLIPS SET	1	100	\$ X n 100.00
9	REAR FENDER COWLING CLIPS SET	1	100	\$ 20 nec 100.00
10	END PANEL SEALANT	1	250	\$ 40 nec 250.00
11	END PANEL TOP GARNISH CLIPS SET	1	100	\$ 20 nec 100.00
12	SPAREWHEEL PANEL SEALANT	1	300	\$ X n 300.00
13	EXHAUST PIPE	1	8000	\$ X n 8,000.00
			Total	\$ 495 1,710.00

LABOUR				
1	SPRAY PAINT ON AFFECTED AREAS	1	2200	\$ 700 2,200.00
2	PANEL BEATING ON AFFECTED AREAS	1	2000	\$ 700 2,000.00
3	TO RNR REAR EXHAUST	1	250	\$ X n 250.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ 330 150.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$ 330 150.00
6	TO UNLOAD AND UPHOISTERY REAR BOOT	1	400	\$ 60 400.00
7	TO CHECK WATER LEAK	1	150	\$ 30 150.00
8	TO RNR FUEL TANK	1	250	\$ X n 250.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	800	\$ X n 800.00
10	TO RNR REAR TAILGATE MECHANISM	1	350	\$ 60 350.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 30 150.00
12	TO PERFORM RUST PROOFING	1	400	\$ 30 400.00
			Total	1640

Parts Replacement Amount	\$ 15,584.12
Total Amount For Labour	\$ 7,250.00
Total Amount	\$ 22,834.12

Taufik 97495749
 - WP' 11/5/21 0330pm
 65 days
 1/2 Remy after repair
 further @ Khandawar.

7569.61
 495
 1640

9704.61 11/5/21 97800
 # 6 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: