

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005922/T1QCQ2**Date:** 21/04/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00056482002

Claimant Vehicle No : GBF356T **Insured Vehicle No :** SLX9149C

Date of Loss: 12/05/2021 Nature of Claim: TP Claim No: SNM21D202783/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF356T**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (M) Engine No: 1KD2602965

Reg. Date: 01/06/2016 (Man. Year: 2016) Chassis No: KDY2318024208

Colour: Silver Odometer: 154194 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 145 R15 Rear Tyre Size: 155 R13 (D)

Front Left Side: LINAM 6 mm Rear Left Side: LINAM 6/6 mm

Front Right Side: LINAM 6 mm Rear Right Side: LINAM 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,205.55	2,272.07	3,933.48	63.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	1,520.00	4,030.00	72.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,755.55	3,792.07	7,963.48	67.74
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	11,755.55	3,000.00	8,755.55	74.48
+ GST 7.00/7.00% (S\$)	822.89	210.00	612.89	74.48
Nett Amount (S\$)	12,578.44	3,210.00	9,368.44	74.48

INSPECTION

Date of Assignment: 21/05/2021

Date Inspected: 19/05/2021 Inspected At: 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING

Estimated Period of Repair: 6.0 days Repairer: AP Automotive Services Pte Ltd (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Apr 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF356T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,116.00 FL	*1,116.00 FL
2	1		*TAILGATE STICKER -DYNA	Necessary	91.00 FL	*45.50 FL
3	2		*TAILGATE SIDE LOCK L+R	Repair	612.00 FL	*- FL
4	4		*SET TAILGATE HINGE	Bent	524.00 FL	*304.80 FL
5	2		*SIDE GATE L+R (NPA)	Not Necessary	0.00 FL	*- FL
6	12		*SIDE GATE HINGES SET L+R	Not Necessary	1,572.00 FL	*- FL
7	1		*END PANEL	Repair	479.00 FL	*- FL
8	2		*END PANEL REFLECTOR L+R	Cracked	172.00 FL	*172.00 FL
9	1		*FLOOR PANEL (NPA)	Not Necessary	0.00 FL	*- FL
10	2		*REAR LOWER BRACKET L+R	Repair	396.00 FL	*- FL
11	4		*REAR LOWER BRACKET STOPPER SET L+R	Not Necessary	236.00 FL	*- FL
12	1		*REAR NUMBER PLATE BRACKET	Bent	162.00 FL	*123.86 FL
13	2		*TAIL LAMP L+R	Cracked	446.00 FL	*446.00 FL
14	2		*TAIL LAMP BRACKET L+R	Bent	314.00 FL	*238.60 FL
15	2		*TAIL LAMP BRACKET REFLECTOR L+R	Cut	136.00 FL	*136.00 FL
16	1		*SPARE TYRE BRACKET (NPA)	Not Necessary	0.00 FL	*- FL
17	1		*REAR EXHAUST PIPE	Not Necessary	520.00 FL	*- FL
18	2		*REAR EXHAUST MOUNTING L+R	Not Necessary	191.40 FL	*- FL
19	2		*REAR CHASSIS L+R (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*REAR CHASSIS CENTER SUPPORT (NPA)	Not Necessary	0.00 FL	*- FL
21	1		*TAILGATE STICKER -70KM/H	Necessary	80.00 FS	*30.00 FS
22	1		*TAILGATE STICKER -6PAX	Necessary	80.00 FS	*30.00 FS
23	1		*TAILGATE STICKER -WEIGHT	Necessary	80.00 FS	*30.00 FS
24	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Bent	120.00 FS	*45.00 FS
26	1		*REAR STEP BRACKET	Bent	500.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,947.40	2,917.76
- List Item Discount on L Items 25.00/25.00% (\$)	1,741.85	645.69
Total Parts (\$)	6,205.55	2,272.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	700.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	700.00
3	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
4	TO RNR TAILGATE MECHANISM	New	800.00	60.00
5	TO RNR SIDE GATE TOP HANDLE	New	800.00	0.00
6	TO RNR REAR EXHAUST	New	400.00	0.00
7	TO PERFORM RUST PROOFING	New	600.00	30.00
Gross Labour Cost (\$\$)			5,550.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >