

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21005924/UPS3Q2  
**Date:** 12/07/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070011388   |
| <b>Claimant Vehicle No :</b> | SLS4260Y                             | <b>Insured Vehicle No :</b> | SKM4001Y     |
| Date of Loss:                | 15/05/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1006490684SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLS4260Y</b>                   | Engine No:  | 10977525N55B30A   |
| Make & Model:               | BMW 535I, 3.0 GT (A)              | Chassis No: | WBAFR72090C580012 |
| Reg. Date:                  | 08/10/2010 (Man. Year: 2010)      | Odometer:   | 102469 km         |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 2979 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 255/35Z R20   | Rear Tyre Size:  | 285/30Z R20   |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 25,482.09         | 14,346.63         | 11,135.46         | 43.70         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 4,130.00          | 2,330.00          | 1,800.00          | 43.58         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>29,612.09</b>  | <b>16,676.63</b>  | <b>12,935.46</b>  | <b>43.68</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>13,000.00</b>  |                   |               |

|                                                  |                  |                  |                  |              |
|--------------------------------------------------|------------------|------------------|------------------|--------------|
| (S\$)                                            | 29,612.09        | 13,000.00        | 16,612.09        | 56.10        |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 2,072.85         | 910.00           | 1,162.85         | 56.10        |
| <b>Nett Amount (S\$)</b>                         | <b>31,684.94</b> | <b>13,910.00</b> | <b>17,774.94</b> | <b>56.10</b> |
| <b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b> |                  | 600.00           |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                    |                  | 2.00             |                  |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>14,512.00</b> |                  |              |
| <b>Global Sum Settlement (S\$)</b>               |                  | <b>14,500.00</b> |                  |              |

INSPECTION

Date of Assignment: 18/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 6.0 days

 Inspected At: Fastech Auto Pte Ltd (HQ)  
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
 Singapore 417883
**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                | Condition          | Repairer's | Amount       |
|-----|-----|----------|--------------------------------------------|--------------------|------------|--------------|
| 1   | 1   |          | *FRONT DOOR N/S                            | Badly Dented       | 3,250.00 F | *2,035.20 FL |
| 2   | 1   |          | *FRONT DOOR GLASS OUTER MOULDING N/S       | Necessary          | 315.00 F   | *215.35 FL   |
| 3   | 1   |          | *FRONT DOOR GLASS FRAME GARNISH N/S        | Necessary          | 118.00 F   | *88.00 FL    |
| 4   | 1   |          | *FRONT DOOR GLASS REGULATOR & MOTOR N/S    | Bent / Jammed      | 945.15 F   | *485.20 FL   |
| 5   | 1   |          | *FRONT DOOR INNER LOCK N/S                 | Shorted            | 655.22 F   | *655.22 FL   |
| 6   | 1   |          | *FRONT DOOR INNER TRIM BOARD N/S           | Deformed / Cracked | 1,988.20 F | *1,949.70 FL |
| 7   | 1   |          | *SET FRONT DOOR INNER TRIM BOARD CLIPS N/S | Necessary          | 60.00 F    | *60.00 FL    |
| 8   | 1   |          | *FRONT DOOR INNER RUBBER N/S               | Necessary          | 329.00 F   | *188.00 FL   |
| 9   | 1   |          | *FRONT DOOR FRAME TOP CHROME MOULDING N/S  | Necessary          | 482.00 F   | *305.00 FL   |
| 10  | 1   |          | *FRONT DOOR CHANNEL N/S                    | Not Necessary      | 455.10 F   | *- FL        |
| 11  | 1   |          | *REAR DOOR N/S                             | Dented / Bent      | 3,100.00 F | *2,015.20 FL |
| 12  | 1   |          | *REAR DOOR GLASS OUTER MOULDING N/S        | Necessary          | 315.00 F   | *210.30 FL   |
| 13  | 1   |          | *REAR DOOR GLASS FRAME GARNISH N/S         | Necessary          | 118.00 F   | *88.00 FL    |
| 14  | 1   |          | *REAR DOOR INNER LOCK N/S                  | Serviceable        | 655.22 F   | *- FL        |
| 15  | 1   |          | *REAR DOOR INNER TRIM BOARD N/S            | Deformed / Cracked | 1,955.20 F | *1,922.30 FL |
| 16  | 1   |          | *SET REAR DOOR INNER TRIM BOARD CLIPS N/S  | Necessary          | 60.00 F    | *60.00 FL    |
| 17  | 1   |          | *REAR DOOR INNER RUBBER N/S                | Necessary          | 322.90 F   | *188.00 FL   |
| 18  | 1   |          | *REAR DOOR FRAME TOP CHROME MOULDING N/S   | Necessary          | 455.00 F   | *315.00 FL   |
| 19  | 1   |          | *REAR DOOR CHANNEL N/S                     | Not Necessary      | 420.00 F   | *- FL        |
| 20  | 1   |          | *REAR FENDER N/S                           | Bent / Warped      | 2,480.00 F | *1,766.20 FL |
| 21  | 1   |          | *REAR WINDSCREEN MOULDING                  | Not Necessary      | 181.00 F   | *- FL        |
| 22  | 1   |          | *REAR WINDSCREEN SEALANT                   | Not Necessary      | 50.00 F    | *- FL        |
| 23  | 1   |          | *REAR BUMPER                               | Deformed / Torn    | 2,150.00 F | *1,579.85 FL |
| 24  | 1   |          | *REAR BUMPER SIDE HOLDER N/S               | Not Necessary      | 116.00 F   | *- FL        |
| 25  | 1   |          | *SET REAR BUMPER CLIPS                     | Necessary          | 60.00 F    | *60.00 FL    |
| 26  | 1   |          | *ROCKER PANEL GARNISH N/S                  | Deformed / Torn    | 988.10 F   | *915.20 FL   |
| 27  | 1   |          | *REAR SHOCK ABSORBER N/S                   | Not Necessary      | 358.00 F   | *- FL        |
| 28  | 1   |          | *REAR WHEEL HUB N/S                        | Not Necessary      | 850.00 F   | *- FL        |
| 29  | 1   |          | *REAR WHEEL HUB BEARING N/S                | Not Necessary      | 450.00 F   | *- FL        |
| 30  | 1   |          | *REAR SPORT RIM 20 INCH                    | Repair             | 1,800.00 F | *- FL        |

F=Franchise part. L=ListItemDisc.

|                                                          |                  |                  |
|----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                  | <b>25,482.09</b> | <b>15,101.72</b> |
| <b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b> | 0.00             | 755.09           |
| <b>Total Parts (\$\$)</b>                                | <b>25,482.09</b> | <b>14,346.63</b> |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|--------|
| Report was unsubmitted during this print-out. |     |          |             |           |            |        |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                 | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                             |          |                 |                 |
| 1                              | TO CHECK WIRING                             | New      | 50.00           | 20.00           |
| 2                              | TO DISMANTLE & REFIX REAR PDC SENSOR        | New      | 80.00           | 50.00           |
| 3                              | TO DISMANTLE & REFIX REAR WINDSCREEN        | New      | 150.00          | 0.00            |
| 4                              | TO DISMANTLE & REFIX CUSHION UPHOLSTERY     | New      | 150.00          | 80.00           |
| 5                              | TO DISMANTLE & REPLACED REAR UNDER CARRIAGE | New      | 200.00          | 0.00            |
| 6                              | TO CONDUCT WHEEL ALIGNMENT                  | New      | 120.00          | 60.00           |
| 7                              | TO TRANSFER BOTH DOOR MECHANISM             | New      | 180.00          | 140.00          |
| 8                              | TO RESET & REPROGRAMME SYSTEM               | New      | 200.00          | 80.00           |
| 9                              | LABOUR FOR PANEL BEATING & REPLACED PARTS   | New      | 1,200.00        | 800.00          |
| 10                             | TO PUTTY & SPRAY PAINTING                   | New      | 1,800.00        | 1,100.00        |
| <b>Gross Labour Cost (S\$)</b> |                                             |          | <b>4,130.00</b> | <b>2,330.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >