

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005927/BQCEN2**Date:** 18/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00003502000

Claimant Vehicle No : SJE8695Y**Insured Vehicle No :** SME7595Z

Date of Loss: 13/05/2021

Nature of Claim: TP

Claim No: SNM21D202772/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJE8695Y**

Make & Model: HONDA STREAM, 1.8 L (A)

Engine No: R18A12803508

Reg. Date: 12/05/2008 (Man. Year: 2008)

Chassis No: JHMRN68408S203497

Colour: Black

Odometer: 164605 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R15

Rear Tyre Size:

205/65R15

Front Left Side: Linglong 5 mm

Rear Left Side:

Yokohama 5 mm

Front Right Side: Linglong 5 mm

Rear Right Side:

Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,016.10	7,991.20	21,024.90	72.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,150.00	3,640.00	2,510.00	40.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,166.10	11,631.20	23,534.90	66.92
Approved Total (Overridden) (S\$)		9,300.00		
(S\$)	35,166.10	9,300.00	25,866.10	73.55
+ GST 7.00/7.00% (S\$)	2,461.63	651.00	1,810.63	73.55
Nett Amount (S\$)	37,627.73	9,951.00	27,676.73	73.55

INSPECTION

Date of Assignment: 21/09/2021

Date Inspected: 18/05/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 12.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2021)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE8695Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,103.30 FL	*580.00 FL
2	1		*FRONT BONNET HINGES L/R	N/s Bent	130.60 FL	*38.90 FL
3	1		*FRONT BONNET MECHANISM LOCK	Jammed	195.30 FL	*85.10 FL
4	1		*FRONT BONNET INSULATOR MAT	Not Necessary	154.10 FL	*- FL
5	9		*FRONT BONNET INSULATOR MAT CLIPS	Not Necessary	90.00 FL	*- FL
6	1		*FRONT BONNET STAND	Not Damaged	57.10 FL	*- FL
7	1		*FRONT BONNET STAND HOLDER	Not Necessary	12.00 FL	*- FL
8	1		*FRONT BONNET STAND HOLDER CLIP	Not Necessary	10.00 FL	*- FL
9	1		*FRONT BONNET RUBBER WEATHERSTRIP	Not Necessary	132.10 FL	*- FL
10	2		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Not Necessary	24.20 FL	*- FL
11	1		*FRONT WINDSCREEN GLASS	Not Damaged	1,484.30 FL	*- FL
12	1		*FRONT WINDSCREEN GLASS RUBBER MOULDING	Not Necessary	69.90 FL	*- FL
13	1		*FRONT WIPER GARNISH BASE	Broken	313.00 FL	*206.85 FL
14	1		*FRONT WIPER GARNISH BASE CORNER COVER L/R	N/s Necessary	199.80 FL	*36.50 FL
15	2		*ROOF TOP RUBBER MOULDING L/R	Not Necessary	315.60 FL	*- FL
16	1		*FRONT GRILLE CHROME	Broken	235.80 FL	*137.50 FL
17	1		*FRONT GRILLE LOGO EMBLEM	Necessary	65.90 FL	*27.40 FL
18	1		*FRONT GRILLE BASE	Broken	311.90 FL	*145.90 FL
19	3		*FRONT GRILLE BASE CLIPS	Necessary	30.00 FL	*30.00 FL
20	1		*FRONT HEADLAMP L/R	N/s Broken	1,499.80 FL	*376.90 FL
21	1		*FRONT BUMPER	Broken	831.90 FL	*430.00 FL
22	2		*FRONT BUMPER SIDE RETAINER L/R	Necessary	50.00 FL	*36.00 FL
23	1		*FRONT BUMPER CORNER RETAINERS L/R	N/s Broken	123.40 FL	*46.80 FL
24	1		*FRONT BUMPER LOWER GRILLE	Broken	211.80 FL	*96.20 FL
25	2		*FRONT BUMPER FOGLAMP L/R	Not Damaged	957.00 FL	*- FL
26	1		*FRONT BUMPER FOGLAMP GARNISH L/R	N/s Cut	113.20 FL	*31.50 FL
27	1		*FRONT BUMPER REINFORCEMENT	Bent	339.70 FL	*218.00 FL
28	1		*FRONT RESONATOR ASSY	Broken	259.80 FL	*85.00 FL
29	1		*FRONT RESONATOR AIRDUCT	Not Damaged	104.70 FL	*- FL
30	2		*FRONT RESONATOR AIRDUCT CLIPS	Not Necessary	20.00 FL	*- FL
31	1		*FRONT SUPPORT PANEL	Broken	656.10 FL	*440.50 FL
32	1		*FRONT SUPPORT PANEL TOP COVER	No such part	110.30 FL	*- FL
33	4		*FRONT SUPPORT PANEL TOP COVER CLIPS	No such part	40.00 FL	*- FL
34	2		*FRONT SUPPORT PANEL CORNER PANEL L/R	No such part	271.60 FL	*- FL
35	2		*FRONT SUPPORT PANEL SIDE GARNISH L/R	No such part	130.00 FL	*- FL
36	2		*FRONT SUPPORT PANEL SIDE GARNISH CLIPS L/R	No such part	20.00 FL	*- FL
37	1		*FRONT SUPPORT PANEL BRACE PANEL	Bent	158.30 FL	*71.80 FL
38	1		*FRONT SUPPORT PANEL HORN L/R	N/s Bent	125.40 FL	*28.00 FL
39	1		*FRONT SUPPORT PANEL SUB-CHASSIS FRAME L/R	N/s Bent	1,424.00 FL	*467.10 FL
40	1		*FRONT FENDER L/R	N/s Dented	1,297.60 FL	*375.40 FL
41	2		*FRONT FENDER INNER SHIELD L/R	Not Damaged	330.20 FL	*- FL
42	2		*FRONT FENDER SIGNAL LAMP L/R	Not Damaged	61.60 FL	*- FL
43	1		*FRONT FENDER WHEELHSE PANEL LH	Not Damaged	581.70 FL	*- FL
44	2		*FRONT FENDER TOP GARNISH L/R	Not Damaged	211.80 FL	*- FL
45	6		*FRONT FENDER TOP GARNISH CLIPS L/R	Not Necessary	60.00 FL	*- FL
46	1		*FRONT SHOCK ABSORBER TOP MOUNTING LH	Not Damaged	97.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*AIRCON CONDENSER	Bent	955.50 FL	*350.00 FL
48	1		*AIRCON CONDENSER SUCTION PIPE	Not Necessary	151.50 FL	*- FL
49	1		*AIRCON CONDENSER DISCHARGE PIPE	Not Necessary	327.40 FL	*- FL
50	1		*AIRCON CONDENSER COOLING PIPE	Not Necessary	215.50 FL	*- FL
51	1		*AIRCON CONDENSER INLET PIPE	Not Necessary	257.90 FL	*- FL
52	2		*AIRCON CONDENSER TOP BRACKET L/R	Necessary	43.20 FL	*43.20 FL
53	2		*AIRCON CONDENSER LWR MOUNTING L/R	Necessary	51.80 FL	*51.80 FL
54	1		*AIRCON FAN MOTOR ASSY	Not Damaged	358.40 FL	*- FL
55	1		*AIRCON FAN BLADE	Not Damaged	105.00 FL	*- FL
56	1		*AIRCON FAN CROWLING	Not Damaged	185.00 FL	*- FL
57	1		*RADIATOR (A)	Not Damaged	1,624.70 FL	*- FL
58	2		*RADIATOR (A) TOP MOUNTING L/R	Not Damaged	51.80 FL	*- FL
59	2		*RADIATOR (A) LWR MOUNTING L/R	Not Damaged	51.80 FL	*- FL
60	1		*RADIATOR (A) TOP HOSE	Not Damaged	52.00 FL	*- FL
61	1		*RADIATOR (A) LWR HOSE	Not Damaged	64.70 FL	*- FL
62	1		*RADIATOR (A) FAN MOTOR ASSY	Repeated	378.10 FL	*- FL
63	1		*RADIATOR (A) FAN BLADE	Repeated	97.10 FL	*- FL
64	1		*RADIATOR (A) FAN CROWLING	Repeated	159.80 FL	*- FL
65	1		*ENGINE MOUNTING LH	Not Damaged	365.10 FL	*- FL
66	1		*ENGINE MOUNTING RH	Not Damaged	325.80 FL	*- FL
67	1		*ENGINE UNDERCOVER (NPA)	Not Necessary	0.00 FL	*- FL
68	7		*ENGINE UNDERCOVER CLIPS	Not Necessary	70.00 FL	*- FL
69	1		*ENGINE INTAKE HOSE	Broken	97.10 FL	*97.10 FL
70	1		*ENGINE INTAKE MANIFOLD	Not Damaged	381.10 FL	*- FL
71	1		*ENGINE INTAKE MANIFOLD HEAT SHIELD	Not Necessary	107.10 FL	*- FL
72	1		*FRONT DASHBOARD FACIAL ASSY	Broken	1,108.90 FL	*400.00 FL
73	1		*FRONT DASHBOARD CENTER GARNISH	Not Necessary	436.10 FL	*- FL
74	1		*FRONT PASSENGER AIRBAG LH	Activated	2,236.80 FL	*580.00 FL
75	1		*FRONT PASSENGER SEATBELT LH	Activated	635.60 FL	*434.80 FL
76	1		*FRONT DRIVER AIRBAG RH	Activated	1,880.90 FL	*680.00 FL
77	1		*FRONT DRIVER SEATBELT RH	Activated	635.60 FL	*434.80 FL
78	2		*FRONT AIRBAG SENSORS (L/R (SUB-FRAME)	Activated	619.60 FL	*230.00 FL
79	1		*FRONT AIRBAG CONTROL UNIT	Activated	1,093.30 FL	*400.00 FL
80	1		*FRONT DOOR LH	Not Damaged	983.50 FL	*- FL
81	1		*FRONT DOOR CORNER GARNISH LH	Not Damaged	2.00 FL	*- FL
82	1		*FRONT DOOR INNER TRIMBOARD LH	Not Damaged	586.03 FL	*- FL
83	1		*FRONT DOOR CHECKER LH	Not Damaged	53.00 FL	*- FL
84	2		*FRONT DOOR HINGES U/L LH	Not Damaged	88.00 FL	*- FL
85	1		*FRONT CROSS MEMBER	Bent	1,273.50 FL	*894.20 FL
86	1		*FRONT STABILISER BAR	Not Damaged	163.30 FL	*- FL
87	2		*FRONT STABILISER BAR BUSH L/R	Not Damaged	17.60 FL	*- FL
88	2		*FRONT STABILISER BAR LINKAGE L/R	Not Damaged	83.00 FL	*- FL
89	1		*AIRCON COMPRESSOR	Jammed	1,265.20 FL	*598.00 FL
90	1		*GEARBOX SOLENOID VALVE	Dented	429.10 FL	*362.20 FL
91	1		*GEARBOX FLOW PIPE	Bent	54.80 FL	*54.80 FL
92	1		*AIR FILTER BOX	Broken	129.60 FL	*90.00 FL
93	1		*AIR FILTER BOX INTAKE DUCT	Broken	88.10 FL	*40.00 FL
94	1		*AIR FILTER BOX OUTFLOW DUCT	Dented	44.10 FL	*28.00 FL
95	5		*GEARBOX FLUID	Not Necessary	150.00 FS	*- FS
96	1		*AIR FILTER	Necessary	50.00 FS	*38.00 FS
97	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
98	1		*FRONT BUMPER NO PLATE	Bent	25.00 FS	*25.00 FS
99	1		*FRONT BUMPER NO PLATE GARNISH	Broken	50.00 FS	*30.00 FS
100	2		*FRONT FENDER INNER SHIELD CLIPS L/R	Not Necessary	60.00 FS	*- FS
101	5		*LITRE ENGINE OIL	Not Necessary	125.00 FS	*- FS
102	1		*AIRCON GAS	Necessary	50.00 FS	*30.00 FS
103	1		*COOLANT	Necessary	120.00 FS	*30.00 FS
104	1		*FRONT DOOR INNER TRIMBOARD CLIPS LH	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 36,097.63 9,943.25

Report was unsubmitted during this print-out.

10/18/21, 1:14 PM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					7,081.53	1,952.05
Total Parts (S\$)					29,016.10	7,991.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIX & RESETTING AIRBAGS,BELTS CONTROL ASSY AND RETIFY FOR PROPER FUNCTIONING	New	600.00	300.00
2	TO DIAGNOSE,REPLACE/OR REPAIR ON THE FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	180.00	80.00
3	TO REMOVE,REINSTALL ROOF TOP UPHOLSTERY,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	120.00	0.00
4	TO REMOVE,REFIX & REPLACE ENGINE PARTS AND MOUNTING AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	350.00
5	TO RESPRAY,PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,600.00	1,000.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE DAMAGED BODYPARTS,REPAIR,ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT	New	1,750.00	1,200.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED & REPLACED PANEL AND WHERE CONSISTENT TO THE ACCIDENT	New	180.00	60.00
8	TO DISMANTLE,REPLACE OR REPAIR AIRCON COMPRESSOR ASSY,PIPIES,HOSES AND RECEIVER DRYER ASSY TO FACILITATE REPAIRS	New	150.00	120.00
9	TO REMOVE,REFIX/RENEW INSTRUMENT PANELS,FITTINGS AND WIRING ASSY TO REPAIR & FACILITATE REPAIRS (DASHBOARD)	New	400.00	250.00
10	TO REMOVE,CHANGE FRONT SUSPENSION PARTS,ABSORBER,LOWER ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB,DRIVESHAFT,CROSS MEMBER,ANTI-ROLL, TOP ARM & STEERING RACK AND PINION	New	300.00	180.00
11	TO REMOVE,REINSTALL AND CHANGE CD CHANGER,SPEAKER & ARRANGE SOUND SYSTEM WIRING	New	120.00	0.00
12	TO DISMANTLE,REPLACE OR REPAIR RADIATOR,PARTS,PRESSURE TEST & REPLACE COOLANT	New	150.00	100.00
Gross Labour Cost (\$)			6,150.00	3,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >