



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105295

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 29/07/2021
Reference CC3/CTI21005934/Gea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 3572K
Insured Veh. YQ 8480J
Claim No. SNM21D202822/C02
Policy No. DMCVSNW00122002002
Accident Date 06/05/2021
Inspection Date 17/05/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21005934/Gea3q2	
			Date: 29/07/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 8480J	Veh. Inspected	SHC 3572K	
Policy No.	DMCVSNW00122002002	Coverage (\$)	0.00	
Claim No.	SNM21D202822/C02	Excess (\$)	0.00	
Assign From		Assign Date	17/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AE IONIQ HEV 1.6	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVKU164834	Colour	BLUE	
Odometer	185184 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/05/2021	Inspection Date	17/05/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3572K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER -FR BUMPER	DEFORMED	430.90	430.90
1	GRILLE ASSY-RADIATOR	CRACKED	1,409.10	1,409.10
10	BUMPER COVER CLIP FRT	NECESSARY	22.00	22.00
1	MOULDING -FRONT BUMPER CTR	CRACKED	368.50	368.50
1	PANEL -FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	LAMP ASSY -HEAD RH	NOT NECESSARY	1,993.65	-
1	CAP -FRONT HOOK	CUT	29.00	29.00
1	COVER -RR BUMPER	DEFORMED	459.40	459.40
1	LAMP ASSY -REAR FOG	BROKEN	201.50	201.50
1	MOULDING ASSY -RR BUMPER C	CRACKED	451.25	451.25
10	BUMPER COVER CLIP REAR	NOT NECESSARY	22.00	-
1	BEAM -RR BUMPER	CRACKED	394.80	394.80
1	ANTENNA ASSY -SMARTKEY	MISSING	40.50	40.50
1	EMBLEM -HYBRID (ADDITIONAL)	NECESSARY	24.30	24.30
1	EMBLEM -IONIQ(ADDITIONAL)	NECESSARY	31.30	31.30
1	BOOTLID COVER (ADDITIONAL)	BUCKLED	2,480.40	2,480.40
1	STAY -REAR BUMPER LH (ADDITIONAL)	BENT	138.10	138.10
1	STAY -REAR BUMPER RH (ADDITIONAL)	BENT	138.10	138.10
1	FRT BUMPER BEAM (ADDITIONAL)	BENT	1,075.10	1,075.10
1	MOULDING FRT NUMBER PLATE (ADDITIONAL)	CRACKED	17.40	17.40
1	FLAP ASSY -ACTIVE AIR UPPER	CRACKED	356.00	356.00
	LESS 20% DISCOUNT		-2,134.42	-1,613.53
			8,537.68	6,454.12
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE FRONT W/CASI (SN)	CRACKED	50.00	50.00
1	NUMBER PLATE W/CASING -RE (SN)	CRACKED	50.00	50.00
1	PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
1	BOOTLID COMFORTDELGRO LOGO (SN) (ADDITIONAL)	NECESSARY	30.00	30.00
1	BOOTLID TEL,NO LOGO (SN) (ADDITIONAL)	NECESSARY	30.00	30.00
1	BOOTLID APPS LOGO (SN) (ADDITIONAL)	NECESSARY	40.00	40.00

Report Ref No. CC3/CTI21005934/Gea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FUEL TANK LIP (PATROL STICKER) (SN) (ADDITIONAL)	NECESSARY	15.00	15.00
			265.00	265.00
	LABOUR			
	PANEL BEATING -FRT .INCLUSIVE OF THE REPAIR OF PANEL -FENDER RH .		800.00	350.00
	SPRAYPAINT CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		50.00	20.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	PANEL BEARING -REAR .		1,050.00	1,050.00
	SPRAYPAINT CHARGE.		1,000.00	1,000.00
	REMOVE/REFIX REVERSE SENSOR .		80.00	40.00
	TOWING .		60.00	60.00
			3,690.00	3,020.00
GRAND TOTAL			12,492.68	9,739.12
RECOMMENDED COST OF REPAIRS				9,739.12

Report Ref No. CC3/CTI21005934/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3572K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3572K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3572K

RE-INSPECTION

