

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI21005935/UTCQ2

Date:

08/06/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMCVSNW00113832000

Claimant Vehicle No : FBP3912R

Insured Vehicle No :

GBF4735G

Date of Loss: 12/05/2021

Nature of Claim:

TP

Claim No: SNM21D202823/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP3912R**

Make & Model: YAMAHA FZ16, 153cc (M)

Engine No: 21CG039783

Reg. Date: 29/05/2014 (Man. Year: 2013)

Chassis No: ME121C0GBD2039778

Colour: Black

Odometer: 2760 km

Engine Capacity: 153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110-70-17	Rear Tyre Size:	150-60-17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,805.40	1,090.10	2,715.30	71.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	560.00	920.00	62.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,285.40	1,650.10	3,635.30	68.78
Approved Total (Overridden) (S\$)		1,300.00		

Nett Amount (S\$)**5,285.40****1,300.00****3,985.40****75.40**INSPECTION

Date of Assignment: 18/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jun 2021)	
Parts:	N/A	YAMAHA FZ16 153cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP3912R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Repair	105.00 FL	*- FL
2	2		*FORK INNER TUBES	Serviceable	480.00 FL	*- FL
3	2		*FORK OUTER TUBES	Repair	500.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Not Necessary	265.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Cut	55.00 FL	*38.00 FL
6	1		*FRONT RIM BEARING	Not Necessary	45.00 FL	*- FL
7	1		*FRONT BRAKE DISC	Not Necessary	185.00 FL	*- FL
8	1		*SET SIDE MIRROR	Broken	140.00 FL	*140.00 FL
9	1		*FRONT SIGNALS	N/S Cut	140.00 FL	*60.00 FL
10	1		*HANDLE -BAR	Serviceable	150.00 FL	*- FL
11	1		*HANDLE -BAR BALANCER (N/S)	Cut	68.00 FL	*35.00 FL
12	1		*SET HAND GRIP	Not Necessary	85.00 FL	*- FL
13	1		*CLUTCH LEVER	Cracked	35.00 FL	*35.00 FL
14	1		*FUEL TANK SIDE COVER -L/H	Cut	250.00 FL	*250.00 FL
15	1		*FRONT LOWER COVER	Cracked	180.00 FL	*180.00 FL
16	1		*HEADLAMP SIDE COVER	Repair	95.00 FL	*- FL
17	1		*SIDE STAND	Cut	95.00 FL	*95.00 FL
18	1		*MAIN STAND	Repair	135.00 FL	*- FL
19	1		*FRONT FOOTREST	N/S Cut	96.00 FL	*48.00 FL
20	1		*FRONT FOOTREST BRACKETS	N/S Bent	220.00 FL	*100.00 FL
21	1		*GEAR PEDAL	Bent	58.00 FL	*58.00 FL
22	1		*REAR HANDLE	Cut	150.00 FL	*150.00 FL
23	2		*REAR FOOTREST	Serviceable	104.00 FL	*- FL
24	2		*REAR SIGNAL LAMPS	Not Necessary	160.00 FL	*- FL
25	1		*SET NUMBER PLATE (FRT & REAR)	Bent	28.00 FS	*20.00 FS
26	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
27	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*SET STEERING CONE	Not Necessary	95.00 FS	*- FS
29	1		*E.R.P IU	Serviceable	180.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,185.00	1,209.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					379.60	118.90
Total Parts (\$\$)					3,805.40	1,090.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	60.00	60.00
2	TO CHECK WIRING AND RESET HEADLAMP FORCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO RE-SPRAY PAINT	New	480.00	250.00
5	TO PROVIDE LABOUR	New	480.00	250.00
Gross Labour Cost (S\$)			1,480.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >