HIN TAT AUGUSTINE & PARTNERS UEN NO. 53130863D

WEBSITE: www.htapartners.com.sg

Advocates & Solicitors Commissioners For Oaths

20 UPPER CIRCULAR ROAD #02-10/12 THE RIVERWALK SINGAPORE 058416

TEL: (65) 6533 0212 FAX: (65) 6533 0313

SECRETARY: RUBY ONG (ruby@htapartners.com.sg)

In Association with: Strohal Legal Group Pte Ltd International Legal Consultants

(65) 6533 0163 (Direct Fax) Service By Fax Not Accepted

Our Ref:

TCL.ro.50048.21.ess

Your Ref:

SNM21D201047/CO2/YP8716K/THAMYL

26 April 2021

PO Builders Pte Ltd

18 Enterprise Road Singapore 629824

By Certificate of Posting (w/o encl)

(for your information only)

By email

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Attn: Ms Pauline Tham / Motor Claims Department

Dear Sirs

ACCIDENT INVOLVING GBK 7294K, YP 8716K, YP 7833L, GBG 3179M, GBB 6954Z & YP 8589K ALONG AYE (CITY) BEFORE EXIT 13 (JURONG TOWN HALL EXIT) ON 23 **FEBRUARY 2021 @ 0720HRS**

We act for Skylink Vehicle Rental Pte. Ltd., the owner of motor vehicle no. GBK 7294K, in relation to the above-captioned road traffic accident.

We are instructed that you were the owner and/or the insurer of motor vehicle no. YP 8716K at the material time. We are further instructed that the accident was caused by your authorised driver and/or your insured driver's negligence in the driving, control and/or management of your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

1.	Cost of Repairs		S\$24,800.00
2.	Rental Charges (35 days x S\$140.00/ day)		S\$ 4,900.00
3.	Survey Report Fees		S\$ 1,284.00
4.	LTA Search Fee		S\$ 14.98
5.	Costs (inclusive of GST)		S\$ 1,070.00
6.	Incidentals		S\$ 50.00
		Total	S\$32,118.98

.../Page2

CONSULTANTS:





HIN TAT AUGUSTINE & PARTNERS

Page No. 2

Our Ref. TCL.ro.50048.21.ess

Your Ref. SNM21D201047/C02/YP8716K/THAMYL

Date: 26 April 2021

The following supporting documents are enclosed herewith: -

- 1. Copy of Singapore Accident Statement by GBK 7294R;
- 2. Copy of Certificate of Insurance from China Taiping Insurance (Singapore) Pte. Ltd.;
- 3. Copy of Repair Bill from Euro Success Serv Pte Ltd;
- 4. Copy of Invoice from Tan Leasing Pte Ltd;
- 5. Copy of Invoice and LTA Search Result of YP 8716K;
- 6. Copy of Survey Invoice & Survey Report from Ajax Inspection Services Pte Ltd.; and
- 7. 54 pcs of original photographs of motor vehicle no. GBK 7294R.

Please note that you / your authorized driver and/or your insured driver should send to us an acknowledgement of receipt of this letter within **fourteen (14)** days of receipt of this letter, failing which our clients will have no alternative but to commence proceedings against you / your authorized driver and/or your insured driver without further notice to you / authorized driver and/or your insured driver.

Please note that if you / authorized driver and/or insured driver have a counterclaim against our clients arising out of the accident, you / authorized driver and/or your insured driver are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within **eight (8)** weeks of your receipt of this letter.

Please note that our client's claim is in respect of its property damage claim and is strictly without prejudice to the uninsured losses and/or injury claim (if any).

Yours faithfully,

Enc.

cc: clients By fax



Enquire Vehicle Owner Details (As At 23 Feb 2021 / 07:20:00)

Vehicle Owner Details

Owner ID Type:

Owner ID:

Company

198802736E

Owner Name:

Registered Address Type:

PQ BUILDERS PTE LTD

Private Residential (Condo Apt or House) /

Shopping / Office Complexes

Registered Block/House No.:

Registered Street Name:

18

ENTERPRISE ROAD

Registered Unit No.:

Registered Building Name:

•

Registered Postal Code:

629824

Vehicle Insurance Details

Vehicle No.

Make Description/Model:

YP8716K

MITSUBISHI / CANTER FEB21ER4SDEN (CBU)

6K ;

Insurance Company Name:

CHINA TAIPING INSURANCE (SINGAPORE)

PTE LTD



Enquire Vehicle's Insurance Particulars (As At 23 Feb 2021 / 07:20:00)

Vehicle No.:

Make Description/Model:

YP8716K

MITSUBISHI / CANTER FEB21ER4SDEN (CBU)

Insurance Company Name:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Business Transaction Reference No.:

20210223145256265339

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Printed on 23 Feb 2021 14:53:27

Copyright © Land Transport Authority of Singapore 2021

EURO SUCCESS SERV PTE LTD

No. 1 Kaki Bukit Avenue 6 #02-03 AutoBay, Singapore 417883

Tel: 9336 5311 Fax: 6741 1019

Name

: SKYLINK VEHICLE RENTAL PTE LTD

Date

: 14 APRIL 2021

Invoice No : SH/GBK7294R

Address : c/o No. 1 Kaki Bukit Avenue 6

#02-03 AutoBay @ Kaki Bukit

Singapore 417883

LUMP SUM REPAIR BILL FOR TOYOTA HIACE NO. GBK7294R

Lump Sum Repair Cost

24,800.00

SINGAPORE DOLLARS: TWENTY FOUR THOUSAND EIGHT HUNDRED ONLY

Signature & Official Stamp

1 Kaki Bukit Ave 6 #02-02 Autobay @Kaki Bukit Singapore 417883

Tel: 88698285 Fax: 67411019

INVOICE

To

MOZUMDER OVIJIT

Nric

:

G6973476L

Address

BLK 680C JURONG WEST CENTRAL 1 #14-52

Vehicle Number Plate GBG911K

And Model:

NISSAN NV350

Rental Rate:

\$140

S/N	Description	Duration/Day	Amount
1	23/02/2021 – 30/03/2021	35	SGD 4900
	Total No of	35	
Days		Total Amount	SGD 4900.00

Remarks:			



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 5. Internation provided most set and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving the control of the part will for a fee the made available upon application by interested parties. and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 24/02/2021 09:54 (SGT) Date of Accident 23/02/2021 07:20 (SGT) Exact Location of Accident AYE, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **GBK7294R**

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner SKYLINK VEHICLE RENTAL PTE LTD Company Reg No 2XXXXX755G Email Address XDETOX32@GMAIL.COM Mobile Phone No (Phone) +65-92338260 Alternative Phone No. +65-92338260

VEHICLE PARTICULARS

Manufacturer Toyota Model Hiace Variant Exact purpose for which vehicle was being used at time of accident Employment Are you claiming under your own insurance policy for repair to

your vehicle? No - Claiming third party Vehicle Category Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance Type of Coverage Comprehensive Fleet Policy Policy Number DMCVSNA00029102000 Cover Note Number

DRIVER

Name of Driver **MOZUMDER OVIJIT** Work Permit No GXXXX476L Date Of Birth 10/11/1989 Occupation Outdoor

Date Of Driving Pass 20/01/2018 3 YEARS AND 1 MONTH Driving experience Gender Male Mobile Number (Phone) +65-84210551 Alt. Phone Number Email Address XDETOX32@GMAIL.COM BLK 680C JURONG WEST CENTRAL 1 #14-52 Address Address complement 643680 Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No
Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE397U Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver **WOO TUCK WYE** NRIC No SXXXX698I Contact Number Address Address complement Postcode

Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YP8716K
Vehicle Manufacturer	300
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	·
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	
Address	:=:
Address complement	
Postcode	
Insurance Company Name	2
Nature Of Damage	200 200
Details of property damaged in accident	E
No. Of Passenger (Including Driver)	
140. Of 1 doooniger (medically briver)	-x

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number Vehicle Manufacturer	YP7833L
	₹
Vehicle Model	-
Vehicle Variant	<u>u</u>
Vehicle Colour	
Vehicle Category	Commercial vehicle
Name of Driver	
Contact Number	-
Address	
Address complement	<u> </u>
Postcode	<u>=</u>
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	Ti.
No. Of Passenger (including Driver)	₹a

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	GBG3179M
Vehicle Manufacturer	100
Vehicle Model	
Vehicle Variant	
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	(2
Contact Number	: <u>-</u>
Address	24
Address complement	2.
Postcode	· =
Insurance Company Name	-
Nature Of Damage	(후) (원)
Details of property damaged in accident	
	: - :
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number	GBB6954Z
Vehicle Manufacturer	
Vehicle Model	*



Vehicle Variant	11
Vehicle Colour	···
Vehicle Category	Commercial vehicle
Name of Driver	
Contact Number	
Address	
Address complement	-
Postcode	<u>u</u>
Insurance Company Name	<u>u</u>
Nature Of Damage	#
Details of property damaged in accident	*
No. Of Passenger (Including Driver)	Ħ

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Manufacturer	
Vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category Commercial Comme	cial vehicle
Name of Driver	
Contact Number	
Address	
Address complement =	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	MOZUMDER OVIJIT
Address	-
Address Complement	*
Post Code	=
Approximate Age Years Old	
Injuries Sustained	BODY
Injured person in which vehicle?	GBK7294R
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No


SKETCH PLAN

IMPORTANT NOTICE

- Filease report correctly the details of the according to speed up this thank process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3 information provided must be as truthful and accurate as possible. Any will dissepte entation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The saud and acceptance of this Formby resurance companies is not an admission of policy liability on the part of the risurance companies.
- 5 Any false reporting may be referred to the Police for investigation
- 5. The risport widlibe rony arded by the insurers of the GV. Records Manuscrimes Contral established by the General Insurance Association
- of Balancore (CV) for prothiving and that copies of this report A 8 five after the made axis inclination by after 651-60 pathes.
- If By the lodgement of this report to the insurers, is so hereby nonsent to the explicing of this report at the centre and to nodes of the report peng made available aforesaid.
- 5 Consent under the Personal Data Protection Act (PDPA)

contensions acen wiedge agree and countinal

- A My insured my wide-shop and the Generalize cance Association of Singaporia. GIA I may are permitted to control to the first and of processing personal case of personal order personal managements and of the first order personal information is and decision and transfer auch the constitution to valid to the process of paying insured notices involved at this account as now have natured vehicles involved at this account as now personal vehicles involved in this account as now personal vehicles in violed in the account as now personal account at the first personal account of the process of the first personal account as the first personal account account of the personal account account of the personal account as the personal transfer of the purpose.
- processing introduce and in decarry with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- an envestigating the accident and/or my came
- cold arriving our and or deal of widthing instructions in restronding to any endo less by the
- jevil administering my claims, impluding the making of parties pondence, statements, shratoes, reports or notices to me, which could involve declarate of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes making packages; and/or
- (v) complying with applicable law in administering processing mandling and/or dealing with my claims.
- collectively the "Purposes":
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents including their law yers/law forms), which may be sited outside of Singapore, for one or more of the above Purposes.



Dø:	cribe	Cire	មកាន	tances	ort	ne A	CCICIO	nt -						Ard a		0.6		40
th.	the	ab	GVC	strite	1	dute	and	time.	1	و بازن	trovctine) (de	ny	HIE ((14)	D.CF.O.		
13	(30	reinig	Tore	95. H	50)	Exit). I	Wis	tro	~ (1 · 5)	shely	ist sa	logra	swide	oxy.	white	ß	
Gli	العل	64	the	1,4	14	Velv	000	left (s e4.00	n I	H.c	brak	¢	end	3 widen	4 1	chile	C
(0)	idal	evi	фя	my	Ve	inc.	when	1	ala	gloted	I je	ried	1	was	invo	lve	141	ű
4	(0		desin	GL	cide	4												
F						_	_											
F																		
F																		
F																		
E																		
-		_	-		-													

Declaration

Why do live the formation growth time is size that as every resort.



Policynoider's Signature | Date & Time

Quint

Driver's Signature (E griver is not the policyholder) / Date & Time

the

Witnessed by Reparting Centre Personnel

























































中間太平保险 (新加坡)有限公司

CERTIFICATE OF INSURANCE

M2467/C

ANGATEA Courtype C

CESTIFICATE NO.

DAICVSNACKUZ9102000

Engine No INCHESTORS

Cha No ITEMEDIZATION

CHR7294R

AUTOSAFE

SKYLINK VEHICLE HENTAL PTE LTO

Keems fleet (

5\$3,000 on

HACRES Sect. 5 EX ON WINDSCHEEN

22/04/2021

HIRE PURCHASE CO. DBS BANK LTD

* Limitations rendered inoperative by Section & of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 1 his and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

Issued By

Lim Lee Choo Authorised Officer

Taiping Insurance (Singapore) Pte Ltd. (Co. Reg. No. 200208384E) Inson Road #16-00 Springleaf Tower Singapore 079909

Q63896111

66222 1033

www.sg.cntaiping.com



Date

: 19 April 2021

То

Euro Success Serv Pte Ltd

Blk 1 Kaki Bukit 6

#02-03 Singapore 417883

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208

Tel: +65 6255 0808 Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No - AV28406

Company Reg No -201318067R GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER

: GBK7294R

OUR REF

: AVS2021-26731/BL

VEHICLE NO

: GBK7294R

CLAIM TYPE

: VEHICLE INSPECTION

DATE OF SURVEY

: 23 March 2021

No.

Description

Amount (S\$)

1

Professional fee

1200.00

Subtotal

1200.00

GST 7.00%

84.00

Total

1284.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows: Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com





INSPECTION REPORT

Euro Success Serv Pte Ltd

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

Assign Date:

23/03/2021

Inspection Date:

23/03/2021

TP Report Date: 24/02/2021

Accident Date:

23/02/2021

TP Policy No:

DMCVSNA00029102000 Our Ref:

AVS2021-26731/BL

Place of Inspection:

Euro Success Serv Pte Ltd

Your Ref:

GBK7294R

Blk 1 Kaki Bukit 6, #02-03

Claimant:

Skylink Vehicle

Rental Pte Ltd

Description of Vehicle:

Veh. No:

GBK7294R

Singapore

Make/Model:

Toyota Hiace Van Turbo 5DR MT

Colour: **Engine Capacity:** White 2,982 cc **Engine No: Chassis No:**

417883

1KDB047045

JTFHT02PX00250700

Odometer:

28353

Reg. Date:

30/10/2020

Condition of Vehicle:

General:

Good

Modification:

No

Steering:

Serviceable

Air-Conditioner:

Yes Serviceable Radio/Cassette/CD:

Yes

Wing Mirror: Paint work:

Yes

Handbrake: Tyre Make:

Bridgestone

Footbrake:

Serviceable

Front Right Side:

5_mm

Good

Front Tyre Size: **Rear Tyre Size:**

195R15C 195R15C

Front Left Side: Rear Left Side:

5_mm 5mm

Rear Right Side:

5mm


Description of Damage:

The damage was found on the rear portion.

Point of Impact:







Adjuster:

Billy Loh

Motor Appraiser

COMPLETED 19 APR 2021

Date

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis. AJAX Inspection Services Pte Ltd



Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle: GBK7294R Our Re					AVS2021-26731/BL
No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation S\$
List Iten	ns				
1	1	Tailgate	Bent	2,265.00 7	530 2,265.00
2	1	Tailgate glass	Cracked	1,115.00 🞖	9 0 1,115.00
3	1	Tailgate view mirror	Not necessary	382.00	#
4	1	Tailgate wiper arm	Not necessary	87.00	
5	1	Tailgate wiper motor	Jammed	432.00	nn 432.00
6	1	Tailgate emblem Toyota	Necessary	60.00	60.00
7	1	Tailgate outer chrome moulding	Cracked	255.00	255.00
8	2	Tailgate licence lamp	Not necessary	85.00	**
9	1	Tailgate inner lock	Jammed	262.00	262.00
10	1	Tailgate inner trims	Cracked	282.00	282.00
11	1	Tailgate inner trims clips	Necessary	68.00	30.00
12	1	Tailgate inner lock actuator	Not necessary	281.00	.
13	1	Tailgate lock striker	Not necessary	52.00	
14	2	Tailgate dampers L/R	Not necessary	364.00	122
15	2	Tailgate hinges L/R	Not necessary	131.00	ne.
16	2	Tailgate side stopper L/R	Not necessary	98.00	J750
17	2	Tailgate side stopper strikers L/R	Not necessary	99.00	
18	1	Tailgate third brake light	Not necessary	332.00	
19	2	Taillamps L/R @ 365 loach	Cracked	1,250.00 <i>73</i>	o <u>2</u> 01,065.30
20	1	Taillamp filler panel inner L/R	Bent LHXA	^ 964.00 ^R 4 ✓ 3	18 .4° 482.00
21	1	Taillamp filler panel outer L/R	Bent LHXnr	1,050.00 RH	
22	1	Rear bumper	Cracked	681.00	681.00
23	1	Rear bumper clips	Necessary	27.00	27.00
24	4	Rear bumper side holders L/R	Necessary	50.00	50.00
25	1	Rear end panel inner	Bent	742.00	625.00
26	1	Rear end panel outer	Bent	613.00	513.00
27	1	Rear end panel top mounting	Not necessary	212.00	##
28	1	Rear exhaust silencer	Bent	1,299.00	²²⁵ 899.00
29	3	Rear exhaust mounting	Bent	86.00	86.00
30	1	Rear floor mat	Not necessary	855.00	=

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Adjustment of Repair Cost for Vehicle:			GBK7294R	Our Ref:	AVS2021-26731/BI
No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation S\$
31	1	Rear floor compartment panel	Not necessary	1,900.00	-
32	1	Rear step panel	Repair	281.00	
33	1	Rear floor panel lower member CTR	Bent		6 <u>2</u> 562.00
34	1	Rear fender L/R @ \$1583.50 cah	Bent LHX		l
35	1	Rear fender outer cover L/R	Bent LHX	l	
36	1	Rear fender inner trim board	Cracked	564.00	282.00
37	1	Rear fender inner trim board clips	Necessary	135.00	135.00
38	1	Rear fender inner lower side covers	Cracked	253.00	126.50
39	1	Rear fender inner panels	Deformed	1,400.00	/ × 1,230.90
40	1	Rear fender wheel housing	Deformed	1,800.00	R × 690.20
41	1	Rear fuel lid	Not necessary	127.00	
42	1	Rear fuel lid opener	Not necessary	90.00	¥2
43	1	Rear fuel filler pipe	Not necessary	290.00	
44	1	Rear diesel tank	Not necessary	1,300.00	
45	2	Rear fender inner frame member L/R	Not necessary	890.00	
46	2	Rear leaf sring L/R	Not necessary	1,650.00	
47	2	Rear shock absorber L/R	Not necessary	380.00	
48	2	Rear side chassis member L/R	Repair	1,050.00	
49	1	Rear spare wheel carrier	Deformed	300.00	220 300.00
50	1	Rear spare wheel carrier support	Bent	500.00	R ≠ 500.00
51	1	Rear gear with axle	Jammed	6,000.00 ≤№ \$	2000 4,200.00
52	2	Rear whel hub shaft L/R	Bent	1,050.00	690.40
53	2	Rear whel hub shaft bearing	Necessary	350.00	225.20
54	1	Rear propellor shaft	Bent	1,400.00 <i>≤N</i> \$	600 1,120.90
55	1	Manual transmission mounting	Not necessary	186.00	22
56	2	Engine mounting	Not necessary	313.00	
57	1	Radiator	Not necessary	891.00	an.
58	1	Radiator fan cowling	Not necessary	190.00	**************************************
59	1	Radiator fan blade	Not necessary	150.00	
60	1	Sliding door R/H	Repair	1,700.00	
61	1	Sliding door track R/H	Not necessary	300.00	

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Inspection Services Pte Ltd

No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation
		=		S\$	S\$
62	1	Sliding door track cover	Not necessary	90.00	##
63	1	Sliding door CTR roller	Not necessary	211.00	**
64	1	Sliding door top roller	Not necessary	211.00	***
65	1	Sliding door lower roller	Not necessary	211.00	
66	1	Sliding door lower track	Not necessary	290.00	
67	1	Sliding door inner lock	Not necessary	260.00	
68	1	Sliding door weatherstrip	Not necessary	200.00	===
69	1	Sliding door inner trim	Not necessary	300.00	
70	1	Sliding door inner trim clips	Not necessary	70.00	
71	1	Manual transmission gear box	Distorted	13,000.00	^ 11,896.30
.11429.30 Sub Total:				61,824.00	34,863.70
25/- 8571.97 Discount (less 25%):				15,456.00	8,715.93
SN \$2,600				46,368.00	26,147.78

Special Nett Items						
1	1	Tailgate glass sealant	Necessary	60.00	15.00	
2	1	Rear sticker 70km	Necessary	10.00	10.00	
3	1	Rear sticker 8 pax	Necessary	10.00	10.00	
4	1	Rear number plate	Necessary	20.00	20.00	
5	1	Rear reverse sensor	Dented	200.00	200.00	
6	2	Rear tyre L/R	Not necessary	150.00	<u>#</u>	
7	1	Rear gear oil	Not necessary	80.00		
8	4	Rear leaf spring U bolt	Bent	180.00	150.00	
311	Sub Total:			710.00	405.00	
			Total Parts Price:	47,078.00	26,552.78	

<u>Labour Cost</u>					
1	Towing.	250.00			
2	To remove refix tailgate glass.	180.00	120.00		
3	To check eletrical wiring.	120.00	30.00		

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



1507697

Adjust	Adjustment of Repair Cost for Vehicle: GBK7294R			Our Ref: AVS2021-26731/BL		
No.	Qty	Description of Parts	Condition	Repairer's Estimate	Our Recommendation S\$	
4	To remov	I ve refix rear undercarriage including rear ax	le	650.00 2	₽ 450.00	
5	To remov	ve refix rear interior trims to assist repair.		180.00	100.00	
6	To check	wheel alignment.		200.00	80.00	
7	To remov	ve replace manual transmission and all atta	800.00 _2	₽ 400.00		
8	To remov	ve replace diesel tank and all attachment.	150.00	120.00		
9	To remov	ve refix ending mounting.	350.00			
10	To respra	ay under coating.	450.00	60.00		
11	Panel bea	ating, cut, weld, remove and replace above	6,500.00 / <u>6</u>	0		
12	To remov	To remove and refit rear petrol tank			× 150.00	
13	To spray	To spray painting			1,200.00	
			Sub Total:	12,110.00 35	0 0 4,510.00	
			59,188.00	31,062.78		

Recommendation and Conclusion:

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimate repair cost is \$\$56,672.75. The repairer has agreed to undertake the repairs at our adjusted lumpsum amount of \$\$24,800.00.

We have not authorised the repair. Under normal circumstances, estimated twenty two (22) working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

The inspection was conducted entirely on a "Without Prejudice" basis.

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



AVS2021-26731/BL

Your Ref:

GBK7294R













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AVS2021-26731/BL

Your Ref:

GBK7294R













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



AVS2021-26731/BL

Your Ref:

GBK7294R













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



AVS2021-26731/BL


Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

AVS2021-26731/BL

Your Ref:

GBK7294R













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.




AVS2021-26731/BL

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2021-26731/BL


Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2021-26731/BL

Your Ref:














Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd



AVS2021-26731/BL

Your Ref:

GBK7294R













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.