

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21005945/ERS3Q2**Date:** 06/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900020829
Claimant Vehicle No :	SLE5717P	Insured Vehicle No :	GBJ2372L
Date of Loss:	04/05/2021	Nature of Claim:	TP
		Claim No:	9732820279SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE5717P	Engine No:	G4KJKDR66388
Make & Model:	KIA SORENTO, 2.4 GDI HID S/R (A)	Chassis No:	KNAPH813MG5239929
Reg. Date:	27/07/2016 (Man. Year: 2016)	Odometer:	119597 km
Colour:	Black		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,246.40	758.00	1,488.40	66.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	980.00	1,150.00	53.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,376.40	1,738.00	2,638.40	60.29
+ GST 7.00/7.00% (S\$)	306.35	121.66	184.69	60.29

Nett Amount (S\$)	4,682.75	1,859.66	2,823.09	60.29
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
Nett Liability (S\$)		2,287.66		

INSPECTION

Date of Assignment: 19/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS	
2	1		*LOGO ASSY -KIA SUB	Not Necessary	68.80 FS	*- FS	
3	1		*MOUNTING ASSY -LICENCE PLATE	Broken	29.60 FS	*29.60 FS	
4	1		*COVER -FR BUMPER UPR	Not Necessary	516.00 FS	*- FS	
5	1		*COVER -FR BUMPER LWR	Cut	516.00 FS	*516.00 FS	
6	1		*GRILLE ASSY-RADIATOR	Not Necessary	590.40 FS	*- FS	
7	1		*ABSORBER -FROTN BUMPER ENERGY	Not Necessary	107.20 FS	*- FS	
8	1		*GRILLE -FRONT BUMPER	Cut	142.40 FS	*142.40 FS	
9	1		*SKID PLATE -FR BUMPER	Not Necessary	176.00 FS	*- FS	
10	1		*FRONT NUMBER PLATE AND FRAME	Cut	50.00 FS	*50.00 FS	
					Total Parts (S\$)	2,246.40	758.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE	New	1,200.00	400.00
2	REMOVE AND INSTALL PARKING ASSIST	New	80.00	80.00
3	PAINT WORK SPRAY FRONT BUMPER	New	700.00	350.00
4	SUPPLY FRONT NUMBER PLATE AND FRAME	New	-	-
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
			Gross Labour Cost (S\$)	980.00
			2,130.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >