

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21005946/ERS3Q2
Date: 16/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800152064
Claimant Vehicle No :	SMF3170L	Insured Vehicle No :	SKF827U
Date of Loss:	08/04/2021	Nature of Claim:	TP
		Claim No:	3460219649SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3170L		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHH7632
Reg. Date:	01/11/2018 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH003872
Colour:	Red	Odometer:	85368 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,254.00	1,074.13	1,179.87	52.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,340.00	1,640.00	55.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,234.00	2,414.13	2,819.87	53.88
+ GST 7.00/7.00% (S\$)	366.38	168.99	197.39	53.88

Nett Amount (S\$)	5,600.38	2,583.12	3,017.26	53.88
		+ Car Rental (5.0 x S\$107.00/day) (S\$)	535.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	3,120.12	

INSPECTION

Date of Assignment: 19/05/2021

Date Inspected: 17/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY ,RH	Broken	663.00 FS	*510.51 FS
3	1		*FACE ,FR BUMPER	Dented	706.00 FS	*543.62 FS
4	1		*COVER ,HEADLAMP SUPT PANEL	Not Necessary	62.00 FS	*- FS
5	1		*GARNISH ,FR BUMPER, RH	Not Necessary	127.00 FS	*- FS
6	1		*BRACKET ,FR BUMPER ,RH	Not Necessary	13.00 FS	*- FS
7	1		*AIR DAM ,SIDE ,FR RH	Not Necessary	18.00 FS	*- FS
8	1		*FENDER ,FR RH	Repair	500.00 FS	*- FS
9	1		*SHIELD ,FR WHEELHOUSE ,RH	Not Necessary	98.00 FS	*- FS
10	1		*EMBLEM ECO	Not Necessary	17.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**2,254.00****1,074.13**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE FRT BUMPER ,FRT RH FENDER & AFFECTED AREA REPAIR ON BONNET	New	1,350.00	450.00
2	PAINT WORK ON FRT BUMPER ,FRT RH FENDERM & BONNET	New	1,400.00	700.00
3	PERFORM RUST PREVENTION	New	80.00	40.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (S\$)			2,980.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >